

## Maintenance seen on some Dunlop composite wheels fitted to an MGBGTV8



### **Dunlop composite wheels have been given an interesting "spruce up"**

It appears any corrosion on the steel rims, which forms near the join between the chromed steel rim and the alloy centre, has been removed and then the metal painted with a narrow strip of silver paint. Unless you make a very close inspection, spotting that remedial work would be easily missed. The removal of corrosion on the chromed steel rim appears to have left a slight dip in the surface on the chrome rim as you run your finger over it, so presumably the removal of corrosion on the rim has resulted in the thickness of the steel rim being reduced slightly near the join with the alloy centre.

Have you seen this treatment on other Dunlop composites?

Victor Smith  
V8 Register – MG Car Club  
0208 392 9434