

RV8 Workshop Notes

Misfire, solving	5	130			11	423
		10	375	Ignition key replacement	1	0
Mountings, engine					8	296
- adjusting the mounts	8	255		Ignition module, remote	10	369
- mounts	3	71		Magnicor plug leads	11	411
- mounts orientation	9	324		Optimax chip, improvements	7	200
Oil filter magnetic wrap	11	408			8	251
Oil pressure switch	9	327			10	360
Oil pump				Part number change points	1	24
- cover & washers	3	88		Starting gremlins	2	66
- hoses (replacements)	3	88		Timing adjustments with		
Optimax chip, improvements	7	200		reimported RV8s	7	200
	8	251			11	422
	10	360		Timing correction in the RV8		
	11	402		Repair Manual AKM7144ENG	11	435
	11	403		Torque wrench settings	2	51
	11	410		Unichip connector problems	7	201
Part number change points	1	24				
PCV valve, check it is clear	8	249		3. COOLING SYSTEM		
Pipe clips	1	4		Antifreeze concerns	9	322
Plenum chamber hose	1	4		Blanking panel, radiator	4	103
Radiator cover, replacement	10	358			6	178
Ratchet, socket set caution	9	353		Coolant bleed insert	11	409
Rear oil seal – crankshaft	3	71		Coolant loss, cause	10	390
Remote ignition module	10	369		Coolant, refilling system	10	357
Road speed sensor	11	440		Coolant refilling, bleed insert	11	409
Rocker cover 3.9 badge				Connecting pipe, corrosion	8	299
- badge	4	105		Cooling fan modification	10	370
- breather element n/s	6	166		Cooling fan override switch	10	373
Sensor, air intake	5	130		Cooling hose layout	8	295
Starter, overheating	5	146		Cooling hose kit, identification	9	338
Starter motor	7	238		Expansion tank		
Starting problems	6	188		- crack in the neck of the tank	390	10
	11	437		- plug	1	10
	11	438		- refilling reminder	1	3
Stepper motor, cleaning	8	283		- corrosion	1	25
Stud, broken - removal	12	442		- filler plug spanner	1	37
Sump gasket, replacement	8	284		- new overflow tank	6	170
Sump gasket , caution	9	339		- where does the coolant go?	9	347
Sump gasket modification	11	420		Fan, cooling fan modification	10	370
Throttle pedal	1	19		Heater rail modification	9	349
Timing adjustments with				Hose, heavy indentation	9	349
reimported RV8s	7	200		Hoses, layout	6	185
Torque wrench settings	2	51			8	295
Unichip connector problems	7	201		Hoses, replacements	9	338
Water pump overhaul	3	99		Part number change points	1	24
Water pump replacement	1	3			5	150
	3	91		Plug, plastic/replacing	5	158
Water pump & air-con drive					5	159
belts	3	90		Plug, get you home tip	5	159
Water pump overhaul	9	314		Pressure cap replacement	10	367
Under bonnet checks	1	0		Radiator coolant loss	9	347
				Radiator cooling fan switch		
2. IGNITION SYSTEM					2	69
Cruise control, retrofit	9	341		Radiator hoses	1	4
Distributor clamp nut wrench	7	229			4	105
Distributor, timing	11	422			9	349

RV8 Workshop Notes

Radiator hoses, steel connecting pipe corrosion	8	299	Gauge not reading correctly	8	270
Radiator cover replacement	10	358	Hot wire fuel injection system	5	140
Radiator hose, bleed insert	11	409	Lucas hot wire system	5	140
	11	434	Part number change points	1	24
Radiator hoses, replacements	6	185	Petrol tank		
	8	295	- filler pipe	1	4
	9	338	- filler pipe	1	7
Radiator blanking panel	4	103	- filler pipe restrictor	1	39
	6	178	- general	1	7
Radiator pressure cap	10	367	- hoses	1	4
Radiator shroud stickers	6	181	- Oetika clamps	1	7
Radiator, refilling	10	357	- removal	1	23
Radiator top hose self purging	11	434	- vent pipes	1	7
Radiator, upgraded	6	170	Pipes, safety check	8	285
Thermostat – check it has a vent	11	415	Plenum chamber plug	4	105
Torque wrench settings	2	51	Starter gremlin – fuel cut off switch	2	66
Water pump			Throttle – see engine management systems	4	123
- feed & return	1	4	Torque wrench settings	2	51
- hose	1	5			
- overhaul	9	314	5. CLUTCH		
- replacement	1	3	Clutch master cylinder		
			- cap	1	14
4. FUEL SYSTEM			- repair kit	1	6
Bosch injectors	11	411		8	269
Cruise control, retrofit	9	341	- replacement	1	6
ECU location, removal & refit	5	144	- new part number	1	50
Electronic fuel ignition			- replacement	1	50
- throttle potentiometer	1	45	- vital part number	1	6
- injectors	1	45	Clutch slave cylinder	1	6
- air flow meter	1	45		3	71
- air valve stepper	1	45	Clutch pedal return spring	10	361
Engine management	4	115		10	361
	4	118	Clutch slave repairs	6	197
	4	122	Part number change points	1	24
Fuel cut off switch			Repair kits. Master/slave	8	269
- cut off switch	2	66	Torque wrench settings	2	51
- starting difficulty	7	219			
Fuel filter blocked, check	9	326	6. GEARBOX		
Fuel filter replacement	3	92	Bushes, rubber UKC854	10	381
Fuel pump			Clutch assembly	3	71
- general	1	29	Crunching gears, solving	10	381
- noisy	1	43	Gearbox lubrication, R380	6	163
- resistor	1	43			
- fuel pump	1	45	Gearbox cross member	2	52
- replacement (Bosch)	3	92		3	71
Fuel system			Gearbox mountings	2	52
- hose clamps & clips	1	4		3	71
- Oetika clamps	1	4	Gearbox remote	3	71
- Oetika clamps	1	7	Gearbox remote, grease	10	384
- filters & hoses	1	4	Gearbox removal	3	71
- non evaporative loss system	1	4	Gearbox, LT77S or R380?	11	404
	1	23	Gearknob		
- fuel filter	1	29	- cleaning	1	18
- filter replacement	3	92			
Fuel tank corrosion	9	326			

RV8 Workshop Notes

- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	8	256
Gear lever gaiter replacement	9	333
Gear lever greasing	10	384
Gear lever grommet	4	105
Gear lever remote moving	10	381
Input shaft	3	71
Gearshift pattern LT77S/R380 LT77 gearbox	11	404
- greasing lever & remote	10	384
- rubber bushes rotting	10	381
- lubricant	10	382
- repairing dust cap bracket	11	405
Notchy gearchange cures	10	382
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points	1	24
 R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
– greasing lever & remote	10	384
- lubrication	6	163
	10	382
– repairing dust cap bracket	11	405
- synthetic oils experience	8	264
Rubber bushes UKC854	10	381
Torque wrench settings	2	51
Towing caution	8	252
Which gearbox do I have?	11	404

7. PROPSHAFT

Part number change points	1	24
Torque wrench settings	2	51

8. REAR AXLE

Breather, plastic replacement	11	413
Breather, thread compatibility	11	418
CWP, new supplies	5	156
Limited slip differential	3	84
Noise from back axle	5	155
Part number change points	1	24
Quaife, differences with an LSD	10	388
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156
Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264

Torque wrench settings	2	51
------------------------	---	----

9. REAR SUSPENSION

Hoyle suspension upgrade	7	208
Hoyle – what's it like?	9	310
Hoyle, installation notes	9	311
Hoyle, setting up	10	363
Hoyle, Spax settings	10	364
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Modifications - caution	9	312
Part number change points	1	24
Rear spring shackle	10	383
Rear wheel bearings	1	40
Recall notice	8	244
Shackle, rear spring caution	10	383
Spax Krypton Gas shocks	8	278
Spax replacement shockers	8	278
Spax settings	10	364
Replacement shockers	8	278
Shock absorber, adjustments	6	174
Shockers, adjustment guide	7	214
Suspension upgrade kit	7	208
Torque wrench settings	2	51

10. INSURANCE

Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168

11. STEERING

Ball joints		
- lower	6	166
- upper	6	166
Part number change points	1	24
Castor reduction		
- details of the B&G kit	7	232
- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266
Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235

RV8 Workshop Notes

PAS option review	9	354
EZ EPAS Swiss approvals	9	355
Steering column, collapsible	11	430
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166

12. FRONT SUSPENSION

Ball joints, steering		
- lower	6	166
- upper	6	166
Bump stop replacement	8	254
Bush replacement in AR bar eye	10	385
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
- further caution	9	312
Drop links, checks	11	410
Drop links, replacement parts	11	412
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points	1	24
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99
- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spax, replacement shockers	8	278
Spax settings	10	364
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51
Track rod end	6	166

13. BRAKES

Brakes, system & adjustments	9	330
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
- refurbishing	10	359
- replacement yellow tag	10	379
Brake fluid choice	8	294
Brake pedal return spring	10	361
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6
- replacement	1	6
Discs, caution for eBay adverts for RV8 discs	9	305
Front brake discs, caution	9	305
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291
Hydraulic hoses	1	6
Part number change points	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket	6	166
Return spring replacement	10	361
Servos and brake systems	8	293
Silicone brake fluid	8	294
Torque wrench settings	2	51

14. ELECTRICAL EQUIPMENT

Aerial		
- replacement	1	11
Air conditioning		
- actuator	11	436
- conditioned air vents	6	189
- corrosion on fans	6	173

RV8 Workshop Notes

	10	376	Headlamp units		
- heater cut-off flap vacuum actuator	11	436	- conversion to LHD	9	308
- service	1	44		9	313
	10	393	- corrosion	1	25
- more passenger legroom	4	124	- cowl, removal	6	167
- preventative maintenance	10	376	- cowl removal & replacement	11	417
- recharging an aircon system	10	378	- replacement (Bosch)	1	1
	10	393	- replacement	2	65
- removal of the a/c system?	6	184	- retainers	6	167
Alarm transmitter			Heater blower motor & fuse	9	336
- caution	1	0	Indicators, front		
-deactivating the volumetric sensor	10	371	- changing amber to clear lenses	6	177
- renew batteries	1	0		8	253
- replacement	1	0	- connector terminal corrosion		
- reprogramming	1	0		5	157
	8	260	Immobiliser	4	117
- solving alarm not working	10	399	Immobiliser – ECU terminal	6	191
Alternator			Immobiliser - synchronisation	7	234
- exchange	6	163	Immobiliser, volumetric sensor	10	371
- no charge warning	6	171	Instruments in fascia	1	24
- replacement	1	48	Insulation cracking	4	110
- no charge light stays on	8	290	Interior lights control caution	11	407
- problem solving	11	421	Key fob, alarm not working	10	399
Battery			LED replacement bulbs	10	386
- condition device	2	56		10	387
- conditioner	7	237	Lens, indicator – changing from amber to clear	6	176
- conditioner, connecting up	11	425	No charge light stays on	8	290
- filler bottle	3	78	Part number change point		
- fixings, missing	5	134		1	24
- increased capacity batteries	8	257	Petrol tank sender unit	4	105
- lifter/carrier	1	9	Radio		
- Snap-On tools lifter	3	73	- CD stacker, fitting	7	239
- another source, lifter	3	78	- conversion (Japan)	1	39
Boot opening switch bulb	10	368	- frequency converter	3	76
Bulb, dashboard replacement	10	368		7	220
Bulbs, replacing with LEDs	10	386		7	221
Central locking, retrofit	9	340	Relay No 1, replacing	6	165
Conditioned air vents	6	189	Rev counter removal	9	318
Cooling fan modification	10	370	Reverse lamp lucars	3	71
Cooling fan override switch	10	373	Reversing light switch	7	212
Cruise control, retrofit	9	341	Rear light cluster	4	105
Dashboard switch bulb	10	368	Saving electrical parts	3	99
DRLs (daytime running lights)	10	398	Speaker grilles, replacement		
Daytime running lights, fitting	10	398		8	281
FM radio frequency converter	3	76	Speedometer change (import)	11	432
			Speedometer repairs	9	306
Fog lights			Starter motor		
- fog lights	1	39	- Bosch starter motor	7	238
- replacement sources	6	199	- not turning over	11	438
Footwell lights	6	165	- overheating	5	146
Fuel pump resistor	1	43	- terminals corrosion	1	25
Front indicator lamp corrosion	5	157	- terminals repair	1	28
	6	163	Tachometer removal	9	318
Fuse box & fuses	5	148	Torque wrench settings	2	51
Fuel gauge not reading correctly	8	270	Volumetric sensor	10	371
			Warning light, No Charge	6	171

RV8 Workshop Notes

Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105
Wiper relays failed?	9	321

15. WHEELS & TYRES

Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points	1	24
Pressures, modern tyres	9	337
Road wheels		
- centre caps	1	10
	9	315
- changed castings	1	10
- corrosion	1	15
	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- refurbishment	9	314
	9	317
	10	389
- refurbishment specialist	10	362
- wheel centre badges	1	15
	8	276
	9	315
	9	317
- wheel lock nuts, wear	3	81
Sealants	8	298
	10	372
Space saver tyres, check	5	133
	8	297
Studs, dummy need care	8	261
	9	315
Torque wrench settings	2	51
Tired tyres, stored RV8s	5	132
Tyres		
- replacements	5	160
- replacements, suppliers	6	182
- more on replacements	6	179
- update on replacement tyres	6	198
- pressures	6	174
- pressures again	6	196
- pressures, modern tyres	9	337
- sealants for tyres	8	298
	10	372
- spacesaver views	10	372
- spacesaver wheel & tyre	9	304
- spacesavers, critical view	9	307
- more on spacesavers	9	316
- suppliers, recommended	6	182
- tyres size calculator	10	395
Wheel nuts, locking	4	121

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Badges, RV8 lettering	9	342
Bonnet alignment		
- alignment	3	80
- Gas struts upgrade	10	365
- release cable	6	166
- stay, clip	6	166
Boot		
- Boot lock dashboard switch		
bulb	10	366
- boot lock switch	10	366
- gas struts	8	259
- gas struts, regassing	9	323
- gas struts, replacements	9	323
- general	1	23
- luggage rack options	9	346
- release mechanism	5	149
- tool stowage mould	1	23
- warning (closing)	1	0
Bumper, rear, realignment	9	325
Cleaning to near concours standards	11	426
Club badge mounting	2	58
	3	95
Colours (paintwork)	1	0
	2	0
Corrosion checks	1	25
	1	42
	3	87
Door glass		
- removal	2	68
- refitting	2	68
- part numbers	2	68
Door handles	5	151
Door mirrors	1	2
- rubber covers	3	74
- knob handles	3	74
- mirror glass	3	74
	6	166
Door seal, inner	5	153
Electric wing mirrors, fitting	10	375
Exterior checks	1	0
Fire risk, unusual/visor mirror	6	190
Gas struts, caution	4	114
	8	259
Gaiter, rubber replacement	9	333
Gear lever gaiter replacement	9	333
Header rail corrosion	1	25
Headlamp cowl, remove	6	167
Headlamp change to LHD	9	308
Hood		
- catches, safety check	8	286
- catches, check fixings	9	332

RV8 Workshop Notes

- cleaning/refurb	4	107	Seats, lowering	7	233
- fitting	1	0	Side skirt removal	5	145
- operation	1	0	Sills		
- polish, plastic rear window	9	303	- mounting brackets	1	25
	10	380	- tread plates	1	27
- rattle	1	20		4	105
- rear surround	1	25	Tonneau covers		
- Renovo products	4	113	- full	2	55
	9	303	- half	2	55
- replacement, caution	8	262	Torque wrench settings	2	51
- replacement hoods, more	8	268	Touch up paint codes	8	300
- sheared pivot repair	1	47	Touch up paint sources	11	439
- stiff operation	1	46	Tow bar, fitting	9	319
- toggle catch checks	9	332	Underbody knocks	6	187
Hood backlight			Water leaks	1	22
- avoiding crease	4	108		2	62
- cat deterrent!	2	53		5	136
- press stud tool	9	348		9	350
- rear window polish	9	303	Waxoyling reimports	3	87
- replacement	2	53	Wheel arch flares	2	70
- zip use & repair	4	109	Windscreen		
	10	394	- carbon fibre replacement	8	246
- zip lubrication	9	343	- checks	1	0
Hood rear window see backlight above			- frame corrosion	1	25
Indicator lenses, changing to clear	6	176	- leaks, water ingress	3	93
Inner door seal retainer strip	5	153		5	136
Jack with the RV8, concerns	9	331	- refitting	1	22
Knocking noise, underbody	6	187	- replacement surround	8	246
Legroom, increasing	5	139	- removal	1	22
Lens, indicator – changing from amber to clear			- rust, pictures	7	225
	6	176	- sealing rubbers	1	22
	8	253	- VIN number etching	3	89
Luggage, fitted set for an RV8	9	431		8	273
Luggage rack options	9	346	Windscreen glass		
MGF electric wing mirrors	10	375	- removal	1	22
Noise from engine on LHS			- refitting	1	22
	5	138	- replacement supply	7	240
Nose cone, removal	7	203	Windstop, fitting	5	127
Number plates				9	328
- correct plates, avoid a fine	10	396	Windstop	7	224
- doublesided tape	7	236	Windstop bracket mod	7	228
- rear fixings	1	39	Windstop design, folding	9	345
- removing Japan spec plate	7	217	Windstop, folding design	9	345
- replacement number plate	8	279	Windstop for taller drivers	9	302
Paint codes	4	125	Wing mirrors, electric	10	375
	8	300		10	377
Paint sources	11	439	Wings		
Part number change points			- Rover badges (Japan)	1	39
	1	24	Wiper bezel	5	151
Retainer strip, inner door seal	5	153	Wiper blades adjustment	1	13
Rear window, hood					
See hood backlight above			17. SERVICE TOOLS		
Rear bumper alignment	9	325	Auten hydraulic car lift	7	209
Seats, unusual fire risk!	6	190	Britool equipment	3	71
Seats, more legroom	5	139	Draper tool 176	1	12
				1	23
			Draper tool T40	1	12
			Filler plug spanner	1	37

RV8 Workshop Notes

Hydraulic car lift or ramp	7	209	Mobile phone, new law	6	193
Jack, using it on an RV8	11	427	Old parts, hang on to them		
Lift, hydraulic	7	209		1	33
Tool storage moulding	1	23		3	91
RV8 toolkit			Phillips & Posidriv differences	9	320
- checklist of contents	1	9	Plaques, rally	8	287
- general	1	39	Posidriv & Phillips differences	9	320
- replacements	2	63	Publications:		
- new toolkit supplies	4	106	Owners Handbook		
- torch replacement	3	72	AKM7144	1	0
Sump plug spanner	1	37	Owners Service Record		
	4	106	AKM7150	1	0
Trolley jack, using on an RV8	11	427	Owners Info Portfolio		
Zyliss Strong Boy	1	14	AKM7158	1	0
			Repair Manual		
			AKM7153	1	0
				4	118
18. VARIOUS			Engine Manual		
Acquiring an MG RV8	1	0	AKM7154ENG	1	0
Alarm transmitter			LT77 Gearbox Manual		
- ECU, vulnerability	6	191	AKM7155ENG	1	0
- instructions card	8	274	RAWS, first approval	7	223
- reprogramming	1	0	R380 Gearbox Manual		
- replacements	1	0	AKM7225	1	0
- retrofitting alarm & central locking system	5	142	Rally plaques for the RV8	8	287
Auctions in Japan	6	195	Reimporting from Japan		
Badge bar for an RV8	8	250	- to Australia	5	135
Buying an MG RV8			- Australian RAWS update	7	215
- guidance note	1	0	- checklist	1	39
- dreams come true!	3	83	- options, local agent?	6	192
- reimporter's checks	4	112	- corrosion checks	3	87
Cleaning an RV8 to near concours standard	11	426	- type approval	1	39
Colours, for the RV8	7	216	- customs requirements	1	39
Concours, cleaning an RV8	11	426	- Waxoyling	3	87
Dehumidifier, Winter storage	7	237	Remote key fob – see alarm transmitter above		
Disklock	6	180	Ratchet, socket set caution	9	353
DVLA info on your car	11	433	Repair manual MG RV8	3	71
DVLA info update	12	441	Reimporting RV8s, auctions	6	195
Fire extinguishers in cars	4	110	Rover Dealer network	1	0
Fire risk, unusual/mirror	6	190	Rover Dealer network	2	0
Gas struts, fire risk	4	114	Seat belts, inertia reel unlock	9	329
Hands free phone, new law	6	193	Screws Phillips & Posidriv	9	320
Hood press studs	9	348	Servicing	1	39
How many RV8s were made?	7	216		6	172
Importing to Australia	5	135	Spare parts	1	33
Jack with the RV8, concerns	9	331		3	82
Japan reimports of RV8s			Spares, essential for touring abroad	8	288
- car documents	1	39	Stoplock	6	180
- checklist	1	0	Steering locks	6	180
- checks & tips	1	39	Stolen cars (Japan)	4	112
- ownership checks	4	112	Storing an RV8 over Winter	7	237
- Modifications	4	120	Technical Info CD, RV8	6	-
Land Transport Safety Authority, New Zealand	1	33	Toolkits for MG RV8	1	0
Le Mans visit - tips	1	49		1	9
Luggage, fitted set for an RV8	9	351		2	63
Luggage rack options	9	346		3	72
Maintenance locations	1	0		4	106

RV8 Workshop Notes

Toolkit, spare wheel moulding	6	166	Heater blower motor & fuse	9	336
Torque wrench settings	2	51	Heater control cable	5	128
Under bonnet stickers	1	39		7	204
VIN identification	1	0		8	247
	5	147	Heater matrix leak, cure	8	248
Water leaks cure, legwell	9	350	Hot RV8 cockpit	11	414
Windstop	7	224		5	126
Windstop, folding design	9	345		6	170
Yellow Autolock	6	180		7	204
				7	227
				8	247
				8	248
19. INTERIOR & INSTRUMENTS			Ignition key, replacement	8	296
Alarm ECU, vulnerability	6	191	Ignition warning light glows	8	280
Ashtray insert	9	334	Immobiliser	4	117
Bezels, removing bezels	9	344	Immobiliser – ECU terminal	6	191
Boot bulkhead clips	9	301	Immobiliser, synchronisation	7	234
Bulkhead clips, boot	9	301	Instruments		
Carpets, replacements source	8	267	- bezels, removing	9	344
Central locking, retrofit	9	340	- misting difficulties	2	57
Checks before purchase	1	0	- oil pressure sensor	2	57
Clipstone leather cleaner	1	17	- fascia switch bulbs	3	85
Clipstone conditioner	1	18	Interior lights control caution	11	407
Cockpit, too hot	5	126	Luggage, fitted	9	351
Cockpit heat, solved	6	170	Mobile phone, hands free kits	6	193
Courtesy light clips	5	141	Oil pressure switch	9	327
Cruise control, retrofit	9	341	Radio		
Dashboard			- FM waveband converter	2	76
- creak, solving	8	266	- FM band expander	7	220
- fascia removal	1	12	- iPod ICE option	7	239
	1	22	- replacement, reimport	7	221
- radio fascia panel	3	79	Seat belts, inertia reel	9	329
- refurbishing laquer	8	277	Seat belt refurbishment	10	391
Door cappings				11	424
- cracking	5	154	Seat belts, replacement	11	424
- refurbishment	5	154	Seat belt stalks, repair/gaiter	10	392
	8	277	Seat frame, colour	9	352
- relacquering trim	8	282	Seat frames, refurbishment	9	352
Door pockets modification	8	289	Seats, headrest upgrade	11	400
Driver headroom tip	1	35	Seats, more legroom	5	139
Emergency flares	7	222	Seats, lowering	7	233
Fascia Shellac coating	2	57	Seats touch up	11	419
Fascia instruments	2	57	Silkaflex, foil heat shield	6	170
Footwell lights	6	165	Speaker grilles, replacement		
	6	166		8	281
Fuse box & fuses	5	148	Speedometer	1	39
Gaiter, rubber replacement	9	333	Speedometer, replacement		
Gearbox knob			mph dial for a reimport	11	432
- cleaning	1	18	Sun visor, fire risk unusual	6	190
- replacement	1	18	Sun visor screws	6	166
- renovation	3	77	Tachometer - redlining	7	206
Gear lever gaiter replacement	9	333	Tachometer removal	9	317
Glovebox	1	12	Temperature gauge	7	207
Glovebox, switch	6	166	Trim colour	1	0
Glovebox lid, refurbishing	8	277		3	86
laquer			Trim panels removal	1	30
Hands free mobile kits	6	193	Trim panels, Velcro strips	7	202
Headrest upgrade	11	400	Upholstery		
Headrest, leather cushions	11	400			

RV8 Workshop Notes

- leathercare tips	1	17
	11	419
- seat removal	1	30
- seat touch up	11	419
Velcro strips, trim panels	7	202
Warning light, No Charge	6	171
Water leaks legwell	9	350
Windstop, fitting	5	127
- another installation	5	143
- Classic Additions, fitting	9	328
- drawings of a windstop	9	335
- folding windstop design	9	345
- neat installation	7	205
- photos of a windstop	9	335
- windstop bracket mod	7	228

Index prepared by Victor Smith (V8 Harvest Gold 1089)