

RV8 Workshop Notes

Index to the whole series

This index covers all volumes of the RV8 Workshop Notes series and will be updated from time to time as the series develops. An updated Index is maintained on the V8 Website at www.v8register.net which holders of RV8 Workshop Notes can download to maintain their copies of the Index.

Topic	Vol	RV8 Note
1. ENGINE		
Advance & retard pipe	1	39
	2	60
	8	258
Advance retard unit	4	120
Air filters	1	0
	1	41
	3	91
	3	99
	4	119
	6	175
Air flow meter	1	4
Air intake sensor	5	130
Bosch starter motor	7	238
Crankshaft rear oil seal	3	71
Distributor clamp nut wrench	7	229
ECU, location, removal & refit		
	5	144
ECU, rechipping	7	226
	7	230
Engine management		
- Data link connector	4	115
- DLC cover strip	4	115
- Diagnostic databook	4	122
- Diagnostic leads	4	118
- Diagnostic tests	4	118
	4	123
- Rover Testbook or T4	4	118
- Test equipment	4	118
Engine performance		
- EPROMS (chips)	1	21
- upgrade	1	21
- RPI Engineering	1	21
Exhaust system		
- catalytic overheat sensors	3	100
	4	101
- catalytic converter	3	99
- clamps	3	97
- cats, replacements	9	309
- down pipes	3	97
- general	1	16
- hangers, replacing	5	134
- mounting hooks	1	25
- manifolds nuts loose	5	138
- manifold LHS noise	5	138
- mounting brackets	1	25
- corrosion	1	25
- rattle	1	36
- removal	8	292
Oil filter, replacement	8	284
Flame trap hoses		
- clamps	1	4
- general	1	5
Flywheel cover plate	3	71
Heater hoses	1	5
Heater box corrosion	1	25
Hose clamps		

- general	1	4
- Norma	1	4
- Oetika	1	4
Hot wire fuel injection system		
	5	140
Idle		
- engine erratic	5	140
- running problems	6	188
- spasmodic idle problems	6	186
Lucas Hot Wire system	5	140
Inlet manifold gasket		
- corrosion	1	25
- general	1	26
Misfire, solving	5	130
Mountings, engine		
- adjusting the mounts	8	255
- mounts	3	71
- mounts orientation	9	324
Oil pressure switch	9	327
Oil pump		
- cover & washers	3	88
- hoses (replacements)	3	88
Optimax chip, improvements	7	200
	8	251
Part number change points	1	24
PCV valve, check it is clear	8	249
Pipe clips	1	4
Plenum chamber hose	1	4
Rear oil seal – crankshaft	3	71
Rocker cover 3.9 badge		
- badge	4	105
- breather element n/s	6	166
Sensor, air intake	5	130
Starter, overheating	5	146
Starter motor	7	238
Starting problems	6	188
Stepper motor, cleaning	8	283
Sump gasket, replacement	8	284
Throttle pedal	1	19
Timing adjustments with reimported RV8s	7	200
Torque wrench settings	2	51
Unichip connector problems	7	201
Water pump overhaul	3	99
Water pump replacement	1	3
	3	91
Water pump & air-con drive belts	3	90
Water pump overhaul	9	314
Under bonnet checks	1	0
2. IGNITION SYSTEM		
Distributor clamp nut wrench	7	229
Ignition key replacement	1	0
	8	296
Optimax chip, improvements	7	200
	8	251
Part number change points		
	1	24
Starting gremlins	2	66
Timing adjustments with reimported RV8s	7	200
Torque wrench settings	2	51
Unichip connector problems	7	201
3. COOLING SYSTEM		
Antifreeze concerns	9	322
Blanking panel, radiator	4	103

RV8 Workshop Notes

	6	178
Connecting pipe, corrosion	8	299
Cooling hose layout	8	295
Expansion tank		
- plug	1	3
- refilling reminder	1	3
- corrosion	1	25
- filler plug spanner	1	37
- new overflow tank	6	170
Hoses, layout	6	185
	8	295
Part number change points		
	1	24
Plug, plastic/replacing	5	150
	5	158
Plug, get you home tip	5	159
Radiator cooling fan switch		
	2	69
Radiator hoses	1	4
	4	105
Radiator hoses, steel		
connecting pipe corrosion	8	299
Radiator hoses, replacements		
	6	185
	8	295
Radiator blanking panel	4	103
	6	178
Radiator shroud stickers	6	181
Radiator, upgraded	6	170
Torque wrench settings	2	51
Water pump		
- feed & return	1	4
- hose	1	5
- overhaul	9	314
- replacement	1	3
4. FUEL SYSTEM		
ECU location, removal & refit		
	5	144
Electronic fuel ignition		
- throttle potentiometer	1	45
- injectors	1	45
- air flow meter	1	45
- air valve stepper	1	45
Engine management	4	115
	4	118
	4	122
Fuel cut off switch		
- cut off switch	2	66
- starting difficulty	7	219
Fuel filter blocked, check	9	326
Fuel filter replacement	3	92
Fuel pump		
- general	1	29
- noisy	1	43
- resistor	1	43
- fuel pump	1	45
- replacement (Bosch)	3	92
Fuel system		
- hose clamps & clips	1	4
- Oetika clamps	1	4
- Oetika clamps	1	7
- filters & hoses	1	4
- non evaporative loss system	1	4
	1	23
- fuel filter	1	29
- filter replacement	3	92
Fuel tank corrosion	9	326

Gauge not reading correctly	8	270
Hot wire fuel injection system		
	5	140
Lucas hot wire system	5	140
Part number change points		
	1	24
Petrol tank		
- filler pipe	1	4
- filler pipe	1	7
- filler pipe restrictor	1	39
- general	1	7
- hoses	1	4
- Oetika clamps	1	7
- removal	1	23
- vent pipes	1	7
Pipes, safety check	8	285
Plenum chamber plug	4	105
Starter gremlin – fuel cut off switch	2	66
Throttle – see engine management systems	4	123
Torque wrench settings	2	51

5. CLUTCH

Clutch master cylinder		
- cap	1	14
- repair kit	1	6
	8	269
- replacement	1	6
- new part number	1	50
- replacement	1	50
- vital part number	1	6
Clutch slave cylinder	1	6
	3	71
Clutch slave repairs	6	197
Part number change points		
	1	24
Repair kits. Master/slave	8	269
Torque wrench settings	2	51

6. GEARBOX

Clutch assembly	3	71
Gearbox lubrication, R380		
	6	163
Gearbox cross member	2	52
	3	71
Gearbox mountings	2	52
	3	71
Gearbox remote	3	71
Gearbox removal	3	71
Gearknob		
- cleaning	1	18
- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	11	256
Gear lever grommet	4	105
Input shaft	3	71
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points		
	1	24
R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
- lubrication	6	163
- synthetic oils experience	8	264

RV8 Workshop Notes

Torque wrench settings	2	51
Towing caution	8	252
7. PROPSHAFT		
Part number change points		
	1	24
Torque wrench settings	2	51
8. REAR AXLE		
CWP, new supplies	5	156
Limited slip differential	3	84
Noise from back axle	5	155
Part number change points	1	24
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156
Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264
Torque wrench settings	2	51
9. REAR SUSPENSION		
Hoyle suspension upgrade	7	208
Hoyle – what's it like?	9	310
Hoyle, installation notes	9	311
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Modifications - caution	9	312
Part number change points		
	1	24
Rear wheel bearings	1	40
Recall notice	8	244
Spax Krypton Gas shocks	8	278
Replacement shockers	8	278
Shock absorber, adjustments	6	174
Shockers, adjustment guide	7	214
Suspension upgrade kit	7	208
Torque wrench settings	2	51
10. INSURANCE		
Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168
11. STEERING		
Ball joints		
- lower	6	166
- upper	6	166
Part number change points		
	1	24
Castor reduction		
- details of the B&G kit	7	232

- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266
Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166
12. FRONT SUSPENSION		
Ball joints, steering		
- lower	6	166
- upper	6	166
Bump stop replacement	8	254
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
- further caution	9	312
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points		
	1	24
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99
- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51
Track rod end	6	166
13. BRAKES		
Brakes, system & adjustments	9	330
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
Brake fluid choice	8	294
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6

RV8 Workshop Notes

- replacement	1	6
Discs, caution for eBay adverts for RV8 discs	9	305
Front brake discs, caution	9	305
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291
Hydraulic hoses	1	6
Part number change points		
	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket		
	6	166
Servos and brake systems	8	293
Silicone brake fluid	8	294
Torque wrench settings	2	51
14. ELECTRICAL EQUIPMENT		
Aerial		
- replacement	1	11
Air conditioning		
- conditioned air vents	6	189
- corrosion on fans	6	173
- service	1	44
- more legroom for the passenger	4	124
- removal of the a/c system?	6	184
Alarm transmitter		
- caution	1	0
- renew batteries	1	0
- replacement	1	0
- reprogramming	1	0
	8	260
Alternator		
- exchange	6	163
- No charge warning	6	171
- replacement	1	48
- no charge light stays on	8	290
Battery		
- condition device	2	56
- conditioner	7	237
- filler bottle	3	78
- fixings, missing	5	134
- increased capacity batteries	8	257
- lifter/carrier	3	73
- Snap-On tools lifter	3	73
- Another source, lifter	3	78
Conditioned air vents	6	189
FM radio frequency converter		
	3	76
Fog lights		

- fog lights	1	39
- replacement sources	6	199
Footwell lights	6	165
Fuel pump resistor	1	43
Front indicator lamp corrosion	5	157
	6	163
Fuse box & fuses	5	148
Fuel gauge not reading correctly	8	270
Headlamp units		
- conversion to LHD	9	308
	9	313
- corrosion	1	25
- cowl, removal	6	167
- replacement (Bosch)	1	1
- replacement	2	65
- retainers	6	167
Indicators, front		
- changing amber to clear lenses	6	177
	8	253
- connector terminal corrosion	5	157
Immobiliser	4	117
Immobiliser – ECU terminal	6	191
Immobiliser - synchronisation	7	234
Instruments in fascia	1	24
Insulation cracking	4	110
Lens, indicator – changing from amber to clear		
	6	176
No charge light stays on	8	290
Part number change point		
	1	24
Petrol tank sender unit	4	105
Radio		
- conversion (Japan)	1	39
- frequency converter	3	76
Relay No 1, replacing	6	165
Rev counter removal	9	318
Reverse lamp lucars	3	71
Reversing light switch	7	212
Rear light cluster	4	105
Saving electrical parts	3	99
Speaker grilles, replacement		
	8	281
Speedometer repairs	9	306
Starter motor		
- Bosch starter motor	7	238
- overheating	5	146
- terminals corrosion	1	25
- terminals repair	1	28
Tachometer removal	9	318
Torque wrench settings	2	51
Warning light, No Charge	6	171
Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105
Wiper relays failed?	9	321
15. WHEELS & TYRES		
Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points		
	1	24
Road wheels		
- centre caps	1	10

RV8 Workshop Notes

	9	315			
- changed castings	1	10			
- corrosion	1	15			
	3	93			
- dummy studs, care! (tip)	8	261			
- general	1	10			
- refurbishment	1	15			
	8	265			
- refurbishment	9	314			
	9	317			
- wheel centre badges	1	15			
	8	276			
	9	315			
	9	317			
- wheel lock nuts, wear	3	81			
Sealants	8	298			
Space saver tyres, check	5	133			
	8	297			
Studs, dummy need care	8	261			
	9	315			
Torque wrench settings	2	51			
Tired tyres, stored RV8s	5	132			
Tyres					
- replacements	5	160			
- replacements, suppliers	6	182			
- more on replacements	6	179			
- update on replacement tyres	6	198			
- pressures	6	174			
- pressures again	6	196			
- sealants for tyres	8	298			
- spacesaver wheel & tyre	9	304			
- spacesavers, critical view	9	307			
- more on spacesavers	9	316			
- suppliers, recommended	6	182			
Wheel nuts, locking	4	121			
16. BODY					
Air intake mesh	1	34			
	5	151			
Badge bar for an RV8	8	250			
Badges, removal with care!	6	183			
Badges – doublesided tape	7	236			
Bonnet alignment					
- alignment	3	80			
- release cable	6	166			
- stay, clip	6	166			
Boot					
- gas struts	8	259			
- gas struts, regassing	9	323			
- gas struts, replacements	9	323			
- general	1	23			
- release mechanism	5	149			
- tool stowage mould	1	23			
- warning (closing)	1	0			
Bumper, rear, realignment	9	325			
Club badge mounting	2	58			
	3	95			
Colours (paintwork)	1	0			
	2	0			
Corrosion checks	1	25			
	1	42			
	3	87			
Door glass					
- removal	2	68			
- refitting	2	68			
- part numbers	2	68			
Door handles	5	151			
Door mirrors	1	2			
	3	74			
	3	74			
- mirror glass	3	74			
	6	166			
Door seal, inner	5	153			
Exterior checks	1	0			
Fire risk, unusual/visor mirror	6	190			
Gas struts, caution	4	114			
	8	259			
Header rail corrosion	1	25			
Headlamp cowl, remove	6	167			
Headlamp change to LHD	9	308			
Hood					
- catches, safety check	8	286			
- catches, check fixings	9	332			
- cleaning/refurb	4	107			
- fitting	1	0			
- operation	1	0			
- polish, plastic rear window	9	303			
- rattle	1	20			
- rear surround	1	25			
- Renovo products	4	113			
	9	303			
- replacement, caution	8	262			
- replacement hoods, more	8	268			
- sheared pivot repair	1	47			
- stiff operation	1	46			
- toggle catch checks	9	332			
Hood backlight					
- avoiding crease	4	108			
- cat deterrent!	2	53			
- rear window polish	9	303			
- replacement	2	53			
- zip use & repair	4	109			
Hood rear window see backlight above					
Indicator lenses, changing to clear	6	176			
Inner door seal retainer strip	5	153			
Jack with the RV8, concerns	9	331			
Knocking noise, underbody	6	187			
Legroom, increasing	5	139			
Lens, indicator – changing from amber to clear					
	6	176			
	8	253			
Noise from engine on LHS					
	5	138			
Nose cone, removal	7	203			
Number plates					
- doublesided tape	7	236			
- rear fixings	1	39			
- removing Japan spec plate	7	217			
- replacement number plate	8	279			
Paint codes	4	125			
	8	300			
Part number change points					
	1	24			
Retainer strip, inner door seal	5	153			
Rear window, hood					
See hood backlight above					
Rear bumper alignment	9	325			
Seats, unusual fire risk!	6	190			
Seats, more legroom	5	139			
Seats, lowering	7	233			
Side skirt removal	5	145			
Sills					
- mounting brackets	1	25			

RV8 Workshop Notes

- tread plates	1	27	- retrofitting alarm & central locking system	5	142
	4	105	Auctions in Japan	6	195
Tonneau covers			Badge bar for an RV8	8	250
- full	2	55	Buying an MG RV8		
- half	2	55	- guidance note	1	0
Torque wrench settings	2	51	- dreams come true!	3	83
Touch up paint codes	8	300	- reimporter's checks	4	112
Tow bar, fitting	9	319	Colours, for the RV8	7	216
Underbody knocks	6	187	Dehumidifier, Winter storage	7	237
Water leaks	1	22	Disklock	6	180
	2	62	Fire extinguishers in cars	4	110
	5	136	Fire risk, unusual/mirror	6	190
Waxoyling reimports	3	87	Gas struts, fire risk	4	114
Wheel arch flares	2	70	Hands free phone, new law	6	193
Windscreen			How many RV8s were made?	7	216
- carbon fibre replacement	8	246	Importing to Australia	5	135
- checks	1	0	Jack with the RV8, concerns	9	331
- frame corrosion	1	25	Japan reimports of RV8s		
- leaks, water ingress	3	93	- car documents	1	39
	5	136	- checklist	1	0
- refitting	1	22	- checks & tips	1	39
- replacement suaround	8	246	- ownership checks	4	112
- removal	1	22	- Modifications	4	120
- rust, pictures	7	225	Land Transport Safety Authority, New Zealand	1	33
- sealing rubbers	1	22	Le Mans visit - tips	1	49
- VIN number etching	3	89	Maintenance locations	1	0
	8	273	Mobile phone, new law	6	193
Windscreen glass			Old parts, hang on to them		
- removal	1	22		1	33
- refitting	1	22		3	91
- replacement supply	7	240	Phillips & Posidriv differences	9	320
Windstop, fitting	5	127	Plaques, rally	8	287
	9	328	Posidriv & Phillips differences	9	320
Windstop	7	224	Publications:		
Windstop bracket mod	7	228	Owners Handbook		
Windstop for taller drivers	9	302	AKM7144	1	0
Wings			Owners Service Record		
- Rover badges (Japan)	1	39	AKM7150	1	0
Wiper bezel	5	151	Owners Info Portfolio		
Wiper blades adjustment	1	13	AKM7158	1	0
			Repair Manual		
17. SERVICE TOOLS			AKM7153	1	0
Auten hydraulic car lift	7	209		4	118
Britool equipment	3	71	Engine Manual		
Draper tool 176	1	12	AKM7154ENG	1	0
	1	23	LT77 Gearbox Manual		
Draper tool T40	1	12	AKM7155ENG	1	0
Filler plug spanner	1	37	RAWS, first approval	7	223
Hydraulic car lift or ramp	7	209	R380 Gearbox Manual		
Lift, hydraulic	7	209	AKM7225	1	0
Tool storage moulding	1	23	Rally plaques for the RV8	8	287
RV8 toolkit			Reimporting from Japan		
- checklist of contents	1	9	- to Australia	5	135
- general	1	39	- Australian RAWS update	7	215
- replacements	2	63	- checklist	1	39
- new toolkit supplies	4	106	- options, local agent?	6	192
- torch replacement	3	72	- corrosion checks	3	87
Sump plug spanner	1	37	- type approval	1	39
	4	106	- customs requirements	1	39
Zyliss Strong Boy	1	14	- Waxoyling	3	87
			Remote key fob – see alarm transmitter above		
18. VARIOUS			Repair manual MG RV8	3	71
Acquiring an MG RV8	1	0	Reimporting RV8s, auctions	6	195
Alarm transmitter			Rover Dealer network	1	0
- ECU, vulnerability	6	191	Rover Dealer network	2	0
- instructions card	8	274			
- reprogramming	1	0			
- replacements	1	0			

RV8 Workshop Notes

Seat belts, inertia reel unlock	9	329
Screws Phillips & Posidriv	9	320
Servicing	1	39
	6	172
Spare parts	1	33
	3	82
Spares, essential for touring abroad	8	288
Stoplock	6	180
Steering locks	6	180
Stolen cars (Japan)	4	112
Storing an RV8 over Winter	7	237
Technical Info CD, RV8	6	-
Toolkits for MG RV8	1	0
	1	9
	2	63
	3	72
	4	106
Toolkit, spare wheel moulding	6	166
Torque wrench settings	2	51
Under bonnet stickers	1	39
VIN identification	1	0
	5	147
Windstop	7	224
Yellow Autolock	6	180
19. INTERIOR & INSTRUMENTS		
Alarm ECU, vulnerability	6	191
Boot bulkhead clips	9	301
Bulkhead clips, boot	9	301
Carpets, replacements source	8	267
Checks before purchase	1	0
Clipstone leather cleaner	1	17
Clipstone conditioner	1	18
Cockpit, too hot	5	126
Cockpit heat, solved	6	170
Courtesy light clips	5	141
Dashboard		
- creak, solving	8	266
- fascia removal	1	12
	1	22
- radio fascia panel	3	79
- refurbishing laquer	8	277
Door cappings		
- cracking	5	154
- refurbishment	5	154
	8	277
- relacquering trim	8	282
Door pockets modification	8	289
Driver headroom tip	1	35
Emergency flares	7	222
Fascia Shellac coating	2	57
Fascia instruments	2	57
Footwell lights	6	165
	6	166
Fuse box & fuses	5	148
Gearbox knob		
- cleaning	1	18
- replacement	1	18
- renovation	3	77
Glovebox	1	12
Glovebox, switch	6	166
Glovebox lid, refurbishing laquer	8	277
Hands free mobile kits	6	193
Heater control cable	5	128
	7	204

	8	247
	8	248
Hot RV8 cockpit	5	126
	6	170
	7	204
	7	227
	8	247
	8	248
Ignition key, replacement	8	296
Ignition warning light glows	8	280
Immobiliser	4	117
Immobiliser – ECU terminal	6	191
Immobiliser, synchronisation	7	234
Instruments		
- misting difficulties	2	57
- oil pressure sensor	2	57
- fascia switch bulbs	3	85
Mobile phone, hands free kits	6	193
Oil pressure switch	9	327
Radio		
- FM waveband converter	2	76
- FM band expander	7	220
- iPod ICE option	7	239
- replacement, reimport	7	221
Seat belts, inertia reel	9	329
Seats, more legroom	5	139
Seats, lowering	7	233
Silkaflex, foil heat shield	6	170
Speaker grilles, replacement		
	8	281
Speedometer	1	39
Sun visor, fire risk unusual	6	190
Sun visor screws	6	166
Tachometer - redlining	7	206
Tachometer removal	9	317
Temperature gauge	7	207
Trim colour	1	0
	3	86
Trim panels removal	1	30
Trim panels, Velcro strips	7	202
Upholstery		
- leathercare tips	1	17
- seat removal	1	30
Velcro strips, trim panels	7	202
Warning light, No Charge		
	6	171
Windstop, fitting	5	127
- another installation	5	143
- Classic Additions, fitting	9	328
- windstop bracket mod	7	228
- neat installation	7	205

Index prepared by Victor Smith (V8 Harvest Gold 1089)