

RV8 Workshop Notes

Index to the whole series

This index covers all volumes of the RV8 Workshop Notes series and will be updated from time to time as the series develops. An updated Index is maintained on the V8 Website at www.v8register.net which holders of RV8 Workshop Notes can download to maintain their copies of the Index.

Topic	Vol	RV8 Note		
1. ENGINE				
Actuator, aircon vacuum flap	11	436		
Adams, Mark, useful rechipping notes	10	360		
	11	402		
	11	403		
	11	410		
Advance & retard pipe	1	39		
	2	60		
	8	258		
Advance retard unit	4	120		
	11	422		
Air filters	1	0		
	1	41		
	3	91		
	3	99		
	4	119		
	6	175		
	11	431		
Air flow meter	1	4		
Air intake sensor	5	130		
Bonnet, gas struts upgrade	10	365		
Bosch starter motor	7	238		
Broken stud removal	12	442		
Coolant bleed insert	11	409		
Crankshaft rear oil seal	3	71		
Cruise control, retrofit	9	341		
Distributor, timing	11	422		
	11	423		
Distributor clamp nut wrench	7	229		
ECU, location, removal & refit				
	5	144		
	10	360		
ECU, rechipping	7	226		
	7	230		
	11	402		
	11	403		
	11	410		
ECU rechipping notes	10	360		
Engine crane or lift	10	397		
Engine load spreader	10	397		
Engine management				
- ECU – what is & what does it do?	11	428		
- Engine management system	11	429		
- ECU fault detection & codes	11	429		
- Diagnostics, ECU	11	429		
- Data link connector	4	115		
			- DLC cover strip	4 115
			- Diagnostic databook	4 122
			- Diagnostic leads	4 118
			- Diagnostic tests	4 118
				4 123
			- Rover Testbook or T4	4 118
			- Test equipment	4 118
			- Tune “Rover speak”	11 429
			Engine performance	
			- EPROMS (chips)	1 21
			- upgrade	1 21
				10 360
			- RPI Engineering	1 21
			- Upgrade	11 410
			Exhaust system	
			- catalytic overheat sensors	3 100
				4 101
			- catalytic converter	3 99
			- clamps	3 97
			- cats, replacements	9 309
			- down pipes	3 97
			- general	1 16
			- hangers, replacing	5 134
			- mounting hooks	1 25
			- manifolds nuts loose	5 138
			- manifold LHS noise	5 138
			- mounting brackets	1 25
			- corrosion	1 25
			- rattle	1 36
			- removal	8 292
			- wrapping or coating	11 416
			Oil filter, replacement	8 284
			Flame trap hoses	
			- clamps	1 4
			- general	1 5
			Flywheel cover plate	3 71
			Heater hoses	1 5
			Heater box corrosion	1 25
			Heater matrix leak, cure	11 414
			Hose clamps	
			- general	1 4
			- Norma	1 4
			- Oetika	1 4
			Hot wire fuel injection system	5 140
			Hot start problem solved	11 437
			Idle	
			- engine erratic	5 140
			- running problems	6 188
			- spasmodic idle problems	6 186
			Ignition module, remote	10 369
			Lucas Hot Wire system	5 140
			Inlet manifold gasket	
			- corrosion	1 25
			- general	1 26
			Mark Adams, chips	10 360
				11 410
			Mass airflow sensor	10 374

RV8 Workshop Notes

Misfire, solving	5	130		11	423
	10	375	Ignition key replacement	1	0
Mountings, engine				8	296
- adjusting the mounts	8	255	Ignition module, remote	10	369
- mounts	3	71	Magnicor plug leads	11	411
- mounts orientation	9	324	Optimax chip, improvements	7	200
Oil filter magnetic wrap	11	408		8	251
Oil pressure switch	9	327		10	360
Oil pump			Part number change points	1	24
- cover & washers	3	88		2	66
- hoses (replacements)	3	88	Starting gremlins		
Optimax chip, improvements	7	200	Timing adjustments with		
	8	251	reimported RV8s	7	200
	10	360		11	422
	11	402	Timing correction in the RV8		
	11	403	Repair Manual AKM7144ENG	11	435
	11	410	Torque wrench settings	2	51
Part number change points	1	24	Unichip connector problems	7	201
PCV valve, check it is clear	8	249			
Pipe clips	1	4	3. COOLING SYSTEM		
Plenum chamber hose	1	4	Antifreeze concerns	9	322
Radiator cover, replacement	10	358	Blanking panel, radiator	4	103
Ratchet, socket set caution	9	353		6	178
Rear oil seal – crankshaft	3	71	Coolant bleed insert	11	409
Remote ignition module	10	369	Coolant loss, cause	10	390
Road speed sensor	11	440	Coolant, refilling system	10	357
Rocker cover 3.9 badge			Coolant refilling, bleed insert	11	409
- badge	4	105	Connecting pipe, corrosion	8	299
- breather element n/s	6	166	Cooling fan modification	10	370
Sensor, air intake	5	130	Cooling fan override switch	10	373
Starter, overheating	5	146	Cooling hose layout	8	295
Starter motor	7	238	Cooling hose kit, identification	9	338
Starting problems	6	188	Expansion tank		
	11	437	- crack in the neck of the tank	390	10
	11	438	- plug	1	10
Stepper motor, cleaning	8	283	- refilling reminder	1	3
Stud, broken - removal	12	442	- corrosion	1	25
Sump gasket, replacement	8	284	- filler plug spanner	1	37
Sump gasket , caution	9	339	- new overflow tank	6	170
Sump gasket modification	11	420	- where does the coolant go?	9	347
Throttle pedal	1	19	Fan, cooling fan modification	10	370
Timing adjustments with			Heater rail modification	9	349
reimported RV8s	7	200	Hose, heavy indentation	9	349
Torque wrench settings	2	51	Hoses, layout	6	185
Unichip connector problems	7	201		8	295
Water pump overhaul	3	99	Hoses, replacements	9	338
Water pump replacement	1	3	Part number change points	1	24
	3	91		5	150
Water pump & air-con drive			Plug, plastic/replacing	5	158
belts	3	90		5	159
Water pump overhaul	9	314	Plug, get you home tip	5	159
Under bonnet checks	1	0	Pressure cap replacement	10	367
			Radiator coolant loss	9	347
2. IGNITION SYSTEM			Radiator cooling fan switch		
Cruise control, retrofit	9	341		2	69
Distributor clamp nut wrench	7	229	Radiator hoses	1	4
Distributor, timing	11	422		4	105
				9	349

RV8 Workshop Notes

Radiator hoses, steel connecting pipe corrosion	8	299	Gauge not reading correctly	8	270
Radiator cover replacement	10	358	Hot wire fuel injection system	5	140
Radiator hose, bleed insert	11	409	Lucas hot wire system	5	140
	11	434	Part number change points	1	24
Radiator hoses, replacements	6	185	Petrol tank		
	8	295	- filler pipe	1	4
	9	338	- filler pipe	1	7
Radiator blanking panel	4	103	- filler pipe restrictor	1	39
	6	178	- general	1	7
Radiator pressure cap	10	367	- hoses	1	4
Radiator shroud stickers	6	181	- Oetika clamps	1	7
Radiator, refilling	10	357	- removal	1	23
Radiator top hose self purging	11	434	- vent pipes	1	7
Radiator, upgraded	6	170	Pipes, safety check	8	285
Thermostat – check it has a vent	11	415	Plenum chamber plug	4	105
Torque wrench settings	2	51	Starter gremlin – fuel cut off switch	2	66
Water pump			Throttle – see engine management systems	4	123
- feed & return	1	4	Torque wrench settings	2	51
- hose	1	5			
- overhaul	9	314	5. CLUTCH		
- replacement	1	3	Clutch master cylinder		
			- cap	1	14
4. FUEL SYSTEM			- repair kit	1	6
Bosch injectors	11	411		8	269
Cruise control, retrofit	9	341	- replacement	1	6
ECU location, removal & refit	5	144	- new part number	1	50
Electronic fuel ignition			- replacement	1	50
- throttle potentiometer	1	45	- vital part number	1	6
- injectors	1	45	Clutch slave cylinder	1	6
- air flow meter	1	45		3	71
- air valve stepper	1	45	Clutch pedal return spring	10	361
Engine management	4	115		10	361
	4	118	Clutch slave repairs	6	197
	4	122	Part number change points	1	24
Fuel cut off switch			Repair kits. Master/slave	8	269
- cut off switch	2	66	Torque wrench settings	2	51
- starting difficulty	7	219			
Fuel filter blocked, check	9	326	6. GEARBOX		
Fuel filter replacement	3	92	Bushes, rubber UKC854	10	381
Fuel pump			Clutch assembly	3	71
- general	1	29	Crunching gears, solving	10	381
- noisy	1	43	Gearbox lubrication, R380	6	163
- resistor	1	43			
- fuel pump	1	45	Gearbox cross member	2	52
- replacement (Bosch)	3	92		3	71
Fuel system			Gearbox mountings	2	52
- hose clamps & clips	1	4		3	71
- Oetika clamps	1	4	Gearbox remote	3	71
- Oetika clamps	1	7	Gearbox remote, grease	10	384
- filters & hoses	1	4	Gearbox removal	3	71
- non evaporative loss system	1	4	Gearbox, LT77S or R380?	11	404
	1	23	Gearknob		
- fuel filter	1	29	- cleaning	1	18
- filter replacement	3	92			
Fuel tank corrosion	9	326			

RV8 Workshop Notes

- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	8	256
Gear lever gaiter replacement	9	333
Gear lever greasing	10	384
Gear lever grommet	4	105
Gear lever remote moving	10	381
Input shaft	3	71
Gearshift pattern LT77S/R380 LT77 gearbox	11	404
- greasing lever & remote	10	384
- rubber bushes rotting	10	381
- lubricant	10	382
- repairing dust cap bracket	11	405
Notchy gearchange cures	10	382
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points	1	24
 R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
– greasing lever & remote	10	384
- lubrication	6	163
	10	382
– repairing dust cap bracket	11	405
- synthetic oils experience	8	264
Rubber bushes UKC854	10	381
Torque wrench settings	2	51
Towing caution	8	252
Which gearbox do I have?	11	404

7. PROPSHAFT

Part number change points	1	24
Torque wrench settings	2	51

8. REAR AXLE

Breather, plastic replacement	11	413
Breather, thread compatibility	11	418
CWP, new supplies	5	156
Limited slip differential	3	84
Noise from back axle	5	155
Part number change points	1	24
Quaife, differences with an LSD	10	388
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156
Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264

Torque wrench settings	2	51
------------------------	---	----

9. REAR SUSPENSION

Hoyle suspension upgrade	7	208
Hoyle – what's it like?	9	310
Hoyle, installation notes	9	311
Hoyle, setting up	10	363
Hoyle, Spax settings	10	364
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Modifications - caution	9	312
Part number change points	1	24
Rear spring shackle	10	383
Rear wheel bearings	1	40
Recall notice	8	244
Shackle, rear spring caution	10	383
Spax Krypton Gas shocks	8	278
Spax replacement shockers	8	278
Spax settings	10	364
Replacement shockers	8	278
Shock absorber, adjustments	6	174
Shockers, adjustment guide	7	214
Suspension upgrade kit	7	208
Torque wrench settings	2	51

10. INSURANCE

Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168

11. STEERING

Ball joints		
- lower	6	166
- upper	6	166
Part number change points	1	24
Castor reduction		
- details of the B&G kit	7	232
- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266
Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235

RV8 Workshop Notes

PAS option review	9	354	Brakes, system & adjustments	9	330
EZ EPAS Swiss approvals	9	355	Brake master cylinder		
Steering column, collapsible	11	430	- repair kit	1	6
Steering rack			- replacement	1	6
- maintenance	2	54		5	152
- mounts warning	8	241	- refurbishing	10	359
- mounts, strengthening	8	242	- replacement yellow tag	10	379
- mounts, cracked report	8	243	Brake fluid choice	8	294
- removal	2	54	Brake pedal return spring	10	361
Torque wrench settings	2	51	Brake servo		
Track rod end	6	166	- failures (warning)	4	102
			- repair kit	1	6
			- replacement	1	6
			- caution, maintenance	4	104
			Brake slave cylinders		
			- repair kit	1	6
			- replacement	1	6
			Discs, caution for eBay		
			advertises for RV8 discs	9	305
			Front brake discs, caution	9	305
			Front brake pads		
			- pads	1	31
				3	96
			- retaining clip	3	99
			Front callipers	1	31
			Front callipers corrosion	3	96
			Glycol brake fluid	8	294
			Handbrake cable	1	31
				4	105
			Handbrake adjustment	3	75
			Handbrake linkage kit	6	166
			Handbrake modification	8	291
			Hydraulic hoses	1	6
			Part number change points		
				1	24
			Rear brake hose lock nut	6	166
			Rear brake & shoes	1	31
				6	162
			Rear brake adjustment		
			- maintenance	3	75
			- full inspection	3	75
			- brake lining removal	3	75
			Rear brake linings, check	6	162
			Rear brake, replacement	6	169
			Rear wheel cylinder gasket		
				6	166
			Return spring replacement	10	361
			Servos and brake systems	8	293
			Silicone brake fluid	8	294
			Torque wrench settings	2	51
			14. ELECTRICAL EQUIPMENT		
			Aerial		
			- replacement	1	11
			Air conditioning		
			- actuator	11	436
			- conditioned air vents	6	189
			- corrosion on fans	6	173

13. BRAKES

RV8 Workshop Notes

	10	376	correctly	8	270
- heater cut-off flap vacuum actuator	11	436	Headlamp units		
- service	1	44	- conversion to LHD	9	308
	10	393		9	313
- more passenger legroom	4	124	- corrosion	1	25
- preventative maintenance	10	376	- cowl, removal	6	167
- recharging an aircon system	10	378	- cowl removal & replacement	11	417
	10	393	- replacement (Bosch)	1	1
- removal of the a/c system?	6	184	- replacement	2	65
Alarm transmitter			- retainers	6	167
- caution	1	0	Heater blower motor & fuse	9	336
-deactivating the volumetric sensor	10	371	Indicators, front		
- renew batteries	1	0	- changing amber to clear lenses	6	177
- replacement	1	0		8	253
- reprogramming	1	0	- connector terminal corrosion		
	8	260		5	157
- solving alarm not working	10	399	Immobiliser	4	117
Alternator			Immobiliser – ECU terminal	6	191
- exchange	6	163	Immobiliser - synchronisation	7	234
- no charge warning	6	171	Immobiliser, volumetric sensor	10	371
- replacement	1	48	Instruments in fascia	1	24
- no charge light stays on	8	290	Insulation cracking	4	110
- problem solving	11	421	Interior lights control caution	11	407
Battery			Key fob, alarm not working	10	399
- condition device	2	56	LED replacement bulbs	10	386
- conditioner	7	237		10	387
- conditioner, connecting up	11	425	Lens, indicator – changing from amber to clear	6	176
- filler bottle	3	78	No charge light stays on	8	290
- fixings, missing	5	134	Part number change point		
- increased capacity batteries	8	257		1	24
- lifter/carrier	1	9	Petrol tank sender unit	4	105
- Snap-On tools lifter	3	73	Radio		
- another source, lifter	3	78	- CD stacker, fitting	7	239
Boot opening switch bulb	10	368	- conversion (Japan)	1	39
Boot opening switch on dash	12	443	- frequency converter	3	76
Bulb, dashboard replacement	10	368		7	220
Bulbs, replacing with LEDs	10	386		7	221
Central locking, retrofit	9	340	Relay No 1, replacing	6	165
Conditioned air vents	6	189	Rev counter removal	9	318
Cooling fan modification	10	370	Reverse lamp lucars	3	71
Cooling fan override switch	10	373	Reversing light switch	7	212
Cruise control, retrofit	9	341	Rear light cluster	4	105
Dashboard switch bulb	10	368	Saving electrical parts	3	99
DRLs (daytime running lights)	10	398	Speaker grilles, replacement		
Daytime running lights, fitting	10	398		8	281
FM radio frequency converter	3	76	Speedometer change (import)	11	432
			Speedometer repairs	9	306
Fog lights			Starter motor		
- fog lights	1	39	- Bosch starter motor	7	238
- replacement sources	6	199	- not turning over	11	438
Footwell lights	6	165	- overheating	5	146
Fuel pump resistor	1	43	- terminals corrosion	1	25
Front indicator lamp corrosion	5	157	- terminals repair	1	28
	6	163	Tachometer removal	9	318
Fuse box & fuses	5	148	Torque wrench settings	2	51
Fuel gauge not reading			Volumetric sensor	10	371

RV8 Workshop Notes

Warning light, No Charge	6	171
Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105
Wiper relays failed?	9	321

15. WHEELS & TYRES

Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points	1	24
Pressures, modern tyres	9	337
Road wheels		
- centre caps	1	10
	9	315
- changed castings	1	10
- corrosion	1	15
	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- refurbishment	9	314
	9	317
	10	389
- refurbishment specialist	10	362
- wheel centre badges	1	15
	8	276
	9	315
	9	317
- wheel lock nuts, wear	3	81
Sealants	8	298
	10	372
Space saver tyres, check	5	133
	8	297
Studs, dummy need care	8	261
	9	315
Torque wrench settings	2	51
Tired tyres, stored RV8s	5	132
Tyres		
- replacements	5	160
- replacements, suppliers	6	182
- more on replacements	6	179
- update on replacement tyres	6	198
- pressures	6	174
- pressures again	6	196
- pressures, modern tyres	9	337
- sealants for tyres	8	298
	10	372
- spacesaver views	10	372
- spacesaver wheel & tyre	9	304
- spacesavers, critical view	9	307
- more on spacesavers	9	316
- suppliers, recommended	6	182
- tyres size calculator	10	395
Wheel nuts, locking	4	121

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Badges, RV8 lettering	9	342
Bonnet alignment		
- alignment	3	80
- Gas struts upgrade	10	365
- release cable	6	166
- stay, clip	6	166
Boot		
- Boot lock dashboard switch		
bulb	10	366
- boot lock switch	10	366
- gas struts	8	259
- gas struts, regassing	9	323
- gas struts, replacements	9	323
- general	1	23
- luggage rack options	9	346
- release mechanism	5	149
- tool stowage mould	1	23
- warning (closing)	1	0
Bumper, rear, realignment	9	325
Cleaning to near concours standards	11	426
Club badge mounting	2	58
	3	95
Colours (paintwork)	1	0
	2	0
Corrosion checks	1	25
	1	42
	3	87
Door glass		
- removal	2	68
- refitting	2	68
- part numbers	2	68
Door handles	5	151
Door mirrors	1	2
- rubber covers	3	74
- knob handles	3	74
- mirror glass	3	74
	6	166
Door seal, inner	5	153
Electric wing mirrors, fitting	10	375
Exterior checks	1	0
Fire risk, unusual/visor mirror	6	190
Gas struts, caution	4	114
	8	259
Gaiter, rubber replacement	9	333
Gear lever gaiter replacement	9	333
Header rail corrosion	1	25
Headlamp cowl, remove	6	167
Headlamp change to LHD	9	308
Hood		
- catches, safety check	8	286

RV8 Workshop Notes

- catches, check fixings	9	332	Seats, more legroom	5	139
- cleaning/refurb	4	107	Seats, lowering	7	233
- fitting	1	0	Side skirt removal	5	145
- operation	1	0	Sills		
- polish, plastic rear window	9	303	- mounting brackets	1	25
	10	380	- tread plates	1	27
- rattle	1	20		4	105
- rear surround	1	25	Tonneau covers		
- Renovo products	4	113	- full	2	55
	9	303	- half	2	55
- replacement, caution	8	262	Torque wrench settings	2	51
- replacement hoods, more	8	268	Touch up paint codes	8	300
- sheared pivot repair	1	47	Touch up paint sources	11	439
- stiff operation	1	46	Tow bar, fitting	9	319
- toggle catch checks	9	332	Underbody knocks	6	187
Hood backlight			Water leaks	1	22
- avoiding crease	4	108		2	62
- cat deterrent!	2	53		5	136
- press stud tool	9	348		9	350
- rear window polish	9	303	Waxoyling reimports	3	87
- replacement	2	53	Wheel arch flares	2	70
- zip use & repair	4	109	Windscreen		
	10	394	- carbon fibre replacement	8	246
- zip lubrication	9	343	- checks	1	0
Hood rear window see backlight above			- frame corrosion	1	25
Indicator lenses, changing to clear	6	176	- leaks, water ingress	3	93
Inner door seal retainer strip	5	153		5	136
Jack with the RV8, concerns	9	331	- refitting	1	22
Knocking noise, underbody	6	187	- replacement surround	8	246
Legroom, increasing	5	139	- removal	1	22
Lens, indicator – changing from amber to clear			- rust, pictures	7	225
	6	176	- sealing rubbers	1	22
	8	253	- VIN number etching	3	89
Luggage, fitted set for an RV8	9	431		8	273
Luggage rack options	9	346	Windscreen glass		
MGF electric wing mirrors	10	375	- removal	1	22
Noise from engine on LHS			- refitting	1	22
	5	138	- replacement supply	7	240
Nose cone, removal	7	203	Windstop, fitting	5	127
Number plates				9	328
- correct plates, avoid a fine	10	396	Windstop	7	224
- doublesided tape	7	236	Windstop bracket mod	7	228
- rear fixings	1	39	Windstop design, folding	9	345
- removing Japan spec plate	7	217	Windstop, folding design	9	345
- replacement number plate	8	279	Windstop for taller drivers	9	302
Paint codes	4	125	Wing mirrors, electric	10	375
	8	300		10	377
Paint sources	11	439	Wings		
Part number change points			- Rover badges (Japan)	1	39
	1	24	Wiper bezel	5	151
Retainer strip, inner door seal	5	153	Wiper blades adjustment	1	13
Rear window, hood			Wipe maintenance	12	444
See hood backlight above					
Rear bumper alignment	9	325	17. SERVICE TOOLS		
Seats, unusual fire risk!	6	190	Auten hydraulic car lift	7	209
			Britool equipment	3	71
			Draper tool 176	1	12
				1	23

RV8 Workshop Notes

Draper tool T40	1	12	Luggage rack options	9	346
Filler plug spanner	1	37	Maintenance locations	1	0
Hydraulic car lift or ramp	7	209	Mobile phone, new law	6	193
Jack, using it on an RV8	11	427	Old parts, hang on to them		
Lift, hydraulic	7	209		1	33
Tool storage moulding	1	23		3	91
RV8 toolkit			Phillips & Posidriv differences	9	320
- checklist of contents	1	9	Plaques, rally	8	287
- general	1	39	Posidriv & Phillips differences	9	320
- replacements	2	63	Publications:		
- new toolkit supplies	4	106	Owners Handbook		
- torch replacement	3	72	AKM7144	1	0
Sump plug spanner	1	37	Owners Service Record		
	4	106	AKM7150	1	0
Trolley jack, using on an RV8	11	427	Owners Info Portfolio		
Zyliss Strong Boy	1	14	AKM7158	1	0
			Repair Manual		
			AKM7153	1	0
18. VARIOUS				4	118
Acquiring an MG RV8	1	0	Engine Manual		
Alarm transmitter			AKM7154ENG	1	0
- ECU, vulnerability	6	191	LT77 Gearbox Manual		
- instructions card	8	274	AKM7155ENG	1	0
- reprogramming	1	0	RAWS, first approval	7	223
- replacements	1	0	R380 Gearbox Manual		
- retrofitting alarm & central locking system	5	142	AKM7225	1	0
Auctions in Japan	6	195	Rally plaques for the RV8	8	287
Badge bar for an RV8	8	250	Reimporting from Japan		
Buying an MG RV8			- to Australia	5	135
- guidance note	1	0	- Australian RAWS update	7	215
- dreams come true!	3	83	- checklist	1	39
- reimporter's checks	4	112	- options, local agent?	6	192
Cleaning an RV8 to near concours standard	11	426	- corrosion checks	3	87
Colours, for the RV8	7	216	- type approval	1	39
Concours, cleaning an RV8	11	426	- customs requirements	1	39
Dehumidifier, Winter storage	7	237	- Waxoyling	3	87
Disklock	6	180	Remote key fob – see alarm transmitter above		
DVLA info on your car	11	433	Ratchet, socket set caution	9	353
DVLA info update	12	441	Repair manual MG RV8	3	71
Fire extinguishers in cars	4	110	Reimporting RV8s, auctions	6	195
Fire risk, unusual/mirror	6	190	Rover Dealer network	1	0
Gas struts, fire risk	4	114	Rover Dealer network	2	0
Hands free phone, new law	6	193	Seat belts, inertia reel unlock	9	329
Hood press studs	9	348	Screws Phillips & Posidriv	9	320
How many RV8s were made?	7	216	Servicing	1	39
Importing to Australia	5	135		6	172
Jack with the RV8, concerns	9	331	Spare parts	1	33
Japan reimports of RV8s				3	82
- car documents	1	39	Spares, essential for touring abroad	8	288
- checklist	1	0	Stoplock	6	180
- checks & tips	1	39	Steering locks	6	180
- ownership checks	4	112	Stolen cars (Japan)	4	112
- Modifications	4	120	Storing an RV8 over Winter	7	237
Land Transport Safety Authority, New Zealand	1	33	Technical Info CD, RV8	6	-
Le Mans visit - tips	1	49	Toolkits for MG RV8	1	0
Luggage, fitted set for an RV8	9	351		1	9
				2	63

RV8 Workshop Notes

	3	72	Hands free mobile kits	6	193
	4	106	Headrest upgrade	11	400
Toolkit, spare wheel moulding			Headrest, leather cushions	11	400
	6	166	Heater blower motor & fuse	9	336
Torque wrench settings	2	51	Heater control cable	5	128
Under bonnet stickers	1	39		7	204
VIN identification	1	0		8	247
	5	147		8	248
Water leaks cure, legwell	9	350	Heater matrix leak, cure	11	414
Windstop	7	224	Hot RV8 cockpit	5	126
Windstop, folding design	9	345		6	170
Yellow Autolock	6	180		7	204
				7	227
				8	247
				8	248
19. INTERIOR & INSTRUMENTS			Ignition key, replacement	8	296
Alarm ECU, vulnerability	6	191	Ignition warning light glows	8	280
Ashtray insert	9	334	Immobiliser	4	117
Bezels, removing bezels	9	344	Immobiliser – ECU terminal	6	191
Boot bulkhead clips	9	301	Immobiliser, synchronisation	7	234
Boot opening switch on dash	12	443	Instruments		
Bulkhead clips, boot	9	301	- bezels, removing	9	344
Carpets, replacements source	8	267	- misting difficulties	2	57
Central locking, retrofit	9	340	- oil pressure sensor	2	57
Checks before purchase	1	0	- fascia switch bulbs	3	85
Clipstone leather cleaner	1	17	Interior lights control caution	11	407
Clipstone conditioner	1	18	Luggage, fitted	9	351
Cockpit, too hot	5	126	Mobile phone, hands free kits	6	193
Cockpit heat, solved	6	170	Oil pressure switch	9	327
Courtesy light clips	5	141	Radio		
Cruise control, retrofit	9	341	- FM waveband converter	2	76
Dashboard			- FM band expander	7	220
- creak, solving	8	266	- iPod ICE option	7	239
- fascia removal	1	12	- replacement, reimport	7	221
	1	22	Seat belts, inertia reel	9	329
- radio fascia panel	3	79	Seat belt refurbishment	10	391
- refurbishing laquer	8	277		11	424
Door cappings			Seat belts, replacement	11	424
- cracking	5	154	Seat belt stalks, repair/gaiter	10	392
- refurbishment	5	154	Seat frame, colour	9	352
	8	277	Seat frames, refurbishment	9	352
- relacquering trim	8	282	Seats, headrest upgrade	11	400
Door pockets modification	8	289	Seats, more legroom	5	139
Driver headroom tip	1	35	Seats, lowering	7	233
Emergency flares	7	222	Seats touch up	11	419
Fascia Shellac coating	2	57	Silkaflex, foil heat shield	6	170
Fascia instruments	2	57	Speaker grilles, replacement		
Footwell lights	6	165		8	281
	6	166	Speedometer	1	39
Fuse box & fuses	5	148	Speedometer, replacement		
Gaiter, rubber replacement	9	333	mph dial for a reimport	11	432
Gearbox knob			Sun visor, fire risk unusual	6	190
- cleaning	1	18	Sun visor screws	6	166
- replacement	1	18	Tachometer - redlining	7	206
- renovation	3	77	Tachometer removal	9	317
Gear lever gaiter replacement	9	333	Temperature gauge	7	207
Glovebox	1	12	Trim colour	1	0
Glovebox, switch	6	166		3	86
Glovebox lid, refurbishing	8	277			
laquer					

RV8 Workshop Notes

Trim panels removal	1	30
Trim panels, Velcro strips	7	202
Upholstery		
- leathercare tips	1	17
	11	419
- seat removal	1	30
- seat touch up	11	419
Velcro strips, trim panels	7	202
Warning light, No Charge	6	171
Water leaks legwell	9	350
Windstop, fitting	5	127
- another installation	5	143
- Classic Additions, fitting	9	328
- drawings of a windstop	9	335
- folding windstop design	9	345
- neat installation	7	205
- photos of a windstop	9	335
- windstop bracket mod	7	228

Index prepared by Victor Smith (V8 Harvest Gold 1089)