

RV8 Workshop Notes

Mass airflow sensor	10	374	Distributor, timing	11	422
Misfire, solving	5	130		11	423
	10	375	Ignition key replacement	1	0
Mountings, engine				8	296
- adjusting the mounts	8	255	Ignition module, remote	10	369
- mounts	3	71	Magnicor plug leads	11	411
- mounts orientation	9	324	Optimax chip, improvements	7	200
Oil filter magnetic wrap	11	408		8	251
Oil pressure switch	9	327		10	360
Oil pump			Part number change points	1	24
- cover & washers	3	88		2	66
- hoses (replacements)	3	88	Starting gremlins	2	66
Optimax chip, improvements	7	200	Timing adjustments with		
	8	251	reimported RV8s	7	200
	10	360		11	422
	11	402	Timing correction in the RV8		
	11	403	Repair Manual AKM7144ENG	11	435
	11	410	Torque wrench settings	2	51
Part number change points	1	24	Unichip connector problems	7	201
PCV valve, check it is clear	8	249			
Pipe clips	1	4	3. COOLING SYSTEM		
Plenum chamber hose	1	4	Antifreeze concerns	9	322
Radiator cover, replacement	10	358	Blanking panel, radiator	4	103
Ratchet, socket set caution	9	353		6	178
Rear oil seal – crankshaft	3	71	Coolant bleed insert	11	409
Remote ignition module	10	369	Coolant loss, cause	10	390
Road speed sensor	11	440	Coolant, refilling system	10	357
Rocker cover 3.9 badge			Coolant refilling, bleed insert	11	409
- badge	4	105	Coolant, waterless - concerns	12	446
- breather element n/s	6	166	Connecting pipe, corrosion	8	299
Sensor, air intake	5	130	Cooling fan modification	10	370
Starter, overheating	5	146	Cooling fan override switch	10	373
Starter motor	7	238	Cooling hose layout	8	295
Starting problems	6	188	Cooling hose kit, identification	9	338
	11	437	Expansion tank		
	11	438	- crack in the neck of the tank	390	10
Stepper motor, cleaning	8	283	- plug	1	10
Stud, broken - removal	12	442	- refilling reminder	1	3
Sump gasket, replacement	8	284	- corrosion	1	25
Sump gasket , caution	9	339	- filler plug spanner	1	37
Sump gasket modification	11	420	- new overflow tank	6	170
Throttle pedal	1	19	- where does the coolant go?	9	347
Timing adjustments with			Fan, cooling fan modification	10	370
reimported RV8s	7	200	Heater rail modification	9	349
Torque wrench settings	2	51	Hose, heavy indentation	9	349
Unichip connector problems	7	201	Hoses, layout	6	185
Water pump overhaul	3	99		8	295
Water pump replacement	1	3	Hoses, replacements	9	338
	3	91	Part number change points	1	24
Water pump & air-con drive				5	150
belts	3	90	Plug, plastic/replacing	5	158
Water pump overhaul	9	314		5	159
Under bonnet checks	1	0	Plug, get you home tip	5	159
			Pressure cap replacement	10	367
2. IGNITION SYSTEM			Radiator coolant loss	9	347
Cruise control, retrofit	9	341	Radiator cooling fan switch		
Distributor clamp nut wrench	7	229		2	69
			Radiator hoses	1	4

RV8 Workshop Notes

	4	105	- fuel filter	1	29
	9	349	- filter replacement	3	92
Radiator hoses, steel			Fuel tank corrosion	9	326
connecting pipe corrosion	8	299	Gauge not reading correctly	8	270
Radiator cover replacement	10	358	Hot wire fuel injection system		
Radiator hose, bleed insert	11	409		5	140
	11	434	Lucas hot wire system	5	140
Radiator hoses, replacements			Part number change points		
	6	185		1	24
	8	295	Petrol tank		
	9	338	- filler pipe	1	4
Radiator blanking panel	4	103	- filler pipe	1	7
	6	178	- filler pipe restrictor	1	39
Radiator pressure cap	10	367	- general	1	7
Radiator shroud stickers	6	181	- hoses	1	4
Radiator, refilling	10	357	- Oetika clamps	1	7
Radiator top hose self purging	11	434	- removal	1	23
Radiator, upgraded	6	170	- vent pipes	1	7
Thermostat – check it has a vent	11	415	Pipes, safety check	8	285
Torque wrench settings	2	51	Plenum chamber plug	4	105
Water pump			Starter gremlin – fuel cut off switch	2	66
- feed & return	1	4	Throttle – see engine management systems	4	123
- hose	1	5	Torque wrench settings	2	51
- overhaul	9	314			
- replacement	1	3	5. CLUTCH		
Waterless coolant concerns	12	446	Clutch master cylinder		
			- cap	1	14
4. FUEL SYSTEM			- repair kit	1	6
Bosch injectors	11	411		8	269
Cruise control, retrofit	9	341	- replacement	1	6
ECU location, removal & refit	5	144	- new part number	1	50
Electronic fuel ignition			- replacement	1	50
- throttle potentiometer	1	45	- vital part number	1	6
- injectors	1	45	Clutch slave cylinder	1	6
- air flow meter	1	45		3	71
- air valve stepper	1	45	Clutch pedal return spring	10	361
Engine management	4	115		10	361
	4	118	Clutch slave repairs	6	197
	4	122	Part number change points		
Fuel cut off switch				1	24
- cut off switch	2	66	Repair kits. Master/slave	8	269
- starting difficulty	7	219	Torque wrench settings	2	51
Fuel filter blocked, check	9	326			
Fuel filter replacement	3	92	6. GEARBOX		
Fuel pump			Bushes, rubber UKC854	10	381
- general	1	29	Clutch assembly	3	71
- noisy	1	43	Crunching gears, solving	10	381
- resistor	1	43	Gearbox lubrication, R380		
- fuel pump	1	45		6	163
- replacement (Bosch)	3	92	Gearbox cross member	2	52
Fuel system				3	71
- hose clamps & clips	1	4	Gearbox mountings	2	52
- Oetika clamps	1	4		3	71
- Oetika clamps	1	7	Gearbox remote	3	71
- filters & hoses	1	4	Gearbox remote, grease	10	384
- non evaporative loss system	1	4	Gearbox removal	3	71
	1	23			

RV8 Workshop Notes

Gearbox, LT77S or R380?	11	404	Synthetic oil recommended	6	263
Gearknob			Synthetic oils experience	8	264
- cleaning	1	18	Torque wrench settings	2	51
- renovation	3	71			
- replacement	1	18	9. REAR SUSPENSION		
- replacement, elm burr knob	8	256	Hoyle suspension upgrade	7	208
Gear lever gaiter replacement	9	333	Hoyle – what's it like?	9	310
Gear lever greasing	10	384	Hoyle, installation notes	9	311
Gear lever grommet	4	105	Hoyle, setting up	10	363
Gear lever remote moving	10	381	Hoyle, Spax settings	10	364
Input shaft	3	71	Konis, adjusting & settings	7	214
Gearshift pattern LT77S/R380	11	404	Konis, uprated		
LT77 gearbox			- fitting a set	7	210
- greasing lever & remote	10	384	- in use in the Alps	7	211
- rubber bushes rotting	10	381	Lowering blocks	6	196
- lubricant	10	382	Lowering the back end	6	196
- repairing dust cap bracket	11	405	Modifications - caution	9	312
Notchy gearchange cures	10	382	Part number change points		
Oil change, photos	8	275		1	24
Oil, experience with synthetic	8	264	Rear spring shackle	10	383
Part number change points			Rear wheel bearings	1	40
	1	24	Recall notice	8	244
R380 gearbox			Shackle, rear spring caution	10	383
- changing oil & access	7	213	Spax Krypton Gas shocks	8	278
	8	271	Spax replacement shockers	8	278
	8	272	Spax settings	10	364
- change point	6	163	Replacement shockers	8	278
– greasing lever & remote	10	384	Shock absorber, adjustments	6	174
- lubrication	6	163	Shockers, adjustment guide	7	214
	10	382	Suspension upgrade kit	7	208
– repairing dust cap bracket	11	405	Torque wrench settings	2	51
- synthetic oils experience	8	264			
Rubber bushes UKC854	10	381	10. INSURANCE		
Torque wrench settings	2	51	Classic car cover		
Towing caution	8	252	- agreed value	2	61
Which gearbox do I have?	11	404	- reinstatement cost	2	61
			- specialist brokers	2	61
			- obtaining valuations	2	61
7. PROPSHAFT			Disclosure reminder	4	-
Part number change points			Immobilisers	4	117
	1	24	Renewals, no grace period	7	218
Torque wrench settings	2	51	Thatcham 1 immobiliser	4	117
				6	168
8. REAR AXLE			Thatcham 2 immobiliser	4	117
Breather, plastic replacement	11	413		6	168
Breather, thread compatibility	11	418			
CWP, new supplies	5	156	11. STEERING		
Limited slip differential	3	84	Ball joints		
Noise from back axle	5	155	- lower	6	166
Part number change points	1	24	- upper	6	166
Quaife, differences with an LSD	10	388	Part number change points		
Rear shock absorber				1	24
- lower mounting bolt	1	32	Castor reduction		
- replacement	1	32	- details of the B&G kit	7	232
- servicing	1	32	- kit is not right for the RV8	7	231
Rear wheel bearings	1	40	Pacing washers, dashboard creak	8	266
Rebuild & refurbishment	5	156	Power assisted steering	7	235
Replacement axles	6	169			

RV8 Workshop Notes

Steering locks	6	180
Steering, PAS	7	235
PAS option review	9	354
EZ EPAS Swiss approvals	9	355
Steering column, collapsible	11	430
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166

12. FRONT SUSPENSION

Ball joints, steering		
- lower	6	166
- upper	6	166
Bump stop replacement	8	254
Bush replacement in AR bar eye	10	385
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
- further caution	9	312
Drop links, checks	11	410
Drop links, replacement parts	11	412
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points	1	24
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99
- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spax, replacement shockers	8	278
Spax settings	10	364
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51
Track rod end	6	166

13. BRAKES

Brakes, system & adjustments	9	330
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
- refurbishing	10	359
- replacement yellow tag	10	379
Brake fluid choice	8	294
Brake pedal return spring	10	361
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6
- replacement	1	6
Discs, caution for eBay adverts for RV8 discs	9	305
Front brake discs, caution	9	305
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291
Hydraulic hoses	1	6
Part number change points	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket	6	166
Return spring replacement	10	361
Servos and brake systems	8	293
Silicone brake fluid	8	294
Torque wrench settings	2	51

14. ELECTRICAL EQUIPMENT

Aerial		
- replacement	1	11
Air conditioning		
- actuator	11	436

RV8 Workshop Notes

- conditioned air vents	6	189	Fuse box & fuses	5	148
- corrosion on fans	6	173	Fuel gauge not reading correctly	8	270
	10	376	Headlamp units		
- heater cut-off flap vacuum actuator	11	436	- conversion to LHD	9	308
- service	1	44		9	313
	10	393	- corrosion	1	25
- more passenger legroom	4	124	- cowl, removal	6	167
- preventative maintenance	10	376	- cowl removal & replacement	11	417
- recharging an aircon system	10	378	- replacement (Bosch)	1	1
	10	393	- replacement	2	65
- removal of the a/c system?	6	184	- retainers	6	167
Alarm transmitter			Heater blower motor & fuse	9	336
- caution	1	0	Indicators, front		
-deactivating the volumetric sensor	10	371	- changing amber to clear lenses	6	177
- renew batteries	1	0		8	253
- replacement	1	0	- connector terminal corrosion		
- reprogramming	1	0		5	157
	8	260	Immobiliser	4	117
- solving alarm not working	10	399	Immobiliser – ECU terminal	6	191
Alternator			Immobiliser - synchronisation	7	234
- exchange	6	163	Immobiliser, volumetric sensor	10	371
- no charge warning	6	171	Instruments in fascia	1	24
- replacement	1	48	Insulation cracking	4	110
- no charge light stays on	8	290	Interior lights control caution	11	407
- problem solving	11	421	Key fob, alarm not working	10	399
Battery			LED replacement bulbs	10	386
- condition device	2	56		10	387
- conditioner	7	237	Lens, indicator – changing from amber to clear	6	176
- conditioner, connecting up	11	425	No charge light stays on	8	290
- filler bottle	3	78	Part number change point		
- fixings, missing	5	134		1	24
- increased capacity batteries	8	257	Petrol tank sender unit	4	105
- lifter/carrier	1	9	Radio		
- Snap-On tools lifter	3	73	- CD stacker, fitting	7	239
- another source, lifter	3	78	- conversion (Japan)	1	39
Boot opening switch bulb	10	368	- frequency converter	3	76
Boot opening switch on dash	12	443		7	220
Bulb, dashboard replacement	10	368		7	221
Bulbs, replacing with LEDs	10	386	Relay No 1, replacing	6	165
Central locking, retrofit	9	340	Rev counter removal	9	318
Conditioned air vents	6	189	Reverse lamp lucars	3	71
Cooling fan modification	10	370	Reversing light switch	7	212
Cooling fan override switch	10	373	Rear light cluster	4	105
Cruise control, retrofit	9	341	Saving electrical parts	3	99
Dashboard switch bulb	10	368	Speaker grilles, replacement		
DRLs (daytime running lights)	10	398		8	281
Daytime running lights, fitting	10	398	Speedometer change (import)	11	432
FM radio frequency converter	3	76	Speedometer repairs	9	306
			Starter motor		
Fog lights			- Bosch starter motor	7	238
- fog lights	1	39	- not turning over	11	438
- replacement sources	6	199	- overheating	5	146
Footwell lights	6	165	- terminals corrosion	1	25
Fuel pump resistor	1	43	- terminals repair	1	28
Front indicator lamp corrosion	5	157	Tachometer removal	9	318
	6	163			

RV8 Workshop Notes

Torque wrench settings	2	51
Volumetric sensor	10	371
Warning light, No Charge	6	171
Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105
Wiper relays failed?	9	321

15. WHEELS & TYRES

Alloy wheels, who made them	12	447
Badges, removing	8	276
Centres, wheels, fixings	12	448
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points	1	24
Pressures, modern tyres	9	337
Road wheels		
- centre caps	1	10
	9	315
- changed castings	1	10
- corrosion	1	15
	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- refurbishment	9	314
	9	317
	10	389
- refurbishment specialist	10	362
- plastic rivets	12	447
- wheel centre badges	1	15
	8	276
	9	315
	9	317
- wheel lock nuts, wear	3	81
- who made the alloy wheels?	12	447
Sealants	8	298
	10	372
Space saver tyres, check	5	133
	8	297
Studs, dummy need care	8	261
	9	315
Torque wrench settings	2	51
Tired tyres, stored RV8s	5	132
Tyres		
- replacements	5	160
- replacements, suppliers	6	182
- more on replacements	6	179
- update on replacement tyres	6	198
- pressures	6	174
- pressures again	6	196
- pressures, modern tyres	9	337
- sealants for tyres	8	298
	10	372
- spacesaver views	10	372

- spacesaver wheel & tyre	9	304
- spacesavers, critical view	9	307
- more on spacesavers	9	316
- suppliers, recommended	6	182
- tyres size calculator	10	395
Wheel centres, fixings	12	448
Wheel nuts, locking	4	121

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Badges, RV8 lettering	9	342
Bonnet alignment		
- alignment	3	80
- Gas struts upgrade	10	365
- release cable	6	166
- stay, clip	6	166
Boot		
- Boot lock dashboard switch		
bulb	10	366
- boot lock switch	10	366
- boot dash switch	12	443
- boot fails to open	12	443
- gas struts	8	259
- gas struts, regassing	9	323
- gas struts, replacements	9	323
- general	1	23
- luggage rack options	9	346
- release mechanism	5	149
- tool stowage mould	1	23
- warning (closing)	1	0
Bumper, rear, realignment	9	325
Cleaning to near concours standards	11	426
Club badge mounting	2	58
	3	95
Colours (paintwork)	1	0
	2	0
Corrosion checks	1	25
	1	42
	3	87
Door glass		
- removal	2	68
- refitting	2	68
- part numbers	2	68
Door handles	5	151
Door mirrors	1	2
- rubber covers	3	74
- knob handles	3	74
- mirror glass	3	74
	6	166
Door seal, inner	5	153
Electric wing mirrors, fitting	10	375
Exterior checks	1	0
Fire risk, unusual/visor mirror	6	190

RV8 Workshop Notes

Gas struts, caution	4	114		8	300
	8	259	Paint sources	11	439
Gaiter, rubber replacement	9	333	Parking sensor, rear	12	449
Gear lever gaiter replacement	9	333	Part number change points		
Header rail corrosion	1	25		1	24
Headlamp cowl, remove	6	167	Retainer strip, inner door seal	5	153
Headlamp change to LHD	9	308	Rear window, hood		
Hood			See hood backlight above		
- catches, safety check	8	286	Rear bumper alignment	9	325
- catches, check fixings	9	332	Rear bumper sensor	12	449
- cleaning/refurb	4	107	Seats, unusual fire risk!	6	190
- fitting	1	0	Seats, more legroom	5	139
- operation	1	0	Seats, lowering	7	233
- polish, plastic rear window	9	303	Side skirt removal	5	145
	10	380	Sills		
- rattle	1	20	- mounting brackets	1	25
- rear surround	1	25	- tread plates	1	27
- Renovo products	4	113		4	105
	9	303	Tonneau covers		
- replacement, caution	8	262	- full	2	55
- replacement hoods, more	8	268	- half	2	55
- sheared pivot repair	1	47	Torque wrench settings	2	51
- stiff operation	1	46	Touch up paint codes	8	300
- toggle catch checks	9	332	Touch up paint sources	11	439
Hood backlight			Tow bar, fitting	9	319
- avoiding crease	4	108	Underbody knocks	6	187
- cat deterrent!	2	53	Water leaks	1	22
- press stud tool	9	348		2	62
- rear window polish	9	303		5	136
- replacement	2	53		9	350
- zip use & repair	4	109	Waxoyling reimports	3	87
	10	394	Wheel arch flares	2	70
- zip lubrication	9	343	Windscreen		
Hood rear window see backlight above			- carbon fibre replacement	8	246
Indicator lenses, changing to clear	6	176	- checks	1	0
Inner door seal retainer strip	5	153	- frame corrosion	1	25
Jack with the RV8, concerns	9	331	- leaks, water ingress	3	93
Knocking noise, underbody	6	187		5	136
Legroom, increasing	5	139	- refitting	1	22
Lens, indicator – changing from amber to clear			- replacement surround	8	246
	6	176	- removal	1	22
	8	253	- rust, pictures	7	225
Luggage, fitted set for an RV8	9	431	- sealing rubbers	1	22
Luggage rack options	9	346	- VIN number etching	3	89
MGF electric wing mirrors	10	375		8	273
Noise from engine on LHS			Windscreen glass		
	5	138	- removal	1	22
Nose cone, removal	7	203	- refitting	1	22
Number plates			- replacement supply	7	240
- correct plates, avoid a fine	10	396	Windscreen wiper		
- doublesided tape	7	236	maintenance	12	444
- rear fixings	1	39	Windstop, fitting	5	127
- removing Japan spec plate	7	217		9	328
- replacement number plate	8	279	Windstop	7	224
Paint codes	4	125	Windstop bracket mod	7	228
			Windstop design, folding	9	345
			Windstop, folding design	9	345
			Windstop for taller drivers	9	302

RV8 Workshop Notes

Wing mirrors, electric	10	375	How many RV8s were made?	7	216
	10	377	Importing to Australia	5	135
Wings			Jack with the RV8, concerns	9	331
- Rover badges (Japan)	1	39	Japan reimports of RV8s		
Wiper bezel	5	151	- car documents	1	39
Wiper blades adjustment	1	13	- checklist	1	0
Wipe maintenance	12	444	- checks & tips	1	39
			- ownership checks	4	112
17. SERVICE TOOLS			- Modifications	4	120
Auten hydraulic car lift	7	209	Land Transport Safety		
Britool equipment	3	71	Authority, New Zealand	1	33
Draper tool 176	1	12	Le Mans visit - tips	1	49
	1	23	Luggage, fitted set for an RV8	9	351
Draper tool T40	1	12	Luggage rack options	9	346
Filler plug spanner	1	37	Maintenance locations	1	0
Hydraulic car lift or ramp	7	209	Mobile phone, new law	6	193
Jack, using it on an RV8	11	427	Old parts, hang on to them		
Lift, hydraulic	7	209		1	33
Tool storage moulding	1	23		3	91
RV8 toolkit			Phillips & Posidriv differences	9	320
- checklist of contents	1	9	Plaques, rally	8	287
- general	1	39	Posidriv & Phillips differences	9	320
- replacements	2	63	Publications:		
- new toolkit supplies	4	106	Owners Handbook		
- torch replacement	3	72	AKM7144	1	0
Sump plug spanner	1	37	Owners Service Record		
	4	106	AKM7150	1	0
Trolley jack, using on an RV8	11	427	Owners Info Portfolio		
Zyliss Strong Boy	1	14	AKM7158	1	0
			Repair Manual		
18. VARIOUS			AKM7153	1	0
Acquiring an MG RV8	1	0		4	118
Alarm transmitter			Engine Manual		
- ECU, vulnerability	6	191	AKM7154ENG	1	0
- instructions card	8	274	LT77 Gearbox Manual		
- reprogramming	1	0	AKM7155ENG	1	0
- replacements	1	0	RAWS, first approval	7	223
- retrofitting alarm & central			R380 Gearbox Manual		
locking system	5	142	AKM7225	1	0
Auctions in Japan	6	195	Rally plaques for the RV8	8	287
Badge bar for an RV8	8	250	Reimporting from Japan		
Buying an MG RV8			- to Australia	5	135
- guidance note	1	0	- Australian RAWS update	7	215
- dreams come true!	3	83	- checklist	1	39
- reimporter's checks	4	112	- options, local agent?	6	192
Cleaning an RV8 to near			- corrosion checks	3	87
conours standard	11	426	- type approval	1	39
Colours, for the RV8	7	216	- customs requirements	1	39
Concours, cleaning an RV8	11	426	- Waxoyling	3	87
Dehumidifier, Winter storage	7	237	Remote key fob – see alarm		
Disklock	6	180	transmitter above		
DVLA info on your car	11	433	Ratchet, socket set caution	9	353
DVLA info update	12	441	Repair manual MG RV8	3	71
Fire extinguishers in cars	4	110	Reimporting RV8s, auctions	6	195
Fire risk, unusual/mirror	6	190	Rover Dealer network	1	0
Gas struts, fire risk	4	114	Rover Dealer network	2	0
Hands free phone, new law	6	193	Seat belts, inertia reel unlock	9	329
Hood press studs	9	348	Screws Phillips & Posidriv	9	320

RV8 Workshop Notes

Seats, more legroom	5	139
Seats, lowering	7	233
Seats touch up	11	419
Silkaflex, foil heat shield	6	170
Speaker grilles, replacement	8	281
Speedometer	1	39
Speedometer, replacement mph dial for a reimport	11	432
Sun visor, fire risk unusual	6	190
Sun visor screws	6	166
Tachometer - redlining	7	206
Tachometer removal	9	317
Temperature gauge	7	207
Trim colour	1	0
	3	86
Trim panels removal	1	30
Trim panels, Velcro strips	7	202
Upholstery		
- leathercare tips	1	17
	11	419
- seat removal	1	30
- seat touch up	11	419
Velcro strips, trim panels	7	202
Warning light, No Charge	6	171
Water leaks legwell	9	350
Windstop, fitting	5	127
- another installation	5	143
- Classic Additions, fitting	9	328
- drawings of a windstop	9	335
- folding windstop design	9	345
- neat installation	7	205
- photos of a windstop	9	335
- windstop bracket mod	7	228

Index prepared by Victor Smith (V8 Harvest Gold 1089)