

## Index

This is a **complete Index to the whole V8 Workshop Notes series** which will enable members to look up topics and find where they have been covered in the series. The Index is regularly updated as new workshop notes are provided by members and added to the series. An **updated copy of the Index** (and the full Contents listing of the series) is maintained on the V8 Website at [www.v8register.net](http://www.v8register.net) where members can download a copy in PDF format. From time to time members may decide they want an update CD so they can obtain the additional workshop notes.

Topic	V8 Note	Vol
<b>1. ENGINE</b>		
Accelerator cable	4	1
	202	5
Air box, bolts caution	53	2
Cam followers		
- how do they work?	43	1
	73	3
- noisy	211	6
	284	8
- noisy, possible cure	261	6
	284	8
Camshaft, changing	244	6
Carburettor adapter		
assembly gasket?	333	10
Chrome nuts under bonnet	81	3
Crankcase breather pipe	171	4
Crankshaft bush	259	6
Cylinder head gasket failure	199	5
Ballast resistance ignition	30	1
Breather pipe, crankcase	171	4
Distributor, advance fault	252	7
Distributor replacement		
options	365	11
Dwell meter	240	6
Exhaust		
- corrosion tip	29	1
- twin pipes	247	7
Exhaust manifolds		
- bolts, changing	126	4
	354	11
- Coppaslip reminder	83	3
- Coppaslip reminder again	83a	3
- cracks on LH unit, causes	35	1
- cracking	95	3
- gaskets, manifold	290	8

- hot air tubes renewing	36	1
	36a	1
- hot air tubes SS units	168	4
- sequel	66	2
- sequel	67	2
- economy tip	77	3
- manifolds	3	1
	158	4
	260	7
	290	8
	354	11
- revisited	59	2
- shrouds, hot air	3	1
- stainless steel manifolds	246	6
- tubular headers	87	3
- tubular systems	87	3
Engine		
- removal	24	1
	254	7
- spacer	57	2
- stabiliser bars	260	7
- reassembly	277	8
- rebuild options	268	7
Fuel interconnection hose	71	2
Head gasket failure	199	5
Hot air tubes		
- renewing	36	1
	36a	1
- stainless steel replacement	168	4
Hydraulic tappets, see cam followers		
Ignition, electronic	379	11
Inlet manifold gasket		
- gasket	120	4
- heavy breathing	17	1
- interchangeability	18	1
Interchangeability of parts	45	1
	212	6
Lubrication	128	4
Misfire, mysterious	328	9
Mountings, engine		
- check	174	4
- packing sheet tip	TET	1
- right hand mounting	11a	1
- right way round, check	174	4
- removal, engine	11	1
- wear	260	7
Oil hose		
- cooler tails	51	2
- rubbing on chassis leg	TET	1
Oil pressure relief valve	26	1
Oil pump problems		
- Priming pump	206	5
- Problems	201	5
Overdrive		
- control valve blocked	33	1
- missing ball	170	4

- relief valve	5	1
- similarities 1800/V8 unit	32	1
	162	4
Rebuild options, engine	268	7
Removal	24	1
	254	7
Replacement V8 engines	86	3
Rocker shafts		
- cam followers	211	6
- opening up the oilways	156	4
- maintenance	23	1
	23a	1
Running on	115	4
Spark plug tester	183	5
Speedometer cable	49	1
Spigot bush	277	8
Stabiliser bar	260	7
Starting problems	240	6
Starter motor		
- alternative	5	--
	6	--
- armature replacement	356	11
- fault	166	4
- fault found and cured	376	11
- hot start problem cure	390	11
- part numbers	60	2
- removal	7	1
	21	7
	342	10
- replacement	251	7
- saving tip	143	4
- slow starter cure	390	11
- solenoid	7a	1
	353	11
Sump drain plug		
- compressible washer	8	1
- drip tip	153	4
- magnetic plug tip	99	3
Supercharging	131	4
Tappets, hydraulic – see cam followers		
Throttle cable		
- caution	4	1
- replacements	202	5
Tickover, rising in hot weather	7	262
Timing, setting	205	5
	258	7
Unleaded fuel, suitability	204	5
Vacuum advance diaphragm	34	1
Water injection	125	4
<b>2. IGNITION SYSTEM</b>		
Ballast ignition resistance systems	30	1
Battery terminal fault	376	11

Centrifugal advance	65	2
Coil, high power	379	11
Coil, hot & poor rivets	388	11
Contact breakers		
- nylon insert, threads strip	42	1
- replacement	240	6
- setting up/dwell meter	240	6
- spares	282	8
- tip 1	42	1
- tip 2	154	4
Distributor, advance fault	252	7
Distributor advance unit fault	252	6
Distributor, Lucas	317	9
Distributor, Mallory unit	316	9
Distributors for the MGBV8	282	8
Distributor replacement options	365	11
Dwell meter	240	6
Dwell adjuster	154	4
	282	8
Electronic ignition systems		
- survey	10	1
- Mobelec	9	1
- Lumentition	9	1
	282	8
- Pertronix conversion	379	11
High tension leads	65	2
Misfire, mystery	328	9
Spark plug tester	183	5
Starting gremlins	240	6
Timing		
- setting	205	5
	258	7
- strobe	205	5
- Rover 3500	258	7
Twin points	65	2
Vacuum unit, distributor	252	6
Warning light glimmer	373	11
<b>3. COOLING SYSTEM</b>		
Additional cooling fans	381	11
Antifreeze	15	1
Additives	136	4
Bonnet louvres	246	6
Coolant	15	1
Coolant filler plug, brass replacement	7	264
	7	265
	7	266
Cooling fans		
- additional cooling fans	382	11
- blades	246	6
- iolite washer	15	1
- override switch	22	1

## V8 Workshop Notes

	22a	1
	246	6
	248	7
	249	7
	288	8
	389	11
- larger fan	16a	1
- motors	271	6
	276	8
- part numbers	61	2
- replacement	271	7
Cooling improvements	246	7
	248	7
	255	7
	288	8
	293	8
	351	11
	352	11
	374	11
	375	11
	377	11
	378	11
	382	11
	388	11
	389	11
Expansion tank		
- do not overfill!	288	8
- hose, replacement	302	9
- replacement	16	1
Fans	246	7
Filler cap	15	1
Filler cap tester	15a	1
Flushing out	288	8
Heater, additional cooling!	246	6
Heater control valve		
- Change point	Chart	5
- Converting	179	5
- Overhauling the valve	189	5
Heater hose		
- BHH1038 splits, care	274	6
- note	15	1
- replacing BHH1083	386	11
Heater matrix, upgrade	256	7
Improved cooling	288	8
Otter switch	2	1
	15	1
	248	6
Overheating	248	7
	288	8
	293	8
	303	9
	374	11
	375	11
	377	11
	378	11
	388	11
Override switch for fans	246	6
	249	6

## Index to the whole series

	288	8
	293	8
Plastic plug rot		
- brass replacement	265	6
- get home tip	266	6
- plug rot	264	6
Pressure system	15	1
Radiator		
- 4 core replacement	248	7
	288	8
	293	8
	352	11
- cap	15a	1
- more cores	16a	1
	246	6
- plastic plug rot	264	6
- plug, brass replacement	265	6
- replacement	--	6
- uprated unit	256	6
Removing badges	246	6
Replacement		
- radiator	--	6
- water pump	--	6
Rubber water hoses	--	6
Steam pipe	16	1
Sykes-Pickavent cap & cooling system tester	15a	1
SPAL cooling fans	382	11
Thermostat, modification	248	7
	288	8
Thermostatic switch, Otter	2	1
	15	1
	248	8
	288	8
	293	8
	352	11
	389	11
Thermostat wrinkle	334	10
Thermostat right way up!	334	10
Water hoses	6	--
	303	9
Water hose, change point	5	--
Water pump		
- dowel holes undersize	130	4
- general	--	6
- overheating	172	4
- remove & refit	1	1
- replacement	246	6
- strip & repair	47	1
- thinner pump	377	11
- thread lubricant	1	1
Water temperature gauge, change point	--	5
<b>4. FUEL SYSTEM</b>		
Accelerator cable		
- caution	4	1
- replacements	202	5

## V8 Workshop Notes

Bendix fuel pump	236	6
Carburettors		
- adapter assembly	55	2
- adapter assembly gasket?	333	10
- balancing	163	4
- balls may drop!!	101	4
- blocked vents	46	1
- dampers, topping up	387	11
- HIF6 SUs	17	1
- flooding, possible cause	294	8
- interconnection tube	71	2
	90	3
	139	4
	196	5
	294	8
- overflow pipe, missing	196	5
- servicing	64	2
Fuel filler cap, replacement	280	8
Fuel pump		
- alternative	236	6
- dual pump conversion	380	11
- Jubilee clip caution	380	11
- lay-up concern	222	6
- relocation	235	6
	237	6
	241	6
-cause of misfire	328	9
Lay up difficulty, fuel		
- Fuel deterioration	222	6
- Fuel pump, SU	222	6
Fuel tank		
- baffle plate, filling	80	3
- corrosion treatment	31	1
- Explosafe	62	2
- protecting a new tank	76	3
- sequel	111	4
- stainless steel replacement	155	4
Fuel tank, change point	--	5
Inlet manifold		
- heavy breathing	17	1
- interchangeability	18	1
Fuel interconnection tube		
- caution/hazard	71	2
- caution again	196	5
- fire hazard	90	3
- fuel leak in engine bay	90	3
- rust prevention tip	139	4
Overflow pipe missing	196	5
Petrol		
- deterioration	222	6
	223	6
- leaded, continued availability	217	6
- lead replacement fuel	209	6
	216	6

## Index to the whole series

- unleaded	204	5
	209	5
	216	6
Petrol tank		
- baffle plate, filling	80	3
- corrosion treatment	31	1
- Explosafe	62	2
- protecting a new tank	76	3
- sequel	111	4
- stainless steel replacement	155	4
Throttle cable		
- caution	4	1
- replacements	202	5
Unleaded fuel		
- additives	209	5
- end of leaded fuel	216	5
-		
- LRP	209	5
	216	6
- opinion, Land Rover Solihull	204	5
- use in an MGBGTV8	204	5
	209	5
<b>5. CLUTCH</b>		
Bush, lubrication	259	7
Clutch release problems	222	6
Clutch pedal, heavy cure	327	9
Lay-up difficulties	222	6
Heavy clutch pedal, cure	327	9
Master cylinder		
- changing	144	4
- repair kit	151	4
Slave cylinder		
- changing	38	1
- clevis pin wear	68	2
- repair kit	151	4
- removal	124	4
- sequel	68	2
Slipping clutch		
- splines sticking	197	5
- splines corrosion	197	5
<b>6. GEARBOX</b>		
Bearings	165	4
Bellhousing, TVR	219	6
Borg-Warner T-5		
- options	218	6
	219	6
	220	6
- replacement	220	6
- speedometer	220	6
Bushes	165	4
Clutch release bearing	371	11
Costello 5 speed gearbox	219	6
Dellow Automotive box		
- Conversion kit	221	6

- Replacement option	221	6
Final drive ratio	207	5
First gear	50	1
	161	4
Gearbox lubrication	267	7
Gear selection problems	142	4
Inhibitor switch	194	5
Laygear	50	1
	52	2
	165	4
Lubrication, Hypoy 90B	182	5
Lubrication, R380	267	7
LT77 substitute	52	2
	85	3
LT77, can I fit this box?	54	2
	100	3
Noise, "ziz" from gearlever	180	5
Overdrive on third gear	368	11
Ratios	207	5
Rebuild, contemplating?	165	4
Reconditioning specialists	322	9
Replacement options	218	7
Replacement gearbox		
- Borg-Warner T-4	218	6
- Borg-Warner T-5	218	6
	219	6
- Clutch choice	219	6
- Costello 5 speed box	219	6
- Crossmember	219	6
- Dellow Autom've box	221	6
- Dellow conversion kit	221	6
- Options, replacement	218	6
- LT77 (SD1 box)	6	218
- R380	218	6
Reverse jumps out	27	1
	121	4
	279	8
R380 replacement box		
- lubrication	267	7
- replacement option	218	6
- source of supply	--	6
SD1 gearbox		
- alternative gearbox	219	6
- fitting an SD1 box	188	5
	219	6
- fitting options	229	6
Shims	165	4
Stripping & rebuild	50a	1
Synchromesh balls	165	4
<b>7. PROPSHAFT</b>		
GKN Driveline	219	6
Replacement gearbox	219	6
Universal joints	285	8
<b>8. REAR AXLE</b>		
Anti-tramp bars, fitting	369	11

"Clonk" from back axle	72	3
	285	8
Crown wheel & pinion	--	6
Cross pin		
- fault	72	3
- modification	98	3
- sequel	134	4
- sequel	135	4
Differential spares	150	4
Hoyle suspension	302	9
upgrade		
Independent rear upgrade	302	9
Interchangeability	37	1
V8/1800		
Lubrication	116	4
Modification		
- important note	98	3
- sequel	134	4
	135	4
- Syd Beer's views	159	4
- Syd Beer, reply	160	4
Options, conversions	391	11
Planet wheels		
- essential check	72	3
- modification	98	3
Propshaft UJs	285	8
Replacement CWP	--	6
Spares	150	4
	392	11
Universal joints	285	8
Upgrade kit – Hoyle Eng	302	9
	391	11
<b>9. REAR SUSPENSION</b>		
Alternative shock absorbers	246	6
Anti-roll bar, rear		
- note	133	4
	245	6
- fitting	167	4
Anti-tramp bars, fitting	369	11
Bushes, upgraded	360	11
Handling		
- improving	44	1
	167	4
- upgrade	245	6
Hoyle suspension	302	9
upgrade		
Independent rear upgrade	302	9
Link arm, rear shocker	230	6
Lowering a V8	133	4
Rear shock absorbers		
- Bilstein	246	7
- Don Hayter's notes	246	7
- Konis	246	7
- lever arm	246	7
- link arm	230	6

- replacement alternatives	246	7
- Spax	246	7
Replacement rear springs	369	11
Ride height & bumpers	239	6
Ron Hopkinson handling kit	245	6
Shock absorber, alternatives		
- alternatives	246	6
- performance	246	6
Spax experiences	366	11
Springs, retempering	133	4
<b>10. INSURANCE</b>		
Agreed value	70	2
	242	6
Classic car insurance	70	2
	242	6
Claims, county court route	132	4
Conversions - insurance	301	9
Disclosure obligations	--	6
Limited mileage policies	242	6
Mobile phone, new law	296	8
Renewals, no grace period	318	9
Reinstatement cost	242	6
Restricted mileage policies	70	2
Thatcham, insurers' requ'ts	278	8
Upgrade kit – Hoyle Eng	302	9
Valuations	114	4
	242	6
V8 Conversions insurance	301	9
<b>11. STEERING</b>		
Castor angle reduction kit	340	10
Column		
- chrome bumper	78	2
- stripping	78	2
Fire risk, horn wiring	308	9
Grease nipples		
- handbook error	6	1
- three not two	6	1
Steering column		
- bush renovation	238	6
- stripping	78	2
Steering rack		
- caution	227	6
- cracked rack mounts	338	10
- bracket on cross member	227	6
- exception note	104	4
- seized mounting bolts	91	3
- strengthening gusset	339	10
Temporary steering tip	275	7

<b>12. FRONT SUSPENSION</b>		
Anti-roll bar, front		
- uprated bar	44	1
	133	4
British Motor Heritage	245	6
Bushes, V8 metal inserts	39	1
Bushes, upgraded	360	11
Castor angle reduction	340	10
Distance tube, change point	--	5
Grease nipples		
- handbook error	6	1
- three not two nipples!	6	1
Handling improvements		
- improving	44	1
- upgrade	245	6
Hoyle suspension upgrade	302	9
Hoyle & RV8 set ups compared	393	11
King pins		
- distance tube	40	1
- replacing	146	4
- refurbishing	146	4
Lowering a V8	133	4
Moss Dynamic Suspension System	245	6
Performance Suspension System, BMHE	245	6
Ride height & bumpers	239	6
Reconditioned shockers	257	7
RV8 front suspension	245	6
RV8 kit compared with a Hoyle set up	393	11
Shock absorbers		
- remove & refit	44	1
- replacements	257	6
- reconditioned quality	257	7
Soft front suspension	286	8
Spax, telescopics		
- conversion	175	4
- telescopics	257	6
Steering rack mounts		
- cracked mounts	338	10
- strengthening gusset	339	10
Track rods ends, releasing	137	4
Upgrade kit – Hoyle Eng	302	9
<b>13. BRAKES</b>		
Anti squeal kit	6	215
Brake calliper	6	215
Brakes pulling	5	181
Brake shims	6	215
Brake servo failures		
- air valve piston leaks	228	6
- cracked vacuum piston	228	6
- failures, important notes	12	1

	228	6
- low brake fluid sensor	331	10
- LBFS detailed fitting guide	332	10
- overhaul kit	56	2
- seal failure	228	6
- servicing summary	56	2
- sequel	94	3
	113	4
- vacuum hose	12a	1
Brake squeal cure (front)	312	9
Cementite explained	335	10
Compensating lever	118	4
Discs		
- cooling	41	1
- drilled	41	1
- warn discs	181	5
Front brake callipers		
- anti-squeal kit	215	6
- overhaul	96	3
- squeal	215	6
	312	9
- upgrade	355	11
Front hose, change point	--	5
Handbrake, compensating lever	118	4
Handbrake fault, solving	383	11
Hydraulic pipe replacement	75	3
Master cylinder, change	144	4
	210	5
Front pads, replacements	335	10
Pulling brakes	181	5
Servo		
- air valve piston leak	228	6
- brake servos & systems	395	11
- cracked vacuum piston	228	6
- failures, important notes	12	1
	228	6
	341	10
- low brake fluid sensor	331	10
- overhaul kit	56	2
- replacement	228	6
- seal failure	228	6
	395	11
- servicing summary	56	2
- sequel	94	3
	113	4
- vacuum hose	12a	1
Shoes, Mintex	151	4
Silicone brake fluid	228	6
	228A	6
	228B	6
Slave cylinder		
- rear	151	4
- repair kit	151	4

### 14. ELECTRICAL EQUIPMENT

Alternator problems		
- AC Delco	18	1
	28	1
- alternative alternators	177	5
	184	5
- alternator connector block	203	5
- bolt tightening sequence	92	3
- Bosch alternative	177	5
- connector block	203	5
- Lucas alternative	74	3
	74a	3
- malfunction	28a	1
- more on alternatives	184	5
- parts breakdown	74a	3
	169	4
- problems	176	5
- pulley retaining nut	176	5
- replacement	285	8
- rectifier terminal fault	298	8
Armature, replacing on starter motor	356	11
Battery		
- alternative battery	105	4
- caution	250	6
- cold cranking current	250	6
- cold start performance	250	6
- conditioner	213	6
	346	10
- current rating	250	6
- deterioration, lay-up	222	6
- filler bottle	225	6
- fitting an 065 12V battery	364	11
- height caution	240	6
- increased battery capacity	363	11
- lifters	224	6
	225	6
- management unit	213	6
- ratings	250	7
- replacing 6v with a 12v	250	7
	329	9
	364	11
- using two 12 v in parallel	330	9
	357	11
- revival	63	2
- securing your batteries	185	5
- terminals, faulty	240	6
- terminal cracked	376	11
- "top hat" connectors	240	6
	329	9
- Varta's website	250	6
- vital check	185	5
Battery lifters		
- Snap-On Tools	224	6
- International Tool Co	224	6
Bullet connector fault	384	11

Caution, terminal clearance	240	6
Cooling fans		
- Brushes, replacement	361	11
- Fault	384	11
- Oilite washer	15	1
- override switch	22	1
	22a	1
- part numbers	61	2
Cigar lighter, replacement	127	4
Cowling, steering column	212	6
Door jamb switch	272	7
Fuel pump, problems		
- alternative pumps	236	6
- Bendix, replacement	236	6
- problems, lay up concerns	222	6
- relocation	235	6
	237	6
	241	6
- cause of misfire	328	9
Fuse box fault	336	10
Fuse box, faulty terminal	336	10
Indicators, fault	384	11
Hazard light switch fault	384	11
Headlamps upgrade		
- upgrade	324	9
- Cibie replacement units	348	10
Heated rear window switch, change point	Chart	5
Heated rear window fault	384	11
Horn fault	307	9
Horn contact repair	385	11
Horn wiring, fire risk	308	9
Lay-up difficulties		
- batteries	222	6
Lighting	326	9
history/terminology		
"Lights on" alarm	323	9
Oil temperature gauge take off, change point	5	--
Tailgate, internal light & switch	273	7
Top hat connectors		
- access panel clearance	240	6
- battery terminals	240	6
	329	9
Rear plate lights, change point	Chart	5
Rear wash/wipe installation	112	4
Replacement starter motor		
- Standard starter motor	6	--
- Nippon Denzo	Chart	6
Reverse lamp switch	194	5
Stalk switch, steering column	212	6

Starter motor		
- remove & replace	7	1
	21	1
	353	11
- relay, change point	Chart	5
- replacement	18	1
	Chart	6
- replacing armature	356	11
- solenoid	7a	1
	353	11
Sealed beam upgrade	324	9
SU fuel pump, problems	222	6
Tailgate lamp	273	6
Tow bar wiring	117	4
Thatcham immobilisers	278	8
Turn indicators fault	384	11
Water pump, electric	288	8
	293	8
Windscreen washer pump, change point	Chart	5
Windscreen wiper motor	82	3
Wiper blades		
- replacement Bosch	198	5
- replacements	198	5
Windscreen wiper box, change point	Chart	5
Wiring colour codes	397	11
Wiring faults	384	11
<b>15. WHEELS &amp; TYRES</b>		
Alloy & steel wheels		
- renovating	20	1
- rivets, airtight	20a	1
Balancing, wheel nuts tip	291	8
Cones, wheel centres	20b	1
Dunlop wheels		
- refurbishment	89	3
	195	5
- renovating	20	1
- rivets, airtight	20a	1
IMS, tyre sealant kit	247	7
Leaky V8 wheels	370	11
Nuts, chrome wheel nuts		
- conical seating slave nuts	291	8
- protecting	138	4
	291	8
- rusting, solving	283	8
- slave nuts, BHH1087	291	8
Metal labels, caution	396	11
Renovation of V8 wheels	195	5
	297	8
Replacement V8 wheels	Chart	6
Space saver wheel & tyre	344	10
Tape for leaky wheels	370	11
Tyres		
- age replacement	269	6
- aspect ratio	187	5

## V8 Workshop Notes

## Index to the whole series

- Goodyear Grand Prix	270	6
- Goodyear NCT	292	8
- Goodyear G800	270	6
- original equipment	270	6
- problems with tyres	396	11
- rolling radius	187	5
- replacements	269	6
- sizes	187	5
- space saver tyre	344	10
- supplier, recommended	292	8
Tyres, original equipment	270	7
V8 road wheels	Chart	6
Vibration cure	25	1
Wheel nuts		
- avoiding damage, V8	291	8
nuts		
- Wall Drive Socket	291	8
- conical seating nuts	291	8
Wheel, space saver	344	10

### 16. BODY

Air dam	288	8
Air intake mesh	243	6
Badge		
- BGT change	Chart	5
- doublesided tape	345	10
- original V8 Register		
badge fixing	129	4
- location, N/S badges	253	6
- small V8 Register badge		
fixing	229	6
- V8 badge location	253	7
Body care		
- bulkhead shelf refurb	394	11
- corrosion, underbody	103	4
- underbody protection	200	5
- front wings	14a	1
- rust	14	1
Body colours	Chart	6
	313	9
Bodyshell, change point	Chart	5
Bonnet		
- hinge alignment	226	6
- louvres	149	4
- broken release catch	325	9
Boot, space saver wheel	344	10
Bosch wiper blade	198	5
Bulkhead shelf refurb	394	11
Bumpers, ride height	239	6
Bumper armatures,		
change point	Chart	5
C post		
- liner clip	208	5
- trim change point	Chart	5
Club badge		
- fitting	193	5
- plinth	193	5
Damp garages		

- desk top fan moves air	200	5
- Protection against damp	200	5
- Damp during winter	200a	5
Door jamb switch	272	7
Door mirror, change	Chart	5
points		
Drain tubes, cleaning	164	4
Front bumper, ride height	239	6
Filler cap, replacement	280	8
Front wheel arch panel	13	1
Front wings		
- fitting new wings	84	3
- remove & refit	15	1
	48	1
Hinge alingnm't, bonnet	226	6
Hood		
- cleaning coffee stains	232	6
- refurbishment	233	6
- rear window, scratches	233	6
- Renovo products	233	6
- soft top proofing	233	6
Inner door seal screws	263	7
Inner wing, change point	Chart	5
Intake mesh, fitting	243	6
Locks, rubber washers	106	4
Louvres in the bonnet	149	4
Number plates,	372	11
replacment		
Petrol tank, rust check	14a	1
Protection against damp	200	5
Rear plastic window,	232	6
cleaning	233	6
Renovo product range	233	6
Rust		
- body care	14	1
	15	1
- prevention tip	58	2
Rear bumper, ride height	239	6
Rear fog lights, fitting	110	4
Rear was/wipe installation	112	4
Rubber lock washers	106	4
Sebring panels	239	6
Splashguards, front wheel		
arch	13	1
Spoiler, front		
- air dam	288	8
- fitting	44	1
	157	4
- LE spoiler	109	4
- sequel	119	4
Spoiler, rear (LE spoiler)	109	4
Tailgate, internal light &		
switch	273	7
"Ted's knob", tip	164	4
Trim colours	Chart	6
V8 badges, theft/replacing	TET	1
Waxoyl		
- treatment	47	4

## V8 Workshop Notes

	147	4
	148	4
Webasto blow out	287	8
Webasto refurbishment	358	11
Wind noise, curing	180	5
Windscreen		
- inserts, chrome	173	4
- replacement	173	4
- replacement service	315	9
Windscreen removal	349	10
Windstop	321	9
Wiper blades		
- Bosch replacement	198	5
- replacement	198	5
<b>17. SERVICE TOOLS</b>		
Adapter for 1800/V8	192	5
Battery filler bottle	225	6
Battery lifter		
- Snap-On Tools	224	6
- International Tools Co	225	6
Churchill tools for V8	192	5
Clutch centraliser	102	5
Crankshaft rear oil sealer protection sleeve	192	5
Engine sling	192	5
Exhaust valve guide		
- remover	192	5
- replacer	192	5
Gudgeon pin remover	192	5
Hydraulic ramp - Auten	304	9
Socket spanner	192	5
Valve guide distance piece	192	5
Valve spring compressor	192	5
<b>18. VARIOUS</b>		
Anti-theft device		
- device	19	1
- secret switch	289	8
Adhesives for the car	108	4
Badge		
- mounting	129	4
- V8 Register badge	229	6
Battery lifter or carrier	224	6
	225	6
Bayford Thrust	217	6
Buying guide	310	9
	311	9
	314	9
Car Number identity	Diag	6
Dehumidifier, Winter storage	346	10
Dwell meter	240	6
Fire extinguishers	186	5
	231	6
France, new speed laws	234	6
France, registering an		

## Index to the whole series

MGBGTV8	295	8
Germany		
- increased V8 interest	305	9
- historic classification	305	9
Handling		
- improvements	44	1
	167	4
- upgrade	245	6
- Upgrade Hoyle kits	302	9
Interchangeability of parts	45	1
	212	6
Lay-up an MGBGTV8	122	4
	222	6
	346	10
Maintenance locations	Diag	6
Mobile phone, new UK law	296	8
Le Mans		
- circuit map	214	6
- planning a trip	214	6
- town map	214	6
Petrol		
- Leaded fuel availability	217	6
- Leaded fuel supplier	217	6
- Lead replacement fuel	216	6
- Unleaded fuel, advice	216	6
Petrol deterioration during a lay-up	222	6
Production, V8 at Abingdon	300	9
Radar detectors	214	6
- general	214	6
- no detectors in France!	234	6
- Valentine One	299	8
Registering an MGBGTV8 in France	295	8
	308	9
Spares when touring abroad	382	11
Speed laws in France	234	6
Steering wheel locks		
- Disklock	289	8
- general	289	8
- Yellow Autolock	289	8
Thatcham immobilisers	278	8
Torch for toolkit	223	6
Underbonnet sound deadening	123	4
V8 front suspension	245	6
V8 Register badge	229	6
V8 Roadster conversion	319	7
V8 grille badge & plinth	193	5
VIN identification	Chart	6
Windscreen reoval	349	10
Wind noise, cures	180	5
Windstop	321	9
<b>19. INTERIOR</b>		

## V8 Workshop Notes

## Index to the whole series

---

Anti-theft		
- Eagle Claw	289	8
- device	19	1
- Dicklock	289	8
- secret switch	289	8
- Yellow Autolock	289	8
Air-conditioning		
background	140	4
Children in an MGBGTV8		
- head restraints	191	5
- seat harness	191	5
Courtesy lamp, rear	151	4
Dashboard, walnut kits	362	11
Disklock	289	8
Dog guard, fitting	79	3
Door seal retainer strip	263	6
Door waist rail capping,		
change points	Chart	5
Eagle Claw, steering lock	289	8
Fire extinguishers		
- detailed note	231	6
- locating	186	5
- types	186	5
	231	6
Fire risk, horn wiring	308	9
Gaiter, gear lever	337	10
Gear lever gaiter, leather	337	10
Gaiter tray, walnut	362	11
Handbrake, change point	Chart	5
Hands free kits, mobile		
phone	296	8
Head restraints, children	191	5
Head restraint rollers,		
change point	Chart	5
Heater control cable	Chart	5
Heater control valve		
- adapting an 1800 unit		
for a V8	179	5
- overhauling	189	5
Heater, uprated unit	10	343
Horn fault	307	9
"Lights on" alarm	323	9
Mobile phone hands free		
kits	296	8
Platform, rear	178	5
modification		
Radio, iPod ICE		
modification	347	10
Rear courtesy lamp	151	4
Rear luggage panel	178	5
Rear seat squab, change		
point	Chart	5
Seats sagging, reviving	190	5
Speedometer		
- cable	49	1
- repair, specialist	367	11
- sequel	102	4
Sun visor, change point	Chart	5

---

---

Temperature gauge		
- tip	141	4
- relocating	281	8
Trim colours	313	9
Walnut trim, fitting kits	362	11
Windblock design	306	9
Yellow Autolock	289	8
Voltmeter, adding	281	8

---

Note: The MGBGTV8 Buying Guide (Note 310 in Volume 9) covers all aspects of the model. The Index is maintained by Victor Smith (Harvest Gold 1089) and covers the whole of the V8 Workshop Notes series.