

Index to the whole series

This index covers all volumes of the RV8 Workshop Notes series and will be updated from time to time as the series develops. An updated Index is maintained on the V8 Website at www.v8register.net which holders of RV8 Workshop Notes can download to maintain their copies of the Index.

Topic	Vol	RV8 Note
1. ENGINE		
Advance & retard pipe	1	39
	2	60
	8	258
Advance retard unit	4	120
Air filters	1	0
	1	41
	3	91
	3	99
	4	119
	6	175
Air flow meter	1	4
Air intake sensor	5	130
Bosch starter motor	7	238
Crankshaft rear oil seal	3	71
Distributor clamp nut wrench	7	229
ECU, location, removal & refit	5	144
ECU, rechipping	7	226
	7	230
Engine management		
- Data link connector	4	115
- DLC cover strip	4	115
- Diagnostic databook	4	122
- Diagnostic leads	4	118
- Diagnostic tests	4	118
	4	123
- Rover Testbook or T4	4	118
- Test equipment	4	118
Engine performance		
- EPROMS (chips)	1	21
- upgrade	1	21
- RPI Engineering	1	21
Exhaust system		
- catalytic overheat sensors	3	100
	4	101
- catalytic converter	3	99
- clamps	3	97
- down pipes	3	97
- general	1	16
- hangers, replacing	5	134
- mounting hooks	1	25
- manifolds nuts loose	5	138
- manifold LHS noise	5	138
- mounting brackets	1	25

Index to the whole series

- corrosion	1	25
- rattle	1	36
- removal	8	292
Oil filter, replacement	8	284
Flame trap hoses		
- clamps	1	4
- general	1	5
Flywheel cover plate	3	71
Heater hoses	1	5
Heater box corrosion	1	25
Hose clamps		
- general	1	4
- Norma	1	4
- Oetika	1	4
Hot wire fuel injection system	5	140
Idle		
- engine erratic	5	140
- running problems	6	188
- spasmodic idle problems	6	186
Lucas Hot Wire system	5	140
Inlet manifold gasket		
- corrosion	1	25
- general	1	26
Misfire, solving	5	130
Mountings, engine		
- adjusting the mounts	8	255
- mounts	3	71
Oil pump		
- cover & washers	3	88
- hoses (replacements)	3	88
Optimax chip, improvements	7	200
	8	251
Part number change points	1	24
PCV valve, check it is clear	8	249
Pipe clips	1	4
Plenum chamber hose	1	4
Rear oil seal – crankshaft	3	71
Rocker cover 3.9 badge		
- badge	4	105
- breather element n/s	6	166
Sensor, air intake	5	130
Starter, overheating	5	146
Starter motor	7	238
Starting problems	6	188
Stepper motor, cleaning	8	283
Sump gasket, replacement	8	284
Throttle pedal	1	19
Timing adjustments with reimported RV8s	7	200
Torque wrench settings	2	51
Unichip connector problems	7	201
Water pump overhaul	3	99
Water pump replacement	1	3
	3	91
Water pump & air-con drive belts	3	90
Under bonnet checks	1	0

RV8 Workshop Notes

2. IGNITION SYSTEM

Distributor clamp nut wrench	7	229
Ignition key replacement	1	0
	8	296
Optimax chip, improvements	7	200
	8	251
Part number change points	1	24
Starting gremlins	2	66
Timing adjustments with reimported RV8s	7	200
Torque wrench settings	2	51
Unichip connector problems	7	201

3. COOLING SYSTEM

Blanking panel, radiator	4	103
	6	178
Connecting pipe, corrosion	8	299
Cooling hose layout	8	295
Expansion tank		
- plug	1	3
- refilling reminder	1	3
- corrosion	1	25
- filler plug spanner	1	37
- new overflow tank	6	170
Hoses, layout	6	185
	8	295
Part number change points	1	24
Plug, plastic/replacing	5	150
	5	158
Plug, get you home tip	5	159
Radiator cooling fan switch		
	2	69
Radiator hoses	1	4
	4	105
Radiator hoses, steel connecting pipe corrosion	8	299
Radiator hoses, replacements	6	185
	8	295
Radiator blanking panel	4	103
	6	178
Radiator shroud stickers	6	181
Radiator, upgraded	6	170
Torque wrench settings	2	51
Water pump		
- feed & return	1	4
- hose	1	5
- replacement	1	3

4. FUEL SYSTEM

ECU location, removal & refit	5	144
Electronic fuel ignition		
- throttle potentiometer	1	45

Index to the whole series

- injectors	1	45
- air flow meter	1	45
- air valve stepper	1	45
Engine management	4	115
	4	118
	4	122
Fuel cut off switch		
- cut off switch	2	66
- starting difficulty	7	219
Fuel filter replacement	3	92
Fuel pump		
- general	1	29
- noisy	1	43
- resistor	1	43
- fuel pump	1	45
- replacement (Bosch)	3	92
Fuel system		
- hose clamps & clips	1	4
- Oetika clamps	1	4
- Oetika clamps	1	7
- filters & hoses	1	4
- non evaporative loss system	1	4
- fuel filter	1	23
- filter replacement	1	29
Gauge not reading correctly	3	92
Hot wire fuel injection system	8	270
Lucas hot wire system	5	140
Part number change points	5	140
	1	24
Petrol tank		
- filler pipe	1	4
- filler pipe	1	7
- filler pipe restrictor	1	39
- general	1	7
- hoses	1	4
- Oetika clamps	1	7
- removal	1	23
- vent pipes	1	7
Pipes, safety check	8	285
Plenum chamber plug	4	105
Starter gremlin – fuel cut off switch	2	66
Throttle – see engine management systems	4	123
Torque wrench settings	2	51
5. CLUTCH		
Clutch master cylinder		
- cap	1	14
- repair kit	1	6
	8	269
- replacement	1	6
- new part number	1	50
- replacement	1	50
- vital part number	1	6
Clutch slave cylinder	1	6
	3	71
Clutch slave repairs	6	197

RV8 Workshop Notes

Part number change points	1	24
Repair kits. Master/slave	8	269
Torque wrench settings	2	51
6. GEARBOX		
Clutch assembly	3	71
Gearbox lubrication, R380	6	163
Gearbox cross member	2	52
	3	71
Gearbox mountings	2	52
	3	71
Gearbox remote	3	71
Gearbox removal	3	71
Gearknob		
- cleaning	1	18
- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	11	256
Gear lever grommet	4	105
Input shaft	3	71
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points	1	24
R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
- lubrication	6	163
- synthetic oils experience	8	264
Torque wrench settings	2	51
Towing caution	8	252
7. PROPSHAFT		
Part number change points	1	24
Torque wrench settings	2	51
8. REAR AXLE		
CWP, new supplies	5	156
Limited slip differential	3	84
Noise from back axle	5	155
Part number change points	1	24
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156
Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264
Torque wrench settings	2	51
9. REAR SUSPENSION		

Index to the whole series

Hoyle suspension upgrade	7	208
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Part number change points	1	24
Rear wheel bearings	1	40
Recall notice	8	244
Spax Krypton Gas shocks	8	278
Replacement shockers	8	278
Shock absorber, adjustments	6	174
	7	214
Shockers, adjustment guide		
Suspension upgrade kit	7	208
Torque wrench settings	2	51
10. INSURANCE		
Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168
11. STEERING		
Ball joints		
- lower	6	166
- upper	6	166
Part number change points	1	24
Castor reduction		
- details of the B&G kit	7	232
- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266
Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166
12. FRONT SUSPENSION		
Ball joints, steering		
- lower	6	166
- upper	6	166

RV8 Workshop Notes

Bump stop replacement	8	254
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points	1	24
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99
- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51
Track rod end	6	166
13. BRAKES		
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
Brake fluid choice	8	294
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6
- replacement	1	6
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291

Index to the whole series

Hydraulic hoses	1	6
Part number change points		
	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket		
	6	166
Servos and brake systems	8	293
Silicone brake fluid	8	294
Torque wrench settings	2	51
14. ELECTRICAL EQUIPMENT		
Aerial		
- replacement	1	11
Air conditioning		
- conditioned air vents	6	189
- corrosion on fans	6	173
- service	1	44
- more legroom for the passenger	4	124
- removal of the a/c system?	6	184
Alarm transmitter		
- caution	1	0
- renew batteries	1	0
- replacement	1	0
- reprogramming	1	0
	8	260
Alternator		
- exchange	6	163
- No charge warning	6	171
- replacement	1	48
- no charge light stays on	8	290
Battery		
- condition device	2	56
- conditioner	7	237
- filler bottle	3	78
- fixings, missing	5	134
- increased capacity batteries	8	257
- lifter/carrier	3	73
- Snap-On tools lifter	3	73
- Another source, lifter	3	78
Conditioned air vents	6	189
FM radio frequency converter	3	76
Fog lights		
- fog lights	1	39
- replacement sources	6	199
Footwell lights	6	165
Fuel pump resistor	1	43
Front indicator lamp	5	157
corrosion	6	163

RV8 Workshop Notes

Fuse box & fuses	5	148
Fuel gauge not reading correctly	8	270
Headlamp units		
- corrosion	1	25
- cowl, removal	6	167
- replacement (Bosch)	1	1
- replacement	2	65
- retainers	6	167
Indicators, front		
- changing amber to clear lenses	6	177
	8	253
- connector terminal corrosion	5	157
Immobiliser	4	117
Immobiliser – ECU terminal	6	191
Immobiliser - synchronisation	7	234
Instruments in fascia	1	24
Insulation cracking	4	110
Lens, indicator – changing from amber to clear		
	6	176
No charge light stays on	8	290
Part number change point	1	24
Petrol tank sender unit	4	105
Radio		
- conversion (Japan)	1	39
- frequency converter	3	76
Relay No 1, replacing	6	165
Reverse lamp lucars	3	71
Reversing light switch	7	212
Rear light cluster	4	105
Saving electrical parts	3	99
Speaker grilles, replacement	8	281
Starter motor		
- Bosch starter motor	7	238
- overheating	5	146
- terminals corrosion	1	25
- terminals repair	1	28
Torque wrench settings	2	51
Warning light, No Charge		
	6	171
Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105

15. WHEELS & TYRES

Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points		
	1	24
Road wheels		
- centre caps	1	10
- changed castings	1	10
- corrosion	1	15

Index to the whole series

	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- wheel centre badges	1	15
	8	276
- wheel lock nuts, wear	3	81
Sealants	8	298
Space saver tyres, check	5	133
	8	297
Studs, dummy need care	8	261
Torque wrench settings	2	51
Tired tyres, stored RV8s	5	132
Tyres		
- replacements	5	160
- replacements, suppliers	6	182
- more on replacements	6	179
- update on replacement tyres	6	198
- pressures	6	174
- pressures again	6	196
- sealants for tyres	8	298
- suppliers, recommended	6	182
Wheel nuts, locking	4	121

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Bonnet alignment		
- alignment	3	80
- release cable	6	166
- stay, clip	6	166
Boot		
- gas struts	8	259
- general	1	23
- release mechanism	5	149
- tool stowage mould	1	23
- warning (closing)	1	0
Club badge mounting	2	58
	3	95
Colours (paintwork)	1	0
	2	0
Corrosion checks	1	25
	1	42
	3	87
Door glass		
- removal	2	68
- refitting	2	68
- part numbers	2	68
Door handles	5	151
Door mirrors	1	2
- rubber covers	3	74
- knob handles	3	74
- mirror glass	3	74
	6	166
Door seal, inner	5	153

RV8 Workshop Notes

Exterior checks	1	0
Fire risk, unusual/visor mirror	6	190
Gas struts, caution	4	114
	8	259
Header rail corrosion	1	25
Headlamp cowl, remove	6	167
Hood		
- catches, safety check	8	286
- cleaning/refurb	4	107
- fitting	1	0
- operation	1	0
- rattle	1	20
- rear surround	1	25
- Renovo products	4	113
- replacement, caution	8	262
- replacement hoods, more	8	268
- sheared pivot repair	1	47
- stiff operation	1	46
Hood backlight		
- avoiding crease	4	108
- cat deterrent!	2	53
- replacement	2	53
- zip use & repair	4	109
Hood rear window see backlight above		
Indicator lenses, changing to clear	6	176
Inner door seal retainer strip	5	153
Knocking noise, underbody	6	187
Legroom, increasing	5	139
Lens, indicator – changing from amber to clear		
	6	176
	8	253
Noise from engine on LHS		
	5	138
Nose cone, removal	7	203
Number plates		
- doublesided tape	7	236
- rear fixings	1	39
- removing Japan spec plate	7	217
- replacement number plate	8	279
Paint codes	4	125
	8	300
Part number change points		
	1	24
Retainer strip, inner door seal	5	153
Rear window, hood		
See hood backlight above		
Seats, unusual fire risk!	6	190
Seats, more legroom	5	139
Seats, lowering	7	233
Side skirt removal	5	145
Sills		
- mounting brackets	1	25
- tread plates	1	27

Index to the whole series

	4	105
Tonneau covers		
- full	2	55
- half	2	55
Torque wrench settings	2	51
Underbody knocks	6	187
Water leaks	1	22
	2	62
	5	136
Waxoyling reimports	3	87
Wheel arch flares	2	70
Windscreen		
- carbon fibre replacement	8	246
- checks	1	0
- frame corrosion	1	25
- leaks, water ingress	3	93
	5	136
- refitting	1	22
- replacement surround	8	246
- removal	1	22
- rust, pictures	7	225
- sealing rubbers	1	22
- VIN number etching	3	89
	8	273
Windscreen glass		
- removal	1	22
- refitting	1	22
- replacement supply	7	240
Windstop, fitting	5	127
Windstop	7	224
Windstop bracket mod	7	228
Wings		
- Rover badges (Japan)	1	39
Wiper bezel	5	151
Wiper blades adjustment	1	13

17. SERVICE TOOLS

Auten hydraulic car lift	7	209
Britool equipment	3	71
Draper tool 176	1	12
	1	23
Draper tool T40	1	12
Filler plug spanner	1	37
Hydraulic car lift or ramp	7	209
Lift, hydraulic	7	209
Tool storage moulding	1	23
RV8 toolkit		
- checklist of contents	1	9
- general	1	39
- replacements	2	63
- new toolkit supplies	4	106
- torch replacement	3	72
Sump plug spanner	1	37
	4	106
Zyliss Strong Boy	1	14

18. VARIOUS

Acquiring an MG RV8	1	0
Alarm transmitter		
- ECU, vulnerability	6	191

RV8 Workshop Notes

- instructions card	8	274
- reprogramming	1	0
- replacements	1	0
- retrofitting alarm & central locking system	5	142
Auctions in Japan	6	195
Badge bar for an RV8	8	250
Buying an MG RV8		
- guidance note	1	0
- dreams come true!	3	83
- reimporter's checks	4	112
Colours, for the RV8	7	216
Dehumidifier, Winter storage	7	237
Disklock	6	180
Fire extinguishers in cars	4	110
Fire risk, unusual/mirror	6	190
Gas struts, fire risk	4	114
Hands free phone, new law	6	193
How many RV8s were made?	7	216
Importing to Australia	5	135
Japan reimports of RV8s		
- car documents	1	39
- checklist	1	0
- checks & tips	1	39
- ownership checks	4	112
- Modifications	4	120
Land Transport Safety Authority, New Zealand	1	33
Le Mans visit - tips	1	49
Maintenance locations	1	0
Mobile phone, new law	6	193
Old parts, hang on to them		
	1	33
	3	91
Plaques, rally	8	287
Publications:		
Owners Handbook		
AKM7144	1	0
Owners Service Record		
AKM7150	1	0
Owners Info Portfolio		
AKM7158	1	0
Repair Manual		
AKM7153	1	0
	4	118
Engine Manual		
AKM7154ENG	1	0
LT77 Gearbox Manual		
AKM7155ENG	1	0
RAWS, first approval	7	223
R380 Gearbox Manual		
AKM7225	1	0
Rally plaques for the RV8	8	287
Reimporting from Japan		
- to Australia	5	135
- Australian RAWS update	7	215
- checklist	1	39
- options, local agent?	6	192

Index to the whole series

- corrosion checks	3	87
- type approval	1	39
- customs requirements	1	39
- Waxoyling	3	87
Remote key fob – see alarm transmitter above		
Repair manual MG RV8	3	71
Reimporting RV8s, auctions	6	195
Rover Dealer network	1	0
Rover Dealer network	2	0
Servicing	1	39
	6	172
Spare parts	1	33
	3	82
Spares, essential for touring abroad	8	288
Stoplock	6	180
Steering locks	6	180
Stolen cars (Japan)	4	112
Storing an RV8 over Winter	7	237
Technical Info CD, RV8	6	-
Toolkits for MG RV8	1	0
	1	9
	2	63
	3	72
	4	106
Toolkit, spare wheel moulding	6	166
Torque wrench settings	2	51
Under bonnet stickers	1	39
VIN identification	1	0
	5	147
Windstop	7	224
Yellow Autolock	6	180

19. INTERIOR & INSTRUMENTS

Alarm ECU, vulnerability	6	191
Boot bulkhead clips	9	301
Bulkhead clips, boot	9	301
Carpets, replacements	8	267
source		
Checks before purchase	1	0
Clipstone leather cleaner	1	17
Clipstone conditioner	1	18
Cockpit, too hot	5	126
Cockpit heat, solved	6	170
Courtesy light clips	5	141
Dashboard		
- creak, solving	8	266
- fascia removal	1	12
	1	22
- radio fascia panel	3	79
- refurbishing laquer	8	277
Door cappings		
- cracking	5	154
- refurbishment	5	154
	8	277
- relacquering trim	8	282
Door pockets modification	8	289

RV8 Workshop Notes

Driver headroom tip	1	35
Emergency flares	7	222
Fascia Shellac coating	2	57
Fascia instruments	2	57
Footwell lights	6	165
	6	166
Fuse box & fuses	5	148
Gearbox knob		
- cleaning	1	18
- replacement	1	18
- renovation	3	77
Glovebox	1	12
Glovebox, switch	6	166
Glovebox lid, refurbishing	8	277
laquer		
Hands free mobile kits	6	193
Heater control cable	5	128
	7	204
	8	247
	8	248
Hot RV8 cockpit	5	126
	6	170
	7	204
	7	227
	8	247
	8	248
Ignition key, replacement	8	296
Ignition warning light glows	8	280
Immobiliser	4	117
Immobiliser – ECU terminal	6	191
Immobiliser,	7	234
synchronisation		
Instruments		
- misting difficulties	2	57
- oil pressure sensor	2	57
- fascia switch bulbs	3	85
Mobile phone, hands free	6	193
kits		
Radio		
- FM waveband converter	2	76
- FM band expander	7	220
- iPod ICE option	7	239
- replacement, reimport	7	221
Seats, more legroom	5	139
Seats, lowering	7	233
Silkaflex, foil heat shield	6	170
Speaker grilles,		
replacement	8	281
Speedometer	1	39
Sun visor, fire risk unusual	6	190
Sun visor screws	6	166
Tachometer - redlining	7	206
Temperature gauge	7	207
Trim colour	1	0
	3	86
Trim panels removal	1	30
Trim panels, Velcro strips	7	202
Upholstery		
- leathercare tips	1	17
- seat removal	1	30

Index to the whole series

Velcro strips, trim panels	7	202
Warning light, No Charge		
	6	171
Windstop, fitting	5	127
- another installation	5	143
- windstop bracket mod	7	228
- neat installation	7	205

Index prepared by Victor Smith (V8 Harvest Gold 1089)