

RV8 Workshop Notes

Mass airflow sensor	10	374	Distributor, timing	11	422
Misfire, solving	5	130		11	423
	10	375	Ignition key replacement	1	0
Mountings, engine				8	296
- adjusting the mounts	8	255	Ignition module, remote	10	369
- mounts	3	71	Ignition module, overheating	12	445
- mounts orientation	9	324	Magnicor plug leads	11	411
Oil filter magnetic wrap	11	408	Optimax chip, improvements	7	200
Oil pressure switch	9	327		8	251
Oil pump				10	360
- cover & washers	3	88	Part number change points	1	24
- hoses (replacements)	3	88		2	66
Optimax chip, improvements	7	200	Starting gremlins	7	200
	8	251	Timing adjustments with	11	422
	10	360	reimported RV8s		
	11	402			
	11	403	Timing correction in the RV8		
	11	410	Repair Manual AKM7144ENG	11	435
Part number change points	1	24	Torque wrench settings	2	51
PCV valve, check it is clear	8	249	Unichip connector problems	7	201
Pipe clips	1	4			
Plenum chamber hose	1	4	3. COOLING SYSTEM		
Radiator cover, replacement	10	358	Antifreeze concerns	9	322
Ratchet, socket set caution	9	353	Blanking panel, radiator	4	103
Rear oil seal – crankshaft	3	71		6	178
Remote ignition module	10	369	Coolant bleed insert	11	409
Road speed sensor	11	440	Coolant loss, cause	10	390
Rocker cover 3.9 badge			Coolant, refilling system	10	357
- badge	4	105	Coolant refilling, bleed insert	11	409
- breather element n/s	6	166	Coolant, waterless concerns	12	446
Sensor, air intake	5	130	Connecting pipe, corrosion	8	299
Starter, overheating	5	146	Cooling fan modification	10	370
Starter motor	7	238	Cooling fan override switch	10	373
Starting problems	6	188	Cooling hose layout	8	295
	11	437	Cooling hose kit, identification	9	338
	11	438	Expansion tank		
Stepper motor, cleaning	8	283	- crack in the neck of the tank	390	10
Stud, broken - removal	12	442	- plug	1	10
Sump gasket, replacement	8	284	- refilling reminder	1	3
Sump gasket , caution	9	339	- corrosion	1	25
Sump gasket modification	11	420	- filler plug spanner	1	37
Throttle pedal	1	19	- new overflow tank	6	170
Timing adjustments with			- where does the coolant go?	9	347
reimported RV8s	7	200	Fan, cooling fan modification	10	370
Torque wrench settings	2	51	Heater rail modification	9	349
Unichip connector problems	7	201	Hose, heavy indentation	9	349
Water pump overhaul	3	99	Hoses, layout	6	185
Water pump replacement	1	3		8	295
	3	91	Hoses, replacements	9	338
Water pump & air-con drive			Part number change points	1	24
belts	3	90		5	150
Water pump overhaul	9	314	Plug, plastic/replacing	5	158
Under bonnet checks	1	0		5	159
			Plug, get you home tip	5	159
2. IGNITION SYSTEM			Pressure cap replacement	10	367
Cruise control, retrofit	9	341	Radiator coolant loss	9	347
Distributor clamp nut wrench	7	229	Radiator cooling fan switch	2	69

RV8 Workshop Notes

Radiator hoses	1	4		1	23
	4	105	- fuel filter	1	29
	9	349	- filter replacement	3	92
Radiator hoses, steel			Fuel tank corrosion	9	326
connecting pipe corrosion	8	299	Gauge not reading correctly	8	270
Radiator cover replacement	10	358	Hot wire fuel injection system		
Radiator hose, bleed insert	11	409		5	140
	11	434	Lucas hot wire system	5	140
Radiator hoses, replacements			Part number change points		
	6	185		1	24
	8	295	Petrol tank		
	9	338	- filler pipe	1	4
Radiator blanking panel	4	103	- filler pipe	1	7
	6	178	- filler pipe restrictor	1	39
Radiator pressure cap	10	367	- general	1	7
Radiator shroud stickers	6	181	- hoses	1	4
Radiator, refilling	10	357	- Oetika clamps	1	7
Radiator top hose self purging	11	434	- removal	1	23
Radiator, upgraded	6	170	- vent pipes	1	7
Thermostat – check it has a vent	11	415	Pipes, safety check	8	285
Torque wrench settings	2	51	Plenum chamber plug	4	105
Water pump			Starter gremlin – fuel cut off switch	2	66
- feed & return	1	4	Throttle – see engine management systems	4	123
- hose	1	5	Torque wrench settings	2	51
- overhaul	9	314			
- replacement	1	3	5. CLUTCH		
Waterless coolant concerns	12	446	Clutch master cylinder		
			- cap	1	14
4. FUEL SYSTEM			- repair kit	1	6
Bosch injectors	11	411		8	269
Cruise control, retrofit	9	341	- replacement	1	6
ECU location, removal & refit	5	144	- new part number	1	50
Electronic fuel ignition			- replacement	1	50
- throttle potentiometer	1	45	- vital part number	1	6
- injectors	1	45	Clutch slave cylinder	1	6
- air flow meter	1	45		3	71
- air valve stepper	1	45	Clutch pedal return spring	10	361
Engine management	4	115		10	361
	4	118	Clutch slave repairs	6	197
	4	122	Part number change points		
Fuel cut off switch				1	24
- cut off switch	2	66	Repair kits. Master/slave	8	269
- starting difficulty	7	219	Torque wrench settings	2	51
Fuel filter blocked, check	9	326			
Fuel filter replacement	3	92	6. GEARBOX		
Fuel pump			Bushes, rubber UKC854	10	381
- general	1	29	Clutch assembly	3	71
- noisy	1	43	Crunching gears, solving	10	381
- resistor	1	43	Gearbox lubrication, R380		
- fuel pump	1	45		6	163
- replacement (Bosch)	3	92	Gearbox cross member	2	52
Fuel system				3	71
- hose clamps & clips	1	4	Gearbox mountings	2	52
- Oetika clamps	1	4		3	71
- Oetika clamps	1	7	Gearbox remote	3	71
- filters & hoses	1	4	Gearbox remote, grease	10	384
- non evaporative loss system	1	4			

RV8 Workshop Notes

Gearbox removal	3	71
Gearbox, LT77S or R380?	11	404
Gearknob		
- cleaning	1	18
- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	8	256
Gear lever gaiter replacement	9	333
Gear lever greasing	10	384
Gear lever grommet	4	105
Gear lever remote moving	10	381
Input shaft	3	71
Gearshift pattern LT77S/R380	11	404
LT77 gearbox		
- greasing lever & remote	10	384
- rubber bushes rotting	10	381
- lubricant	10	382
- repairing dust cap bracket	11	405
Notchy gearchange cures	10	382
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points		
	1	24
R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
- greasing lever & remote	10	384
- lubrication	6	163
	10	382
- repairing dust cap bracket	11	405
- synthetic oils experience	8	264
Rubber bushes UKC854	10	381
Torque wrench settings	2	51
Towing caution	8	252
Which gearbox do I have?	11	404

7. PROPSHAFT

Part number change points	1	24
Torque wrench settings	2	51

8. REAR AXLE

Breather, plastic replacement	11	413
Breather, thread compatibility	11	418
CWP, new supplies	5	156
Limited slip differential	3	84
Noise from back axle	5	155
Part number change points	1	24
Quaife, differences with an LSD	10	388
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156

Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264
Torque wrench settings	2	51

9. REAR SUSPENSION

Hoyle suspension upgrade	7	208
Hoyle – what's it like?	9	310
Hoyle, installation notes	9	311
Hoyle, setting up	10	363
Hoyle, Spax settings	10	364
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Modifications - caution	9	312
Part number change points		
	1	24
Rear spring shackle	10	383
Rear wheel bearings	1	40
Recall notice	8	244
Shackle, rear spring caution	10	383
Spax Krypton Gas shocks	8	278
Spax replacement shockers	8	278
Spax settings	10	364
Replacement shockers	8	278
Shock absorber, adjustments	6	174
Shockers, adjustment guide	7	214
Suspension upgrade kit	7	208
Torque wrench settings	2	51

10. INSURANCE

Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168

11. STEERING

Ball joints		
- lower	6	166
- upper	6	166
Part number change points		
	1	24
Castor reduction		
- details of the B&G kit	7	232
- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266

RV8 Workshop Notes

Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235
PAS option review	9	354
EZ EPAS Swiss approvals	9	355
Steering column, collapsible	11	430
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166

12. FRONT SUSPENSION

Ball joints, steering		
- lower	6	166
- upper	6	166
Bump stop replacement	8	254
Bush replacement in AR bar eye	10	385
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
- further caution	9	312
Drop links, checks	11	410
Drop links, replacement parts	11	412
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points	1	24
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99
- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spax, replacement shockers	8	278
Spax settings	10	364
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51

Track rod end	6	166
---------------	---	-----

13. BRAKES

Brakes, system & adjustments	9	330
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
- refurbishing	10	359
- replacement yellow tag	10	379
Brake fluid choice	8	294
Brake pedal return spring	10	361
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6
- replacement	1	6
Discs, caution for eBay adverts for RV8 discs	9	305
Front brake discs, caution	9	305
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291
Hydraulic hoses	1	6
Part number change points	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket	6	166
Return spring replacement	10	361
Servos and brake systems	8	293
Silicone brake fluid	8	294
Torque wrench settings	2	51

14. ELECTRICAL EQUIPMENT

Aerial		
- replacement	1	11
Air conditioning		

RV8 Workshop Notes

- actuator	11	436	Fuel pump resistor	1	43
- aircon vents improved	12	450	Front indicator lamp corrosion	5	157
- conditioned air vents	6	189		6	163
- corrosion on fans	6	173	Fuse box & fuses	5	148
	10	376	Fuel gauge not reading correctly	8	270
- flow, aircon outlet extended	12	450	Headlamp units		
- heater cut-off flap vacuum actuator	11	436	- conversion to LHD	9	308
- service	1	44		9	313
	10	393	- corrosion	1	25
- more passenger legroom	4	124	- cowl, removal	6	167
- preventative maintenance	10	376	- cowl removal & replacement	11	417
- recharging an aircon system	10	378	- replacement (Bosch)	1	1
	10	393	- replacement	2	65
- removal of the a/c system?	6	184	- retainers	6	167
Alarm transmitter			Heater blower motor & fuse	9	336
- caution	1	0	Indicators, front		
-deactivating the volumetric sensor	10	371	- changing amber to clear lenses	6	177
- renew batteries	1	0		8	253
- replacement	1	0	- connector terminal corrosion	5	157
- reprogramming	1	0		4	117
	8	260	Immobiliser	6	191
- solving alarm not working	10	399	Immobiliser – ECU terminal	7	234
Alternator			Immobiliser - synchronisation	10	371
- exchange	6	163	Immobiliser, volumetric sensor	1	24
- no charge warning	6	171	Instruments in fascia	4	110
- replacement	1	48	Insulation cracking	11	407
- no charge light stays on	8	290	Interior lights control caution	10	399
- problem solving	11	421	Key fob, alarm not working	10	386
Battery			LED replacement bulbs	10	387
- condition device	2	56		10	387
- conditioner	7	237	Lens, indicator – changing from amber to clear	6	176
- conditioner, connecting up	11	425	No charge light stays on	8	290
- filler bottle	3	78	Parking sensor, rear (mod)	12	449
- fixings, missing	5	134	Part number change point	1	24
- increased capacity batteries	8	257		4	105
- lifter/carrier	1	9	Petrol tank sender unit		
- Snap-On tools lifter	3	73	Radio		
- another source, lifter	3	78	- CD stacker, fitting	7	239
Boot opening switch bulb	10	368	- conversion (Japan)	1	39
Boot opening switch on dash	12	443	- frequency converter	3	76
Bulb, dashboard replacement	10	368		7	220
Bulbs, replacing with LEDs	10	386		7	221
Central locking, retrofit	9	340	Relay No 1, replacing	6	165
Conditioned air vents	6	189	Rev counter removal	9	318
Cooling fan modification	10	370	Reverse lamp lucars	3	71
Cooling fan override switch	10	373	Reversing light switch	7	212
Cruise control, retrofit	9	341	Rear light cluster	4	105
Dashboard switch bulb	10	368	Saving electrical parts	3	99
DRLs (daytime running lights)	10	398	Speaker grilles, replacement	8	281
Daytime running lights, fitting	10	398		11	432
FM radio frequency converter	3	76	Speedometer change (import)	9	306
			Speedometer repairs		
Fog lights			Starter motor		
- fog lights	1	39	- Bosch starter motor	7	238
- replacement sources	6	199	- not turning over	11	438
Footwell lights	6	165			

RV8 Workshop Notes

- overheating	5	146
- terminals corrosion	1	25
- terminals repair	1	28
Tachometer removal	9	318
Torque wrench settings	2	51
Volumetric sensor	10	371
Warning light, No Charge	6	171
Windscreen washer jets	1	8
Wiper blades & arms	4	105
Wiper wheelboxes	4	105
Wiper relays failed?	9	321

15. WHEELS & TYRES

Allen key, wheel centre fixings	12	448
Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points	1	24
Pressures, modern tyres	9	337
Road wheels		
- centre caps	1	10
	9	315
- changed castings	1	10
- corrosion	1	15
	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- refurbishment	9	314
	9	317
	10	389
- refurbishment specialist	10	362
- wheel centre badges	1	15
	8	276
	9	315
	9	317
- wheel lock nuts, wear	3	81
Sealants	8	298
	10	372
Space saver tyres, check	5	133
	8	297
Studs, dummy need care	8	261
	9	315
Torque wrench settings	2	51
Tired tyres, stored RV8s	5	132
Tyres		
- replacements	5	160
- replacements, suppliers	6	182
- more on replacements	6	179
- update on replacement tyres	6	198
- pressures	6	174
- pressures again	6	196
- pressures, modern tyres	9	337
- sealants for tyres	8	298
	10	372

- spacesaver views	10	372
- spacesaver wheel & tyre	9	304
- spacesavers, critical view	9	307
- more on spacesavers	9	316
- suppliers, recommended	6	182
- tyres size calculator	10	395
Wheel centre fixings	12	448
Wheel nuts, locking	4	121
Wheels, plastic rivets	12	447

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Badges, RV8 lettering	9	342
Bonnet alignment		
- alignment	3	80
- Gas struts upgrade	10	365
- release cable	6	166
- stay, clip	6	166
Boot		
- Boot lock dashboard switch		
bulb	10	366
- boot lock switch	10	366
- gas struts	8	259
- gas struts, regassing	9	323
- gas struts, replacements	9	323
- general	1	23
- luggage rack options	9	346
- release mechanism	5	149
- tool stowage mould	1	23
- warning (closing)	1	0
Bumper, rear parking sensor	12	449
Bumper, rear, realignment	9	325
Cleaning to near concours standards	11	426
Club badge mounting	2	58
	3	95
Colours (paintwork)	1	0
	2	0
Corrosion checks	1	25
	1	42
	3	87
Door glass		
- removal	2	68
- refitting	2	68
- part numbers	2	68
Door handles	5	151
Door mirrors	1	2
- rubber covers	3	74
- knob handles	3	74
- mirror glass	3	74
	6	166
Door seal, inner	5	153
Electric wing mirrors, fitting	10	375
Exterior checks	1	0

RV8 Workshop Notes

Fire risk, unusual/visor mirror	6	190	Paint codes	4	125
Gas struts, caution	4	114		8	300
	8	259	Paint sources	11	439
Gaiter, rubber replacement	9	333	Parking sensor, rear	12	449
Gear lever gaiter replacement	9	333	Part number change points		
Header rail corrosion	1	25		1	24
Headlamp cowl, remove	6	167	Retainer strip, inner door seal	5	153
Headlamp change to LHD	9	308	Rear window, hood		
Hood			See hood backlight above		
- catches, safety check	8	286	Rear bumper alignment	9	325
- catches, check fixings	9	332	Rear bumper, parking sensor	12	449
- cleaning/refurb	4	107	Seats, unusual fire risk!	6	190
- fitting	1	0	Seats, more legroom	5	139
- operation	1	0	Seats, lowering	7	233
- polish, plastic rear window	9	303	Side skirt removal	5	145
	10	380	Sills		
- rattle	1	20	- mounting brackets	1	25
- rear surround	1	25	- tread plates	1	27
- Renovo products	4	113		4	105
	9	303	Tonneau covers		
- replacement, caution	8	262	- full	2	55
- replacement hoods, more	8	268	- half	2	55
- sheared pivot repair	1	47	Torque wrench settings	2	51
- stiff operation	1	46	Touch up paint codes	8	300
- toggle catch checks	9	332	Touch up paint sources	11	439
Hood backlight			Tow bar, fitting	9	319
- avoiding crease	4	108	Underbody knocks	6	187
- cat deterrent!	2	53	Water leaks	1	22
- press stud tool	9	348		2	62
- rear window polish	9	303		5	136
- replacement	2	53		9	350
- zip use & repair	4	109	Waxoyling reimports	3	87
	10	394	Wheel arch flares	2	70
- zip lubrication	9	343	Windscreen		
Hood rear window see backlight above			- carbon fibre replacement	8	246
Indicator lenses, changing to clear	6	176	- checks	1	0
Inner door seal retainer strip	5	153	- frame corrosion	1	25
Jack with the RV8, concerns	9	331	- leaks, water ingress	3	93
Knocking noise, underbody	6	187		5	136
Legroom, increasing	5	139	- refitting	1	22
Lens, indicator – changing from amber to clear			- replacement surround	8	246
	6	176	- removal	1	22
	8	253	- rust, pictures	7	225
Luggage, fitted set for an RV8	9	431	- sealing rubbers	1	22
Luggage rack options	9	346	- VIN number etching	3	89
MGF electric wing mirrors	10	375		8	273
Noise from engine on LHS			Windscreen glass		
	5	138	- removal	1	22
Nose cone, removal	7	203	- refitting	1	22
Number plates			- replacement supply	7	240
- correct plates, avoid a fine	10	396	Windstop, fitting	5	127
- doublesided tape	7	236		9	328
- rear fixings	1	39	Windstop	7	224
- removing Japan spec plate	7	217	Windstop bracket mod	7	228
- replacement number plate	8	279	Windstop design, folding	9	345
			Windstop, folding design	9	345
			Windstop for taller drivers	9	302
			Wing mirrors, electric	10	375

RV8 Workshop Notes

	10	377			
Wings			Importing to Australia	5	135
- Rover badges (Japan)	1	39	Jack with the RV8, concerns	9	331
Wiper bezel	5	151	Japan reimports of RV8s		
Wiper blades adjustment	1	13	- car documents	1	39
Wipe maintenance	12	444	- checklist	1	0
			- checks & tips	1	39
			- ownership checks	4	112
			- Modifications	4	120
17. SERVICE TOOLS			Land Transport Safety		
Auten hydraulic car lift	7	209	Authority, New Zealand	1	33
Britool equipment	3	71	Le Mans visit - tips	1	49
Draper tool 176	1	12	Luggage, fitted set for an RV8	9	351
	1	23	Luggage rack options	9	346
Draper tool T40	1	12	Maintenance locations	1	0
Filler plug spanner	1	37	Mobile phone, new law	6	193
Hydraulic car lift or ramp	7	209	Old parts, hang on to them		
Jack, using it on an RV8	11	427		1	33
Lift, hydraulic	7	209		3	91
Tool storage moulding	1	23	Phillips & Posidriv differences	9	320
RV8 toolkit			Plaques, rally	8	287
- checklist of contents	1	9	Posidriv & Phillips differences	9	320
- general	1	39	Publications:		
- replacements	2	63	Owners Handbook		
- new toolkit supplies	4	106	AKM7144	1	0
- torch replacement	3	72	Owners Service Record		
Sump plug spanner	1	37	AKM7150	1	0
	4	106	Owners Info Portfolio		
Trolley jack, using on an RV8	11	427	AKM7158	1	0
Zyliss Strong Boy	1	14	Repair Manual		
			AKM7153	1	0
				4	118
18. VARIOUS			Engine Manual		
Acquiring an MG RV8	1	0	AKM7154ENG	1	0
Alarm transmitter			LT77 Gearbox Manual		
- ECU, vulnerability	6	191	AKM7155ENG	1	0
- instructions card	8	274	RAWS, first approval	7	223
- reprogramming	1	0	R380 Gearbox Manual		
- replacements	1	0	AKM7225	1	0
- retrofitting alarm & central			Rally plaques for the RV8	8	287
locking system	5	142	Reimporting from Japan		
Auctions in Japan	6	195	- to Australia	5	135
Badge bar for an RV8	8	250	- Australian RAWS update	7	215
Buying an MG RV8			- checklist	1	39
- guidance note	1	0	- options, local agent?	6	192
- dreams come true!	3	83	- corrosion checks	3	87
- reimporter's checks	4	112	- type approval	1	39
Cleaning an RV8 to near			- customs requirements	1	39
conours standard	11	426	- Waxoyling	3	87
Colours, for the RV8	7	216	Remote key fob – see alarm		
Concours, cleaning an RV8	11	426	transmitter above		
Dehumidifier, Winter storage	7	237	Ratchet, socket set caution	9	353
Disklock	6	180	Repair manual MG RV8	3	71
DVLA info on your car	11	433	Reimporting RV8s, auctions	6	195
DVLA info update	12	441	Rover Dealer network	1	0
Fire extinguishers in cars	4	110	Rover Dealer network	2	0
Fire risk, unusual/mirror	6	190	Seat belts, inertia reel unlock	9	329
Gas struts, fire risk	4	114	Screws Phillips & Posidriv	9	320
Hands free phone, new law	6	193	Servicing	1	39
Hood press studs	9	348		6	172
How many RV8s were made?	7	216			

RV8 Workshop Notes

Silkaflex, foil heat shield	6	170
Speaker grilles, replacement	8	281
Speedometer	1	39
Speedometer, replacement mph dial for a reimport	11	432
Sun visor, fire risk unusual	6	190
Sun visor screws	6	166
Tachometer - redlining	7	206
Tachometer removal	9	317
Temperature gauge	7	207
Trim colour	1	0
	3	86
Trim panels removal	1	30
Trim panels, Velcro strips	7	202
Upholstery		
- leathercare tips	1	17
	11	419
- seat removal	1	30
- seat touch up	11	419
Velcro strips, trim panels	7	202
Warning light, No Charge	6	171
Water leaks legwell	9	350
Windstop, fitting	5	127
- another installation	5	143
- Classic Additions, fitting	9	328
- drawings of a windstop	9	335
- folding windstop design	9	345
- neat installation	7	205
- photos of a windstop	9	335
- windstop bracket mod	7	228

Index prepared by Victor Smith (V8 Harvest Gold 1089)