

Alternator cover seen on a late rubber bumper MGBGTV8 in Switzerland



An alternator cover seen on a late rubber bumper MGBGTV8 in Switzerland. Victor Rodrigues thinks "it is a good idea providing efficient safety when doing some inspection or repairs whenever the engine runs. Do you know if this item was a standard/factory BL equipment or a simple after market item? Do you know if it is still available to purchase?"