

V8NOTE569 - keep your back axle breather clear to avoid moisture build up



569

Keep your back axle breather clear to avoid moisture build up

Ralph Hardwick recently purchased an MGBGT V8 and dropped it off with Brown & Gammons for a check over and service during which Ralph reports "they picked up a few issues, so it will remain there for a while until they are sorted. One issue they found was it appears that the rear axle breather was blocked - the resulting condensation build up together with having only covered 1,000 miles in the last seven years, has caused some corrosion and bearing issues".

Check your plastic breather pipe is not missing

See V8NOTE498 contributed by Derek Squires recommended checking your back axle breather is not missing and replacing it with a brass item which is much more durable. [V8NOTE498](#)