

Introducing The...

MG Car Club

Membership Includes.....

Subcription to our award winning 100 page Club magazine

Free Technical Help

Disounts on Insurance

Discounts on Tickets

Discounts on Spares

Hundreds of annual events

Quality MG Merchandise

Affiliated Clubs Worldwide

7 Race Championships

A great social life!



Why You Should Join Us.

Founded in 1930 we have the experience and know how to help you make the most of owning and running an MG. Activities are organised for all age groups, tastes and models of MG. Social meets, touring, technical seminars, autotests, hill climbs and race meetings!



MGB Register

The MGB Register welcomes all enthusiasts with MGB and MGBGT models. The key strengths of the MGB Register are:

MGB Register website

An active website with news, information on an active programme of events, a useful discussion forum, an MGB Shop with a popular clothing range, cars for sale adverts, an eNewsletter and Tech Tips (general, electrical and mechanical).

- Programme of events organised by the MGB Register each year including a Spring Run, an annual Weekend Event, an MGB Maintenance and Rolling Road weekend and an annual MGB Lecture. The MGB Register has always been a particularly sociable group with regular gatherings at MG Car Club meetings, particularly at the Club's annual International MG Meeting at Silverstone.
- MGB Workshop Notes a series of useful spares and service tips and information.

With these strengths and essential support, the MGB Register is certainly the specialist group any MGB or MGBGT enthusiast should join. From its formation in the late 1970s, the MGB Register has attracted large numbers of MGB enthusiasts and continues to grow strongly today with members in the UK and overseas.

Joining the MGB Register

Joining the MGB Register is very straightforward there is an easy to use online registration form at http://www.mgb-register.org or you can obtain a form from Club Office or from the MGB Registrar and mail it

MGB Registrar MG Car Club Kimber House PO Box 251 Abingdon on Thames Oxfordshire OX14 1FF

MG Car Club

If you are an MG enthusiast then here is the MG Club for you. We welcome enthusiasts for all models of the famous marque - from machines like the current MGF and recent MG RV8 bearing the famous Octagon to modern BCV8 classics, Midgets, MGAs and back to the T-types and those pre-war models that created the legend that is MG!

The MG Car Club has a regular award winning monthly magazine called Safety Fast!, active Registers providing technical support and spares help for each MG model, spares specialists, insurance schemes for MGs and of course some of the best club motor sport and competition events - all within a wide and comprehensive social network in the UK, Mainland Europe and overseas, In all the MG Car Club has around 30,000 members Worldwide.

The MG Car Club, founded with factory support and encouragement in 1930, is run by enthusiasts for

enthusiasts. We maintain our close association the old factory with our Club Office in Cemetery Road in Abingdon adjacent to Larkhill House, the former administrative building at the MG plant. The MG Car Club is run in the true spirit of a members' motor club and each member can participate in the activities and the running of the Club. It is company limited by quarantee.

Joining the MG Car Club

If you are not a member of the MG Car Club, full membership details and a new member pack can be obtained from the Club's office in Abingdon, the home of MG. Just contact:

MG Car Club Kimber House PO Box 251 Abingdon on Thames Oxfordshire OX14 1FF Tel: 01235 555552 mgcc@mgcc.co.uk www.mgcc.co.uk

The Club Office team will be pleased to hear from you and welcome you as a member of the MG Car Club the Marque of Friendship!

Why not join now!



Cover photo: An MGB Roadster in Tartan Red with an LED sidelight bulb upgrade. (Photo: Victor Smith)

MGB Workshop Notes Series

The MGB Workshop Notes series is based on the successful V8 Workshop Notes series we started in early 1979 together with additional notes contributed by MGB enthusiasts. The V8 Register has produced the MGB Workshop Notes series for MGB enthusiasts as a source of useful information on servicing MGBs and sourcing spare parts.

Shortly after the formation of the V8 Register in 1978, the V8 Workshop Notes series was launched to help members maintain this limited production model and source spares. Victor Smith, the founder of the V8 Register, took on the role of editing the series and encouraging contributions from members of the V8 Register. Many individual notes were published in the V8 Register column in Safety Fast! - the award winning monthly magazine of the MG Car Club - but as the number of notes grew rapidly, the series was published as individual volumes in a convenient A5 spiral bound lavflat format.

The aims of the series are quite simple – they are to amplify or clarify the MGB Workshop Manual AKD3259 and to give tips on the availability of spares and service. The series has continued to thrive and is a popular source of information for fellow MGB enthusiasts.

Caution and Disclaimer

The V8 Register of the MG Car Club has published the articles contained herein in good faith. However, neither the MG Car Club, the V8 Register, the MGB Register or their officers, nor the respective authors, can accept legal responsibility for the accuracy of any of the statements contained herein. These articles are intended to supplement the official workshop manual and any other publications produced and/or supplied by MG and/or MG Rover and reference should be made to those publications. Accordingly the MG Car Club Limited, the V8 Register, the MGB Register and their officers and the authors of these articles hereby disclaim responsibility for any legal and/or technical liability whatsoever (as may by law be disclaimed) as might otherwise arise.

© Copyright reserved

The copyright and intellectual property rights of the material set out in this publication are reserved by the V8 Register of the MG Car Club and no reproduction and/or reprocessing of the whole or any part of the material herein and/or sale of copies of the material (whether electronic or print) may be made without the express permission in writing of the V8 Registrar of the V8 Register.

Detailed Index

A detailed Index is also available on the V8 Website and copies can be downloaded free of charge so you can keep your copy of the MGB Workshop Notes series up to date. See:

www.v8register.net/MGB/files/MGB%20Notes%20Index.pdf

Insurance disclosure reminder

Members of the MGB Register and/or readers of these workshop notes are reminded that modifications to the original specification of their vehicle by way of changes of equipment, specification of equipment or components, design of equipment or components or the assembly of any components forming part of their vehicle may be deemed a "modification of the vehicle" by an insurer and require disclosure at the inception, during the term and upon any renewal of motor insurance cover for your the vehicle.

The duty of disclosure is fundamental to contracts of insurance (insurances are contracts of the "utmost good faith") and at all times the insured should make full and accurate disclosure to the insurer of any and all material matters having a bearing on the insurer's assessment of the risk and decision as to the terms for covering such risk. When reading each of the workshop notes in this volume and the rest of the MGB Workshop Notes series, you should consider the content of the note in the light of your duty to disclose any modifications made to your vehicle to your insurer. Where necessary a full and accurate disclosure should be made. If you have any doubt with regard to the need for disclosure of any matter, you should consult your broker and/or insurer in order to clarify the position. The Caution and Disclaimer on page 4 of this volume shall also apply.

Useful MGB references

AKD39000
AKD7598
AKM3661
AKD3259
AKM4070
AKM0039

Moss Europe also supply their parts catalogues for the MGB: http://www.moss-europe.co.uk/MGB.aspx or by telephone on 0800 281182.

Information on SU carburettors

Two A4 sized booklets were produced by SU. Tuning SU HIF Carburettors **AUC 9940 AKD 7521 AUC 9939A** Understanding how the HIF works **AKD 7902**

Editor of the MGB Workshop Notes series

This series of workshop notes has been edited from the successful long running series of V8 Workshop Notes that started in late 1978 only a few years after the MGBGTV8 model was launched. Inevitably times have changed in so many ways with the availability of replacement parts and the prices mentioned in various notes since then so readers should read the notes with that time period in mind. The new series of MGB Workshop Notes has been produced as many MGB and MGBGT enthusiasts have requested an edited series like this.

Roger Aldridge Editor, MGB Workshop Notes

Contents Listing

Volume 1		29.	Improving the MGB's handling	Ohilin Margan
Throttle cable – a caution		30.	Front wing baffle extensions	Philip Morgan
2. Removing the relief valve on a V8 ove	Victor Smith	31.	Speedometer cable	Mick Westrop
-	John Dupont	32.	Brake servo – a servicing summa	Peter Laidler
Handbook error – steering & suspension points			A rust prevention tip	Peter Laidler
4. Drain plug washer (sump) & pressure	John Dupont relief valve		Cooling fan motor	Mick Westrop
5. Brake servo failure	John Dupont		-	Peter Laidler
	John Dupont		Petrol tank modification	Paul Busby
6. Front wheel arch (see also Note 48)	Jeff Ward		Battery revival	Jerry Bright
7. Looking after your body!	Tom Studer	37.	Clutch slave cylinder sequel	Mick Westrop
8. Continued body care!	Philip Morgan	38.	Is your clutch really worn out?	Graham Freeman
9. How to keep cool under pressure – V8 system	. •	39.	Back axle clonk	Chris Hall
•	Colin Leisk	40.	Replacing hydraulic brake pipes	Jerry Bright
10. More cooling tips	Jim Gibson	41.	Fuel tanks for the BGT	Peter Laidler
11. Even more cooling tips L	othar Taverne	42.	Rear silencer – an economy tip	Chris Hall
12. Anti-theft device	Victor Smith	43.	Dog guard for BGT!	
13. Cooling fan override switch	Philip Morgan	44.	Petrol tank Sequel	David Yeo
14. Sequel to the manual switch for cooling		45.	Chrome nuts under the bonnet?	Chris Bovington
15. Reverse gear jumps out?		46.	Wiper motor fault	Peter Laidler
16. V8 alternator	Peter Laidler	47.	Prevention of seizure of nuts and	
17. Delco Remy alternator malfunction	Chris Hall	48.	Fitting new front wings	Jerry Bright
S 18. V8 alternator – another sequel	teve Foldhazy	49.	Magnetic sump nut	Mick Westrop
(abstra	ct from notes)	50.	Mind the toaster fingers!	Bill Burridge
20. Ballast resistance ignition system	Peter Laidler		Fire hazard article	Geoff Seaton
	John Dupont		Steering rack	John Dupont
21. Saving your petrol tank from corrosion	n Jerry Bright		Alternator bolt tightening tip	Paul Busby
22. Overdrive unit malfunction	Chris Hall			John Dupont
23. Leaking vacuum advance diaphragm	Chris Hall		Servo sequel	Geoff Seaton
24. Interchangeability of MGBV8 and Rov 1)	er parts (Part		Front brake calliper overhaul	John Dupont
25. Inter-changeability of parts (Part 2)	Peter Laidler		A small tip on speedo cable	Graham Freeman
	Peter Laidler		Underbody corrosion	Paul Busby
26. Front suspension modification	Peter Laidler		The steering rack – another exce	ption to note Peter Laidler
27. Better brakes for your MGB	Peter Laidler	59.	More on batteries	Chris Bovington
MGB Workshop Notes - Contents Listing				5

28. Loss of sparks

Chris Hall

60. Rubber lock washers				Victor Smith
Anthony 61. Waxoyl treatment for an MGB or V8	y Tindale	90.	Rust prevention – a further note	nthony Wilkinson
	Sovington	91.	Worn lower king pin bush	-
·	DO0	92.	Waxoyling an MGB or MGBGT Pa	
	y Tindale	93.	Waxoyling an MGB or MGBGT Pa	Roger Cooper art 2
	Sovington	94.	Fitting louvres in a bonnet	Roger Cooper
65. Rear wash/wipe installation for an MGBGT Aider	n Bristow		Drain plug drips	Simon Horlock
66. Brake servo sequel – more! Pete	er Laidler			Hayden Winn
67. Valuation of MGs for insurance purposes God	frey Joly		That dwell adjuster again!	John Coulson
68. MG running on	y Tindale	97.	Stainless steel petrol tank	John Roslyn
69. Wiring diagram layout for the new two plug socket requirements for tow bars		98.	Front spoilers for the MGB	Hayden Winn
Vict	tor Smith	99.	Cleaning out your drain tubes	•
	e French	100	. Improve your handling- fit a rear a	
	e French	101.	. Overheating mystery	Paul Busby
72. Take care - your balls may drop! Ge	eoff Allen	102	. Removing a windscreen from an N	Jack Wilson //GBGT
73. Jumping out of reverse – another sequel Mick	10/		. Telescopic front suspension conve	Peter Laidler
74. Laying up an MGB	" 0 1		Elw	ood von Seilbold
75. Under bonnet sound deadening felt dropping	ng Wastran		. Alternator problems	Mike Breedon
Volume 2	Westrop	105.	. Alternative alternator	Jacques Millet
76. Clutch slave cylinder removal		106.	. Easier access to spare wheel spa	ce Jacques Millet
77. Electronic water injection system	e French	107	. Heater control valve	Peter Laidler
	y Tindale	108	. Wind noise reduction	
Mick	Westrop	109	. Brakes pulling	N.N. Mason
	e French	110.	. Spark plug tester	Don Bishop
80. Lubricating oils	D A 14/314		. An important safety check	Simon Porlock
81. Mounting badges on a rubber bumpered N	MG			Roger Parker
82. Supercharging for road or track			. Fire extinguishers for your MG	David Knowles
83. To claim or not to claim!		113.	. Tyre aspect ratios	David Knowles
Alan 84. Suspension and handling problem solution	Kingwell ns	114.	Fitting an SD1 5 Speed gearbox	John Wilson
Hayo 85. Tie rod ends	den Winn	115.	. Overhauling the heater valve	David Knowles
	en Dodds	116	. Revival of sagging seats	
Ke	en Dodds	117.	. Rear head restraints for children	Dave Wellings
	Manners	118.	. Wiper blade replacements	Dave Wellings
	en Dodds	119.	Protection against damp in storag	Peter Beadle e
89. Changing clutch and brake master cylinder	ers		<u> </u>	Tim Langan

David Knowles 121. Pick those ratios! 122. C-post liner clip 123. Interchange of parts between the US spec MGBGT and the MGBGTV8 124. Battery management 125. Tips for attending the annual 24 heures du Mans (Cordon Hesketh-Jones Cordon Hesketh-Jones Cardon H	120. More protection against damp	148. Ride height and bumpers
122. C-post liner clip David Knowles 123. Interchange of parts between the US spec MGBGT and the MGBGTV8 Paul Kile 124. Battery management 125. Tips for attending the annual 24 heures to Mans Victor Smith 126. Dealing with a squeal from the front brake the Jones Gordon Hesketh-Jones Gordon Hesketh-Jones (According Hesketh-Jones)	121. Pick those ratios!	149. Trouble with the original "top hat" battery
123. Interchange of parts between the US spec MGBGT and the MGBGTV8 124. Battery management 125. Tips for attending the annual 24 heures du Mans Victor Smith 126. Dealing with a squeal from the front brakes Gordon Hesketh-Jones (Gordon Hesketh-Jones Wictor Smith 127. Replacement gearboxes Victor Smith 128. MGBV8 gearbox, clutch and propshatt Roger Parker 129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure 137. Silicone or mineral brake fluid for V88? Dave Wellings, Gordon Hesketh-Jones (Gordon Hesketh-	122. C-post liner clip	Victor Smith
Paul Kile 124. Battery management 125. Tips for attending the annual 24 heures du Mans Victor Smith 126. Dealing with a squeal from the front brakes Gordon Hesketh-Jones 127. Replacement gearboxes Victor Smith 128. MGBV8 gearbox, clutch and propshatt Roger Parker 129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox Kurt Schley 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment 135. Steering rack caution 137. Siticone or mineral brake fluid ro Vr8s? Dave Wellings, Gordon Hesketh-Jones Victor Smith 138. Brake Servot failure Victor Smith 139. Para shock absorber link arm 140. Using fire extinguishers in cas Pawe Wellings, Gordon Hesketh-Jones Wictor Smith 141. Cleaning a coffee stain from an RV8 soft top Dave Wellings and the hydraulic systems Georg Muller 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Reprint of a Times article 145. Alternative fuel pumps Reprint of a Times article 146. Relocating the fuel pump in the V8 boot space – a caulion Reprint of a Times article 147. Steering column bush renovation Sylan Ditchman 155. Alternative fuel pump in the V8 boot space – a caulion Reprint of a Times article 147. Steering column bush renovation Sylan Ditchman 158. Fault with the distributor vacuum unit Georg Hall 158. Fault with the distributor vacuum unit Reprint be distributor vacuum unit Reprint be fuel pump in the V8 sort space – a caulion Sylan Ditchman 159. Front shock absorbers on the MGBGTV8 Roger Parker 160. Rising tickover in hot conditions Simon Pickford & Roger Parker 161. Have you got a screw loose? Roger Parker & Norman Green Rising tickover in hot conditions Ris	123. Interchange of parts between the US spec	Roger Parker
Bryan Ditchman 126. Dealing with a squeal from the front brakes Gordon Hesketh-Jones 127. Replacement gearboxes Victor Smith 128. MGBV8 gearbox, clutch and propshaft Roger Parker 129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox Authouses 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V82? Dave Wellings, Gordon Hesketh-Jones Bowly Rear shock absorbers in Karns Georg Muller 139. Rear shock absorbers on MGBV3 155. Fault with the distributor vacuum unit 156. Front shock absorbers on the MGBGTV8 157. Fault with the distributor vacuum unit 158. Engine cooling tip for the MGBGTV8 158. Engine cooling tip for the MGBGTV8 159. Front shock absorbers on the MGBGTV8 150. Silicone or mineral brake fluid for V82? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller 137. Silicone or mineral brake fluid for V82? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Gordon Hesketh-Jones Solving the cut be cooling the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones Solving the cut be cooling to the cooling the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones Solving the rusting wheen lusts Gordon Hesketh-Jones Solving the fue	Paul Kile	
125. Tips for attending the annual 24 heures du Mans Victor Smith 126. Dealing with a squeal from the front brakes Gordon Hesketh-Jones 127. Replacement gearboxes 128. MGBV8 gearbox, clutch and propshaft Roger Parker 129. Borg-Warner T-5 gearbox information 128. MGBV8 gearbox, clutch and propshaft Roger Parker 129. Borg-Warner T-5 gearbox information 129. Borg-Warner T-5 gearbox information 120. Dellow Automotive 5 speed gearbox 121. Layup and storage concerns for the MGBV8 enthusiast 122. Battery lifter or carrier 123. Battery carriers or lifters, another source 124. Bonnet hinge alignment 125. Steering rack caution 126. Brake servo failure 127. Silicone or mineral brake fluid for V82? 128. Batke Fluid - corrosion in the hydraulic systems 129. Power Wellings, Gordon Hesketh-Jones 129. Power Wellings 129. Power Welli	124. Battery management	151. Insurance for classic MGs
126. Dealing with a squeal from the front brakes Gordon Hesketh-Jones Cordon Hesketh-Jones Victor Smith Roger Parker 129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox Kurt Schley 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones Bowly, Georg Muller, Allan Doyle, & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Bowley, Georg Muller, Allan Doyle, & Paul Wiley 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps 146. Relocating the fuel pump in the V8 boot space – a caution Roger Parker 155. Fitting an override switch on the cooling fans Ian Thomson 156. Fitting an 12 volt battery to a chrome bumpered MGBGTV8 Gordon Hesketh-Jones 157. Fault with the distributor vacuum unit 158. Engine cooling tip for the MGBGTV8 Simon Pickford & Roger Parker 168. Engine cooling tip for the MGBGTV8 Simon Pickford & Roger Parker 169. Rising tickover in hot conditions Forth shock absorbers on the MGBGTV8 Simon Pickford & Roger Parker 160. Picture with the distributor vacuum unit 161. Have you got a screw loose? Bryan Ditchman 161. Have you got a screw loose? Bryan Ditchman 161. Have you got a screw loose? Bryan Ditchman 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 164. White smoke – a scary moment! 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary m	125. Tips for attending the annual 24 heures du Mans	Victor Smith 152. Air intake mesh
127. Replacement gearboxes Victor Smith Roger Parker Rog	126. Dealing with a squeal from the front brakes	153. Small steps & giant strides in the handling
128. MGBV8 gearbox, clutch and propshaft Roger Parker 129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox Kurt Schley 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm 140. Using fire extinguishers in cars 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation 155. Fitting an override switch on the cooling fans (an Thomson MGBGTV8 157. Fault with the distributor vacuum unit Geoff Hall 158. Engine cooling tip for the MGBGTV8 159. Front shock absorbers on the MGBGTV8 160. Rising tickover in hot conditions 161. Have you got a screw loose? 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 163. Dov wened to replace the tyres on our V8s before they are worn out? 164. May be you got a screw loose? 165. Have you got a screw loose? 166. White swoth faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 167. Temporary steering tip Gordon Hesketh-Jones 168. White smoke – a scary moment Dave Wellings 169. White smoke – a scary moment Dave Wellings 169. White smoke – a scary moment Dave Wellings 169. White smoke – a scary moment Dave Wellings 160. White smoke – a scary moment Dave Wellings 161. Have you got a screw loose? 162. Options when faced with an engine rebuild Dave Wellings (Front ham faced with an engine rebuild Dave Wellings (Front ham faced with an engine rebuild Dave Wellings (Front ham faced with an engine rebuild Dave Wellings (Fr	127. Replacement gearboxes	154. Rear shock absorbers for MGBV8s
129. Borg-Warner T-5 gearbox information Bob Hyclak 130. Dellow Automotive 5 speed gearbox Kurt Schley 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Reviral of Anon 155. Fault with the distributor vacuum unit 158. Engine cooling tip for the MGBGTV8 Bob Mason 159. Front shock absorbers on the MCBGTV8 Simon Pickford & Roger Parker 160. Rising tickover in hot conditions Revising tickover in hot conditions Geoff Hall 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Poor plane wellings, Gordon Hesketh-Jones 164. White smoke – a scary moment! Dave Wellings Gordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! Dave Wellings Roger Parker 160. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 166. White smoke – a scary moment! Dave Wellings Gordon Hesketh-Jones 167. Temporary steering tip 168. Thatcham immobilisers 169. Rysan Ditchman 169. Peter Berry 160. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 169. White smoke – a scary moment! Dave Wellings Roger of Hell 169. White smoke – a scary moment! Dave Wellings Roger of Hell 169. White smoke – a scary m	128. MGBV8 gearbox, clutch and propshaft	155. Fitting an override switch on the cooling fans
Sordon Hesketh-Jones Kurt Schley 131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Span Dix Wellings Anon 157. Fault with the distributor vacuum unit Geoff Hall 158. Engine cooling tip for the MGBGTV8 Simon Pickford & Roger Parker 160. Rising tickover in hot conditions Geoff Hall 161. Have you got a screw loose? Richard Sorgen Parker 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 163. Do we need to replace the tyres on our V8s before they are worn out? Roger Parker & Norman Green Door jamb switch operating the internal console light Gordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Roger Parker 169. Dov jamb switch operating the internal console light Dave Wellings & Gordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Roger Parker 169. Norman 160. White smoke – a scary moment! 160. White smoke – a scary moment! 160. Solving the rusting wheel the pressure gauge and adding	129. Borg-Warner T-5 gearbox information	156. Fitting a 12 volt battery to a chrome bumpered
131. Layup and storage concerns for the MGBV8 enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment 135. Steering rack caution 136. Brake servo failure 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller 139. Rear shock absorber link arm 140. Using fire extinguishers in cars 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation 158. Engine cooling tip for the MGBGTV8 Simon Pickford & Roger Parker 159. Front shock absorbers on the MGBGTV8 Simon Pickford & Roger Parker 160. Rising tickover in hot conditions Geoff Hall 161. Have you got a screw loose? Rising tickover in hot conditions Geoff Hall 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Pran Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Roger Parker 165. Do we need to replace the tyres on our V8s before they are worn out? Roger Parker 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers Roger fallen 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 169. White smoke – a scary moment! 160. Dave Wellings, 6ordon Hesketh-Jones 161. Have you got a screw loose? Richard with an engine rebuild Dave Wellings, 6ordon Hesketh-Jones 162. Options when faced with an engine rebuild Dave Wellings as Gordon Hesketh-Jones 165. Internal tailgate lamp 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter 171. Solving the ru	130. Dellow Automotive 5 speed gearbox	Gordon Hesketh-Jones
enthusiast Dave Wellings 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 158. Engine cooling tip for the MGBGTV8 Simon Pickford & Roger Parker 160. Rising tickover in hot conditions Geoff Hall 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Bryan Ditchman 163. Do we need to replace the tyres on our V8s before they are worn out? Roger Parker 164. Door jamb switch operating the internal console light Gordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers Richard Groves Richard Groves Richard Groves 169. RV8 filler cap for the MGBGTV8 Relocating the temperature/oil pressure gauge and adding a voltmeter 170. Relocating the temperature/oil pressure gauge and adding a voltmeter 171. Solving the rusting wheel nuts! Solving the rusting wheel in Hallian & V8 Website postings and the Hall whe postings and the pressure gau	· · · · · · · · · · · · · · · · · · ·	
Bob Mason 132. Battery lifter or carrier Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Para Ditchman 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Bryan Ditchman 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! Gordon Hesketh-Jones 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 160. White smoke – a scary moment! 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 160. White smoke – a scary moment! 160. White smoke – a scary moment! 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones 165. Internal tailgate lamp 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 170. Relocating the temperature/oil pressure gauge and adding a voltmeter 171. Solving the rusting wheel nuts! 172. What could that "clonk" noise be? 173. Soft suspension on an MGBGT 174. Webasto blowout!	• •	
Anon 133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Geoff Allen 147. Steering column bush renovation Andrew Brown 147. Steering column bush renovation Reprint of a Geoff Allen 147. Steering column bush renovation Andrew Brown 147. Steering column bush renovation Andrew Brown 148. Brian Jackson 149. Rising tickover in hot conditions Geoff Hall 144. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Dow eneed to replace the tyres on our V8s before they are worn out? Roger Parker & Norman Green 165. Internal tailgate lamp Gordon Hesketh-Jones Bryan Ditchman 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers Richard Groves Richard Groves Richard Groves Bryan Ditchman 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT 174. Webasto blowout!		0
133. Battery carriers or lifters, another source Brian Jackson 134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Geoff Allen 147. Steering column bush renovation 159. Rising tickover in hot conditions Geoff Hall 161. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings, Gordon Hesketh-Jones Dow e need to replace the tyres on our V8s before they are worn out? Roger Parker & Norman Green Dow need to replace the tyres on our V8s before they are worn out? Roger Parker & Norman Green Door jamb switch operating the internal console light Gordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT In Hallifax & V8 Website postings 174. Webasto blowout!	132. Battery lifter or carrier Anon	
134. Bonnet hinge alignment Bryan Ditchman 135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Have you got a screw loose? Bryan Ditchman 162. Options when faced with an engine rebuild Dave Wellings & Gordon Hesketh-Jones Roger Parker & Norman Green 164. Door jamb switch operating the internal console light Bordon Hesketh-Jones 165. Internal tailgate lamp Gordon Hesketh-Jones 166. White smoke – a scary moment! 167. Temporary steering tip 168. Thatcham immobilisers Richard Groves Relocating the temperature/oil pressure gauge and adding a voltmeter 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter 171. Solving the rusting wheel nuts! Solving the susting a screw on out? Solving the full pump in the V8 boot space – a caution 160. White smoke – a scary moment! 161. Have you got a screw the full pane worn out? Solving the full pump in the vise on our V8s before they are worn out? 162. Internal tailgate la		160. Rising tickover in hot conditions
135. Steering rack caution Kevin Hallsworth 136. Brake servo failure Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Table Wellings & Gordon Hesketh-Jones before they are worn out? Roger Parker & Norman Green Dov jamb switch operating the internal console light Gordon Hesketh-Jones Bove Wellings & Gordon Hesketh-Jones Bove need to replace the tyres on our V8s before they are worn out? Roger Parker & Norman Green Bovor jamb switch operating the internal console light Gordon Hesketh-Jones Bovor jamb switch operating the internal console light Gordon Hesketh-Jones Bovor jamb switch operating the internal console light Boror jamb switch operating		
Name		•
Victor Smith 137. Silicone or mineral brake fluid for V8s? Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Geoff Allen 146. White smoke – a scary moment! More a scary moment! More a scary moment! Dave Wellings Geoff Allen 167. Temporary steering tip 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT 174. Webasto blowout!	Kevin Hallsworth	Dave Wellings & Gordon Hesketh-Jones
137. Silicone or mineral brake fluid for V8s?		·
Dave Wellings, Gordon Hesketh-Jones, Steve Bowley, Georg Muller, Allan Doyle & Paul Wiley 138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Geoff Allen 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Reprint of a Times article 169. RV8 filler cap for the MGBGTV8 Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT Iain Hallifax & V8 Website postings 174. Webasto blowout!		
138. Brake Fluid - corrosion in the hydraulic systems Georg Muller 139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Gordon Hesketh-Jones Gordon Hesketh-Jones Bryan Ditchman 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Reprint of a Times article 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!	Dave Wellings, Gordon Hesketh-Jones, Steve	164. Door jamb switch operating the internal console
139. Rear shock absorber link arm Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Gordon Hesketh-Jones Temporary steering tip Geoff Allen 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Richard Groves 8 Bryan Ditchman 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 170. Relocating the trusting wheel nuts! Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
Bryan Ditchman 140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. White smoke – a scary moment! 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Richard Groves Richard Groves Richard Groves Richard Groves 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT Iain Hallifax & V8 Website postings 174. Webasto blowout!		165. Internal tailgate lamp
140. Using fire extinguishers in cars Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Andrew Brown 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Richard Groves Richard Groves Richard Groves 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman Geoff Allen 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
Andrew Brown 141. Cleaning a coffee stain from an RV8 soft top David Lawler 142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Geoff Allen 167. Temporary steering tip Geoff Allen 168. Thatcham immobilisers Richard Groves Reprint of a Times article 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT Iain Hallifax & V8 Website postings 174. Webasto blowout!		· · · · · · · · · · · · · · · · · ·
142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Pictor Smith 168. Thatcham immobilisers Richard Groves Reprint of a Times article 169. RV8 filler cap for the MGBGTV8 Relocating the temperature/oil pressure gauge and adding a voltmeter Foordon Hesketh-Jones Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!	Andrew Brown	
142. Renovo soft top care products Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Richard Groves Richard Groves Reprint of a Times article 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
Victor Smith 143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Victor Smith 169. RV8 filler cap for the MGBGTV8 Bryan Ditchman 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
143. Speeding British drivers may lose their driving licence in France Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Reprint of a Times article 150. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
Reprint of a Times article 144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Geoff Allen 170. Relocating the temperature/oil pressure gauge and adding a voltmeter Gordon Hesketh-Jones 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT Iain Hallifax & V8 Website postings 174. Webasto blowout!		
144. SU fuel pump relocation Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 147. Steering column bush renovation Gordon Hesketh-Jones Gordon Hesketh-Jones Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
Peter Berry 145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 171. Solving the rusting wheel nuts! Gordon Hesketh-Jones 172. What could that "clonk" noise be? Ben Millard & V8 Website postings 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 174. Webasto blowout!		
145. Alternative fuel pumps Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen Geoff Allen 147. Steering column bush renovation Gordon Hesketh-Jones Gordon Hesketh-Jones Howard Gosling 172. What could that "clonk" noise be? Ben Millard & V8 Website postings I ain Hallifax & V8 Website postings 174. Webasto blowout!		
Howard Gosling 146. Relocating the fuel pump in the V8 boot space – a caution Geoff Allen 172. What could that "clonk" noise be? Ben Millard & V8 Website postings Soft suspension on an MGBGT Iain Hallifax & V8 Website postings 174. Webasto blowout!	·	
caution Geoff Allen 173. Soft suspension on an MGBGT lain Hallifax & V8 Website postings 147. Steering column bush renovation 174. Webasto blowout!	•	172. What could that "clonk" noise be?
Geoff Allen Iain Hallifax & V8 Website postings 147. Steering column bush renovation 174. Webasto blowout!	caution	· · · · · · · · · · · · · · · · · · ·
17 11 Woodala Diaman.		Iain Hallifax & V8 Website postings
ben williard & v8 Website postings		
	Sames Stabilan	ben williard & vo website postings

	•		
175.	Overheating problems with an MGBGTV8 Andrew Edgerton-Smith & Victor Smith	202.	Front brake problem Gordon Hesketh-Jones
176.	Steering wheel locks	203.	Solving a fuse box riddle
177.	Ben Millard & V8 Bulletin Board postings Recommended tyre supplier	204.	Tony Head Leather gear lever gaiter, not rubber
178.	Peter Kilmister MGBGTV8 cooling and overheating concerns	205.	Tony Head Review of the B&G castor reduction kit
179.	Roger Parker Cause of carburettor flooding	206.	Chris Hunt Cooke & Victor Smith Uprated heater on a V8
180.	Dr Gavin Bailey Getting an MGBGTV8 registered in France	207.	Gordon Hesketh-Jones Space saver wheels for V8s
181.	Franck Morand New mobile phone law in the UK	208.	David Waterton Care with doublesided tape fixings
182.	Victor Smith Winter wheels for the MGBGTV8	209.	Gavin Bailey Storing a V8 over Winter
183.	Dr Gavin Bailey Radar detector, a necessary protection?	210.	Postings from the V8BB Fitting a "modern CD stacker" in a V8 David Boniface
184.	Victor Smith Insurance for a V8 Roadster	211.	Cibie headlamp upgrade
185.	Ray Cobley & Geoff King Hoyle suspension upgrade kits – a step change	212.	David Biddle Front windscreen replacement on an MGB
	in improved handling Victor Smith & Geoff King		Roadster Bill McCullough
186.	To lift or not to lift, that is the question Gavin Bailey	213.	Reducing heat from downunder! John Hornabrook
187.	Horn fault causing an MOT failure Victor Smith	214.	Fitting an ultimate radiator to cool a V8 Jamie Trapp
188.	Another way of registering a V8 in France Franck Morand	215.	MGB & MGBGT front brake upgrade Geoff King
189.	A long hot night at the Le Mans Classic – in fact just a little too hot!	216.	Another 12v battery conversion Kai Knickmann
	Franck Morand	217.	Refurbishing a Webasto sunshine roof
190.	Solving front brake squeal Mike Russell		Bob Owen
191.	No longer a period of grace on motor insurance	218.	Uprated suspension bushes John Targett
191.	renewals	219.	Fitting a walnut dashboard
	Victor Smith	213.	Barrie Franklin
192.	MGBV8 conversion – from dream to reality Geoff King	220.	Fitting an 065 12 volt battery in an MGBGTV8 Malcolm Venables
193.	Another windstop that looks good and works well	221.	Experience with Spax shock absorbers Andy Torode & Gordon Hesketh-Jones
194.	Mike Simmonds Fitting a "lights on" alarm to an MGBGT	222.	Fitting anti-tramp bars to an MGBGTV8 Chris Armitage
405	Alan Turner	223.	Where can I get a clean pair of number plates?
195.	Upgrading the sealed beam units on an MGB Steve Taylor	224.	Robert Crowson Why is there a glimmer from my ignition warning
196.	How do you open the bonnet when the release cable has snapped?	224.	light? Nigel Melbert, Chris Hunt Cooke & Brian Moyse
197.	Geoff Allen Lighting history and terminology	225.	Frustration with tracing and solving a starting problem
107.	Bob Owen		Dave Wellings
198.	12 volt battery conversion	Volu	me 4
400	Victor Smith		
199.	Two 12 volt batteries in parallel Fred Jenns	226.	Essential spares when touring abroad Geoff King, Bob Owen, Victor Smith, Jim
200.	TE low brake fluid detector – a vital safety		Gibson, Rob Lewis, Rob Collier & Mike Lane
	device for an MGBGTV8 Bob Owen	227.	Solving a faulty handbrake
201.	Fitting a TE Low Brake Fluid Sensor in easy stages	228.	Barrie Jones Common wiring faults
	Victor Smith	229.	Barrie Jones Horn contact repair
MOD !	Warkshan Notes Contents Listing	223.	nom contact repair

	•		
230.	Mike Russell Topping up the damper on an SU HIF	257.	Workshop tips Ian Ailes
231.	Victor Smith Battery conversion cures a V8 hot start	258.	Using Jubilee clips correctly and choosing the correct size
	problem Bob Owen	259.	lan Jennings Solving malfunctions with a V8 overdrive
232.	Refurbishing the bulkhead shelf Clive Wagerfield	260.	Victor Smith Fitted luggage for an MGB
233.	Brake systems and servos Bob Owen	261.	Peter Wallis and Ken Clayton Caution with your bonnet catch
234.	Caution with replacement tyres Howard Gosling	262.	Malcolm Venables
235.	Which brake fluid?		Courtesy light upgrade Jon Moulds
236.	On the rolling road at Aldon	263.	Power steering options review Victor Smith
237.	Alan Rennie Tyre sealants	264.	Gearbox trouble with a Factory V8 box Nick Gray
238.	Roger Parker & an AA note Where can I get a touch up!	265.	Replacement distributor with a Pertronix Ignitor upgrade
239.	Angus Munro Replacement plain rubber cooling hoses – a	266.	Victor Smith Dealing with parabolic springs winding up
	caution		under torque
240.	Editor Renovo's plastic screen polish works! Angus Munro	267.	Michael Beswick Replacement V8 clutch master cylinder David Brown
241.	Critical views on spacesaver wheels Bulletin Board contributors	268.	Modification to avoid a failed bonnet catch Ralph Coulson
242.	Repairing an overdrive switch fault Barrie Jones	269.	Different rear panel joints on a Factory MGBGT
243.	Refurbishing the seats on an MGBGT Richard Searle		Stuart Ratcliff, Mike Howlett & Michael O'Leary
244.	Fuel pump replacement options Bob Owen	270.	Failed MGB bonnet catch - an alternative solution
245.	Lights-on alarm Graham Cornford	271.	Jon Moulds Essential bonnet lock & safety catch servicing
246.	Getting an MGBV8 registered in Belgium Henri Malcorps	27 1.	for an MGB Ralph Coulson
247.	Concerns with antifreeze for classic MGs Victor Smith	272.	Overheating - it may be a tired radiator cap Victor Smith
248.	Improving a standard MGBGT seat Barrie Jones	273.	More on burnt out relays Vic Todman
249.	Fitting an oil thermostat to an MGBV8 Ralph Coulson	274.	Cooling fans upgrade from Revotec Victor Smith
250.	What pressures do you use with modern tyres on an MGBV8?	275.	Cleaning out the fresh air vent chamber drain tube
	Ron Gammons		Victor Smith
251.	Sourcing a fitting an upgraded aluminium radiator	276.	Drop link failure Alan McLean, Ron Gammons & Gordon
	Graham Cornford		Hesketh-Jones
252.	How do you get the windscreen and rear window chrome inserts back into the rubber	277.	Radiator pressure caps Tony Lake
	surround?	278.	Solving a problem with an LH overdrive
253.	Dave Wellings and Pete Jevons Fitting central locking to an MGBGTV8		cycling in and out Victor Smith
254.	Martin Ashby Installing cruise control to an MGBV8	279.	Fitting air-con to an MGBGTV8 Gordon Hesketh-Jones
255.	Ralph Coulson Luggage racks for MGV8s	280.	Hoyle IRS for a V8 Roadster Angus Munro & Mike Howlett
256.	Chris Yates Failed replacement rear brake adjuster	281.	Inline fuse protection for the V8 overdrive TechTorque article in Safety Fast!
_50.	Barrie Jones	282.	Solving bad electrical contacts in the fuse box Gordon Hesketh-Jones
MODW	Jorkshan Notes Contents Listing		٥

MGB	Workshop Notes
283.	Do MGBs need oil coolers? Andrew Lord, Mike Howlett & Roger Parker
284.	Replacing a faulty fuse box Gordon Hesketh-Jones
285.	MGBGTV8 horn bracket – an alternative part Gordon Mallett
286.	Tracing a puzzling misfire on a Factory MGBGTV8
	Ian Ailes & Peter Beadle
287.	A warning for tall people Chris Hunt Cooke
288.	Replacing a faulty horn Victor Smith
289.	Rear spring shackle
290.	George Wilder Head up display with overdrive at night
291.	Victor Smith LED lights conversion
292.	Victor Smith Non-LED daytime running lights on classic cars
293.	Michael Bernhard Curing a sticking carburettor float
294.	Richard Withington What are the key issues to consider when deciding whether to fit 175 or 185 tyres on an MGBGT
	Victor Smith
295.	Replacing the spring on the tailgate stay assembly
296.	Mike Russell Importance of the seemingly insignificant – breather pipes on an SU fuel pump
297.	Peter Cook Avoiding a fine for an incorrect registration plate
	George Wilder
298.	Getting an MGBGT that's been stored back on the road
	Mike Howlett, Malcolm Venables, Bob Owen & Gavin Brown
299.	Retrofitting daytime driving lights to a classic car
300.	Vic Todman & Victor Smith Dash cams – what are they like?
Volum	Victor Smith
Voluli	ie 5
301.	Replacing dashboard instrument bulbs with LEDs
302.	Richard Withington & Nic Houslip Next note
JUZ.	Contributor

The MGB Workshop Notes series continues