

RV8 Workshop Notes

Index to the whole series

This index covers all volumes of the RV8 Workshop Notes series and will be updated from time to time as the series develops. An updated Index is maintained on the V8 Website at www.v8register.net which holders of RV8 Workshop Notes can download to maintain their copies of the Index.

Topic	Vol	RV8 Note		
1. ENGINE				
Actuator, aircon vacuum flap	11	436		
Adams, Mark, useful re-chipping notes	10	360		
	11	402		
	11	403		
	11	410		
Advance & retard pipe	1	39		
	2	60		
	8	258		
Advance retard unit	4	120		
	11	422		
Air filters	1	0		
	1	41		
	3	91		
	3	99		
	4	119		
	6	175		
	11	431		
	12	464		
Air flow meter	1	4		
Air intake sensor	5	130		
Air intake re-positioning	13	481		
Bonnet, gas struts upgrade	10	365		
Bosch starter motor	7	238		
Broken stud removal	12	442		
	12	461		
Coolant bleed insert	11	409		
Crankshaft rear oil seal	3	71		
Cruise control, retrofit	9	341		
Distributor, timing	11	422		
	11	423		
Distributor clamp nut wrench	7	229		
ECU, location, removal & refit	5	144		
	10	360		
ECU, re-chipping	7	226		
	7	230		
	11	402		
	11	403		
	11	410		
ECU re-chipping notes	10	360		
Engine crane or lift	10	397		
Engine load spreader	10	397		
Engine management				
- ECU – what is & what does it do?	11	428		
- Engine management system	11	429		
- ECU fault detection & codes	11	429		
			- Diagnostics, ECU	11 429
			- Data link connector	4 115
			- DLC cover strip	4 115
			- Diagnostic databook	4 122
			- Diagnostic leads	4 118
			- Diagnostic tests	4 118
				4 123
			- Rover Testbook or T4	4 118
			- Test equipment	4 118
			- Tune “Rover speak”	11 429
			Engine performance	
			- EPROMS (chips)	1 21
			- upgrade	1 21
				10 360
			- RPI Engineering	1 21
			- Upgrade	11 410
			Exhaust system	
			- catalytic overheat	3 100
			sensors	4 101
			- catalytic converter	3 99
			- clamps	3 97
			- cats, replacements	9 309
			- down pipes	3 97
				13 480
			- general	1 16
			- hangers, replacing	5 134
			- mounting hooks	1 25
			- manifolds nuts loose	5 138
			- manifold LHS noise	5 138
			- mounting brackets	1 25
			- corrosion	1 25
			- rattle	1 36
			- removal	8 292
			- safety issue	13 480
			- wrapping or coating	11 416
			Oil filter, replacement	8 284
				464 12
			Flame trap hoses	
			- clamps	1 4
			- general	1 5
			Flywheel cover plate	3 71
			Heater hoses	1 5
			Heater box corrosion	1 25
			Heater matrix leak, cure	11 414
			Heat shield, starter motor	12 467
			Hose clamps	
			- general	1 4
			- Norma	1 4
			- Oetika	1 4
			Hot wire fuel injection system	5 140
			Hot start problem solved	11 437
			Idle	
			- engine erratic	5 140
			- running problems	6 188
			- spasmodic idle problems	6 186
			Ignition module, remote	10 369
			Ignition module, overheating	12 445
			Lucas Hot Wire system	5 140

RV8 Workshop Notes

Inlet manifold gasket			Water pump overhaul	3	99
- corrosion	1	25	Water pump replacement	1	3
- general	1	26		3	91
Manuals checklist, V8 engine	12	462	Water pump & air-con drive belts	3	90
Mark Adams, chips	10	360	Water pump overhaul	9	314
	11	410	Under bonnet checks	1	0
Mass airflow sensor	10	374			
Misfire, solving	5	130	2. IGNITION SYSTEM		
	10	375	Cruise control, retrofit	9	341
Mountings, engine			Distributor clamp nut wrench	7	229
- adjusting the mounts	8	255	Distributor, timing	11	422
- mounts	3	71		11	423
- mounts orientation	9	324	Ignition key replacement	1	0
Oil filter magnetic wrap	11	408		8	296
Oil leaks from sump gasket	13	477	Ignition module, remote	10	369
Oil pressure switch	9	327	Ignition module, overheating	12	445
Oil pump			Magnicor plug leads	11	411
- cover & washers	3	88	Optimax chip, improvements	7	200
- hoses (replacements)	3	88		8	251
Optimax chip, improvements	7	200		10	360
	8	251	Part number change points	1	24
	10	360	Starting gremlins	2	66
	11	402	Timing adjustments with reimported RV8s	7	200
	11	403		11	422
	11	410	Timing correction in the RV8 Repair Manual AKM7144ENG	11	435
Part number change points	1	24	Torque wrench settings	2	51
PCV valve, check it is clear	8	249	Unichip connector problems	7	201
Pipe clips	1	4			
Plenum chamber hose	1	4	3. COOLING SYSTEM		
Radiator cover, replacement	10	358	Antifreeze concerns	9	322
Ratchet, socket set caution	9	353	Blanking panel, radiator	4	103
Rattling sound in the engine	12	463		6	178
Rear oil seal – crankshaft	3	71	Coolant bleed insert	11	409
Remote ignition module	10	369	Coolant loss, cause	10	390
Road speed sensor	11	440	Coolant, refilling system	10	357
Rocker cover 3.9 badge			Coolant refilling, bleed insert	11	409
- badge	4	105	Coolant, waterless concerns	12	446
- breather element n/s	6	166	Connecting pipe, corrosion	8	299
Sensor, air intake	5	130	Cooling fan modification	10	370
Starter, overheating	5	146	Cooling fan override switch	10	373
Starter motor	7	238	Cooling hose layout	8	295
Starting problems	6	188	Cooling hose kit, identification	9	338
	11	437	Expansion tank		
	11	438	- crack in the neck of the tank	10	390
Stepper motor, cleaning	8	283	- plug	1	10
Stud, broken - removal	12	442	- refilling reminder	1	3
	12	641	- corrosion	1	25
Sump gasket, replacement	8	284	- filler plug spanner	1	37
Sump gasket, caution	9	339	- new overflow tank	6	170
Sump oil leak from gasket	13	477	- where does the coolant go?	9	347
Sump gasket modification	11	420	Fan, cooling fan modification	10	370
Throttle pedal	1	19	Heater rail modification	9	349
Timing adjustments with reimported RV8s	7	200	Hose, heavy indentation	9	349
Torque wrench settings	2	51	Hoses, layout	6	185
Unichip connector problems	7	201		8	295
V8 engine manuals, checklist	12	462			

RV8 Workshop Notes

Hoses, replacements	9	338	Fuel filter replacement	3	92
Improving cooling	13	481		12	458
Part number change points	1	24	Fuel pump		
Plug, plastic/replacing	5	150	- general	1	29
	5	158	- noisy	1	43
Plug, get you home tip	5	159	- resistor	1	43
Pressure cap replacement	10	367	- fuel pump	1	45
Radiator coolant loss	9	347	- replacement (Bosch)	3	92
Radiator cooling fan switch	2	69	Fuel system		
Radiator hoses	1	4	- hose clamps & clips	1	4
	4	105	- Oetika clamps	1	4
	9	349	- Oetika clamps	1	7
Radiator hoses, steel			- filters & hoses	1	4
connecting pipe corrosion	8	299	- non evaporative loss system	1	4
Radiator cover replacement	10	358		1	23
Radiator hose, bleed insert	11	409	- fuel filter	1	29
	11	434	- filter replacement	3	92
Radiator hoses, replacements	6	185	Fuel tank corrosion	9	326
	8	295	Gauge not reading correctly	8	270
	9	338	Hot wire fuel injection system	5	140
Radiator blanking panel	4	103	Lucas hot wire system	5	140
	6	178	Part number change points	1	24
Radiator pressure cap	10	367	Petrol tank		
Radiator shroud stickers	6	181	- filler pipe	1	4
Radiator, refilling	10	357	- filler pipe	1	7
Radiator, replacement			- filler pipe restrictor	1	39
aluminium unit	12	475	- general	1	7
Radiator top hose self-purging	11	434	- hoses	1	4
Radiator, upgraded	6	170	- Oetika clamps	1	7
Removing heat from a V8 engine bay	13	481	- removal	1	23
Thermostat – check it has a vent	11	415	- vent pipes	1	7
Torque wrench settings	2	51	Pipes, safety check	8	285
Water pump			Plenum chamber plug	4	105
- feed & return	1	4	Starter gremlin – fuel cut off switch	2	66
- hose	1	5	Throttle – see engine management systems	4	123
- overhaul	9	314	Torque wrench settings	2	51
- replacement	1	3			
Waterless coolant concerns	12	446			
4. FUEL SYSTEM			5. CLUTCH		
Bosch injectors	11	411	Clutch master cylinder		
Cruise control, retrofit	9	341	- cap	1	14
ECU location, removal & refit	5	144	- repair kit	1	6
Electronic fuel ignition				8	269
- throttle potentiometer	1	45	- replacement	1	6
- injectors	1	45	- new part number	1	50
- air flow meter	1	45	- replacement	1	50
- air valve stepper	1	45	- vital part number	1	6
Engine management	4	115	Clutch slave cylinder	1	6
	4	118		3	71
	4	122	Clutch pedal return spring	10	361
Fuel cut off switch				10	361
- cut off switch	2	66	Clutch slave repairs	6	197
- starting difficulty	7	219	Part number change points	1	24
Fuel filter blocked, check	9	326	Repair kits. Master/slave	8	269
	12	458	Torque wrench settings	2	51
			6. GEARBOX		

RV8 Workshop Notes

Bushes, rubber UKC854	10	381
Clutch assembly	3	71
Crunching gears, solving	10	381
Gearbox lubrication, R380	6	163
Gearbox cross member	2	52
	3	71
Gearbox mountings	2	52
	3	71
Gearbox remote	3	71
Gearbox remote, grease	10	384
Gearbox removal	3	71
Gearbox, LT77S or R380?	11	404
Gearknob		
- cleaning	1	18
- renovation	3	71
- replacement	1	18
- replacement, elm burr knob	8	256
Gear lever gaiter replacement	9	333
Gear lever greasing	10	384
Gear lever grommet	4	105
Gear lever remote moving	10	381
Input shaft	3	71
Gearshift pattern LT77S/R380	11	404
LT77 gearbox		
- greasing lever & remote	10	384
- rubber bushes rotting	10	381
- lubricant	10	382
- repairing dust cap bracket	11	405
Notchy gearchange cures	10	382
Oil change, photos	8	275
Oil, experience with synthetic	8	264
Part number change points	1	24
R380 gearbox		
- changing oil & access	7	213
	8	271
	8	272
- change point	6	163
- greasing lever & remote	10	384
- lubrication	6	163
	10	382
- repairing dust cap bracket	11	405
- synthetic oils experience	8	264
Rubber bushes UKC854	10	381
Torque wrench settings	2	51
Towing caution	8	252
Which gearbox do I have?	11	404

7. PROPSHAFT

Part number change points	1	24
Prop Shaft Universal Joints	13	486+
Torque wrench settings	2	51

8. REAR AXLE

Breather, plastic replacement	11	413
	12	456
Breather, thread compatibility	11	418
CWP, new supplies	5	156
Limited slip differential	3	84

Noise from back axle	5	155
Part number change points	1	24
Quaife, differences with an LSD	10	388
Rear shock absorber		
- lower mounting bolt	1	32
- replacement	1	32
- servicing	1	32
Rear wheel bearings	1	40
Rebuild & refurbishment	5	156
Replacement axles	6	169
Synthetic oil recommended	6	263
Synthetic oils experience	8	264
Torque wrench settings	2	51

9. REAR SUSPENSION

Hoyle suspension upgrade	7	208
Hoyle – what's it like?	9	310
Hoyle, installation notes	9	311
Hoyle, setting up	10	363
Hoyle, Spax settings	10	364
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Lowering blocks	6	196
Lowering the back end	6	196
Modifications - caution	9	312
Part number change points	1	24
Polybushes disintegrating	13	478
Rear spring shackle	10	383
Rear wheel bearings	1	40
Recall notice	8	244
Shackle, rear spring caution	10	383
Spax Krypton Gas shocks	8	278
Spax replacement shockers	8	278
Spax settings	10	364
Replacement shockers	8	278
Shock absorber, adjustments	6	174
Shockers, adjustment guide	7	214
Suspension upgrade kit	7	208
Torque wrench settings	2	51

10. INSURANCE

Classic car cover		
- agreed value	2	61
- reinstatement cost	2	61
- specialist brokers	2	61
- obtaining valuations	2	61
Disclosure reminder	4	-
Insurance write-off categories	13	489
Immobilisers	4	117
Renewals, no grace period	7	218
Thatcham 1 immobiliser	4	117
	6	168
Thatcham 2 immobiliser	4	117
	6	168

RV8 Workshop Notes

11. STEERING

Ball joints		
- lower	6	166
- upper	6	166
Part number change points	1	24
Castor reduction		
- details of the B&G kit	7	232
- kit is not right for the RV8	7	231
Pacing washers, dashboard creak	8	266
Power assisted steering	7	235
Steering locks	6	180
Steering, PAS	7	235
PAS option review	9	354
EZ EPAS Swiss approvals	9	355
Steering column, collapsible	11	430
Steering rack		
- maintenance	2	54
- mounts warning	8	241
- mounts, strengthening	8	242
- mounts, cracked report	8	243
- removal	2	54
Torque wrench settings	2	51
Track rod end	6	166

12. FRONT SUSPENSION

Ball joints, steering		
- lower	6	166
- upper	6	166
Bump stop replacement	8	254
Bush replacement in AR bar eye	10	385
Castor shims	4	105
Castor reduction kit		
- details of the B&G kit	7	232
- kit not right for the RV8	7	231
- further caution	9	312
Drop links, checks	11	410
Drop links, replacement parts	11	412
Cross member corrosion	1	25
Front coil springs		
- comparison	2	59
- Japan spec	2	59
- removal & overhaul	3	98
- UK spec	2	59
Konis, adjusting & settings	7	214
Konis, uprated		
- fitting a set	7	210
- in use in the Alps	7	211
Part number change points	1	24
Polybushes disintegrating	13	478
Power assisted steering	5	129
Recall notice	8	244
Shock absorber		
- adjustments/ride	6	174
- adjustments guide	7	214
- overhaul	3	94
	3	99

- replacement	1	32
	8	278
- servicing	1	32
Spax Krypton Gas shocks	8	278
Spax, replacement shockers	8	278
Spax settings	10	364
Spring, replacements	6	194
Steering, PAS	5	129
Steering rack	5	131
Torque wrench settings	2	51
Track rod end	6	166

13. BRAKES

Brakes, system & adjustments	9	330
Brake master cylinder		
- repair kit	1	6
- replacement	1	6
	5	152
- refurbishing	10	359
- replacement yellow tag	10	379
Brake fluid choice	8	294
Brake pedal return spring	10	361
Brake servo		
- failures (warning)	4	102
- repair kit	1	6
- replacement	1	6
- caution, maintenance	4	104
Brake slave cylinders		
- repair kit	1	6
- replacement	1	6
Discs, caution for eBay adverts for RV8 discs	9	305
Front brake discs, caution	9	305
Front brake pads		
- pads	1	31
	3	96
- retaining clip	3	99
Front callipers	1	31
Front callipers corrosion	3	96
Glycol brake fluid	8	294
Handbrake cable	1	31
	4	105
Handbrake adjustment	3	75
Handbrake linkage kit	6	166
Handbrake modification	8	291
Hydraulic hoses	1	6
Part number change points	1	24
Rear brake hose lock nut	6	166
Rear brake & shoes	1	31
	6	162
Rear brake adjustment		
- maintenance	3	75
- full inspection	3	75
- brake lining removal	3	75
Rear brake linings, check	6	162
Rear brake, replacement	6	169
Rear wheel cylinder gasket	6	166
Return spring replacement	10	361

RV8 Workshop Notes

Servos and brake systems	8	293	Central locking, retrofit	9	340
Silicone brake fluid	8	294	Conditioned air vents	6	189
Torque wrench settings	2	51	Cooling fan modification	10	370
14. ELECTRICAL EQUIPMENT					
Aerial					
- replacement	1	11	Cruise control, retrofit	9	341
Air conditioning					
- actuator	11	436	Dashboard switch bulb	10	368
- aircon vents improved	12	450	DRLs (daytime running lights)	10	398
- conditioned air vents	6	189	Daytime running lights, fitting	10	398
- corrosion on fans	6	173	Earthing issues	13	482
	10	376	Electrical devices, prudent safety measures	470	12
- flow, aircon outlet extended	12	450	FM radio frequency converter	3	76
- heater cut-off flap vacuum actuator	11	436	Fog lights		
- service	1	44	- fog lights	1	39
	10	393	- replacement sources	6	199
- more passenger legroom	4	124	Footwell lights	6	165
- preventative maintenance	10	376	Fuel pump resistor	1	43
- recharging an aircon system	10	378	Front indicator lamp corrosion	5	157
	10	393		6	163
- re-gassing	13	479	Fuse box & fuses	5	148
- removal of the a/c system?	6	184	Fuel gauge not reading correctly	8	270
Alarm transmitter					
- caution	1	0	Headlamp units		
-deactivating the volumetric sensor	10	371	- conversion to LHD	9	308
- renew batteries	1	0		9	313
- replacement	1	0	- corrosion	1	25
- reprogramming	1	0	- cowl, removal	6	167
	8	260	- cowl removal & replacement	11	417
- solving alarm not working	10	399	- dust cover	13	487
Alternator					
- exchange	6	163	- replacement (Bosch)	1	1
- no charge warning	6	171	- replacement	2	65
- replacement	1	48	- retainers	6	167
- no charge light stays on	8	290	Heater blower motor & fuse	9	336
- problem solving	11	421	Indicators, front		
Amplifier, radio replacement	12	459	- changing amber to clear lenses	6	177
Battery charger, care in use	471	12		8	253
Battery					
- condition device	2	56	- connector terminal corrosion	5	157
- conditioner	7	237	Immobiliser	4	117
	469	12	Immobiliser – ECU terminal	6	191
	472	12	Immobiliser - synchronisation	7	234
- conditioner, connecting up	11	425	Immobiliser, volumetric sensor	10	371
- filler bottle	3	78	Instruments in fascia	1	24
- fixings, missing	5	134	Insulation cracking	4	110
- increased capacity batteries	8	257	Interior lights control caution	11	407
- lifter/carrier	1	9	Key fob, alarm not working	10	399
- Snap-On tools lifter	3	73	LED replacement bulbs	10	386
- another source, lifter	3	78		10	387
Boot opening switch bulb					
	10	368		12	457
Boot opening switch on dash					
	12	443		13	483
Bulb, dashboard replacement					
	10	368		13	484
Bulbs, replacing with LEDs					
	10	386	Lens, indicator – changing from amber to clear	6	176
			No charge light stays on	8	290
			Parking sensor, rear (mod)	12	449
			Part number change point	1	24

RV8 Workshop Notes

Petrol tank sender unit	4	105		10	389
Radio			- refurbishment specialist	10	362
- amplifier replacement	12	459	- wheel centre badges	1	15
- CD stacker, fitting	7	239		8	276
- conversion (Japan)	1	39		9	315
- frequency converter	3	76		9	317
	7	220	- wheel lock nuts, wear	3	81
	7	221	Sealants	8	298
Rear No. Plate Bulbs	13	484		10	372
Relay No 1, replacing	6	165	Space saver tyres, check	5	133
Relative visibility concerns	12	455		8	297
Rev counter removal	9	318	Studs, dummy need care	8	261
Reverse lamp lucars	3	71		9	315
Reversing light switch	7	212	Torque wrench settings	2	51
Rear light cluster	4	105	Tired tyres, stored RV8s	5	132
Rear light repair	12	460			
Saving electrical parts	3	99	Tyres		
Side Light - Improving	13	483	- replacements	5	160
Speaker grilles, replacement	8	281	- replacements, suppliers	6	182
Speedometer change (import)	11	432	- more on replacements	6	179
Speedometer repairs	9	306	- update on replacement tyres	6	198
Starter motor			- pressures	6	174
- Bosch starter motor	7	238	- pressures again	6	196
- heat shield, fitting	12	467	- pressures, modern tyres	9	337
- not turning over	11	438	- safety issue		
- overheating	5	146	- downpipe/clamp/tyre	13	480
- terminals corrosion	1	25	- sealants for tyres	8	298
- terminals repair	1	28		10	372
Tachometer removal	9	318	- spacesaver views	10	372
Temp. gauge earthing issues	13	482	- spacesaver wheel & tyre	9	304
Torque wrench settings	2	51	- spacesavers, critical view	9	307
Volumetric sensor	10	371	- more on spacesavers	9	316
Warning light, No Charge	6	171	- suppliers, recommended	6	182
Windscreen washer jets	1	8	- tyres size calculator	10	395
Wiper blades & arms	4	105	Wheel centre fixings	12	448
Wiper wheelboxes	4	105	Wheel nuts, locking	4	121
Wiper relays failed?	9	321	Wheels, plastic rivets	12	447

15. WHEELS & TYRES

Allen key, wheel centre fixings	12	448
Badges, removing	8	276
Checks before purchase	1	0
Front wheel bearings	1	38
Part number change points	1	24
Pressures, modern tyres	9	337
Road wheels		
- centre caps	1	10
	9	315
- changed castings	1	10
- corrosion	1	15
	3	93
- dummy studs, care! (tip)	8	261
- general	1	10
- refurbishment	1	15
	8	265
- refurbishment	9	314
	9	317

16. BODY

Air intake mesh	1	34
	5	151
Badge bar for an RV8	8	250
Badges, removal with care!	6	183
Badges – doublesided tape	7	236
Badges, RV8 lettering	9	342
Bonnet alignment		
- alignment	3	80
- Gas struts upgrade	10	365
- release cable	6	166
- stay, clip	6	166
Boot		
- Boot lock dashboard switch		
bulb	10	366
- boot lock switch	10	366
- gas struts	8	259
- gas struts, regassing	9	323
- gas struts, replacements	9	323
- general	1	23

RV8 Workshop Notes

- luggage rack options	9	346	- cat deterrent!	2	53
- release mechanism	5	149	- press stud tool	9	348
- tool stowage mould	1	23	- rear window polish	9	303
- warning (closing)	1	0	- replacement	2	53
Bumper, rear parking sensor	12	449	- zip use & repair	4	109
Bumper, rear, realignment	9	325		10	394
Cleaning to near concours standards	11	426	- zip lubrication	9	343
Club badge mounting	2	58	Hood rear window see backlight above		
	3	95	Indicator lenses, changing to clear	6	176
Colours (paintwork)	1	0	Inner door seal retainer strip	5	153
	2	0	Jack with the RV8, concerns	9	331
Corrosion checks	1	25	Knocking noise, underbody	6	187
	1	42	Legroom, increasing	5	139
	3	87	Lens, indicator – changing from amber to clear	6	176
Door glass				8	253
- removal	2	68	Luggage, fitted set for an RV8	9	431
- refitting	2	68	Luggage rack options	9	346
- part numbers	2	68	MGF electric wing mirrors	10	375
Door handles	5	151	Noise from engine on LHS	5	138
Door mirrors	1	2	Nose cone, removal	7	203
- rubber covers	3	74	Number plates		
- knob handles	3	74	- correct plates, avoid a fine	10	396
- mirror glass	3	74	- double sided tape	7	236
	6	166	- rear fixings	1	39
Door seal, inner	5	153	- removing Japan spec plate	7	217
Electric wing mirrors, fitting	10	375	- replacement number plate	8	279
Exterior checks	1	0	- replacing spacer fixing pads	13	476
Fire risk, unusual/visor mirror	6	190	Paint codes	4	125
Gas struts, caution	4	114		8	300
	8	259	Paint sources	11	439
Gaiter, rubber replacement	9	333	Parking sensor, rear	12	449
Gear lever gaiter replacement	9	333	Part number change points	1	24
Grille badge, fitting	12	465	Retainer strip, inner door seal	5	153
	12	466	Rear window, hood		
Header rail corrosion	1	25	See hood backlight above		
Headlamp cowl, remove	6	167	Rear bumper alignment	9	325
Headlamp change to LHD	9	308	Rear bumper, parking sensor	12	449
Headlamp dust covers	13	487	Relative visibility concerns	12	455
Hood			Seats, unusual fire risk!	6	190
- catches, safety check	8	286	Seats, more legroom	5	139
- catches, check fixings	9	332	Seats, lowering	7	233
- cleaning/refurb	4	107	Side skirt removal	5	145
- fitting	1	0	Sills		
- operation	1	0	- mounting brackets	1	25
- polish, plastic rear window	9	303	- tread plates	1	27
	10	380		4	105
- rattle	1	20	Tonneau covers		
- rear surround	1	25	- full	2	55
- Renovo products	4	113	- half	2	55
	9	303	Torque wrench settings	2	51
- replacement, caution	8	262	Touch up paint codes	8	300
- replacement hoods, more	8	268	Touch up paint sources	11	439
- sheared pivot repair	1	47	Tow bar, fitting	9	319
- stiff operation	1	46	Underbody knocks	6	187
- toggle catch checks	9	332	Water leaks	1	22
Hood backlight					
- avoiding crease	4	108			

RV8 Workshop Notes

	2	62
	5	136
	9	350
Waxoyling reimports	3	87
Wheel arch flares	2	70
Windscreen		
- carbon fibre replacement	8	246
- checks	1	0
- frame corrosion	1	25
- leaks, water ingress	3	93
	5	136
- refitting	1	22
- replacement surround	8	246
- removal	1	22
- rust, pictures	7	225
- sealing rubbers	1	22
- VIN number etching	3	89
	8	273
Windscreen glass		
- removal	1	22
- refitting	1	22
- replacement supply	7	240
Windstop, fitting	5	127
	9	328
Windstop	7	224
Windstop bracket mod	7	228
Windstop design, folding	9	345
Windstop, folding design	9	345
Windstop for taller drivers	9	302
Wing mirrors, electric	10	375
	10	377
Wings		
- Rover badges (Japan)	1	39
Wiper bezel	5	151
Wiper blades adjustment	1	13
Wipe maintenance	12	444
17. SERVICE TOOLS		
Auten hydraulic car lift	7	209
Britool equipment	3	71
Draper tool 176	1	12
	1	23
Draper tool T40	1	12
Filler plug spanner	1	37
Hydraulic car lift or ramp	7	209
Jack, using it on an RV8	11	427
Lift, hydraulic	7	209
Tool storage moulding	1	23
RV8 toolkit		
- checklist of contents	1	9
- general	1	39
- replacements	2	63
- new toolkit supplies	4	106
- torch replacement	3	72
Spark Plug Sockets	13	485
Sump plug spanner	1	37
	4	106
Trolley jack, using on an RV8	11	427

Zyliss Strong Boy	1	14
-------------------	---	----

18. VARIOUS

Acquiring an MG RV8	1	0
Alarm transmitter		
- ECU, vulnerability	6	191
- instructions card	8	274
- reprogramming	1	0
- replacements	1	0
- retrofitting alarm & central locking system	5	142
Auctions in Japan	6	195
Badge bar for an RV8	8	250
Battery chargers, care in use	471	12
Battery conditioner, mounting	469	12
Battery conditioners, popular	472	12
Buying an MG RV8		
- guidance note	1	0
- dreams come true!	3	83
- reimporter's checks	4	112
Cleaning an RV8 to near concours standard	11	426
Colours, for the RV8	7	216
Concours, cleaning an RV8	11	426
Dehumidifier, Winter storage	7	237
Disklock	6	180
DVLA info on your car	11	433
DVLA info update	12	441
Electrical devices, care in lay-up	470	12
Fire extinguishers in cars	4	110
Fire risk, unusual/mirror	6	190
France – importing a vehicle	488	13
Gas struts, fire risk	4	114
Hands free phone, new law	6	193
Hood press studs	9	348
How many RV8s were made?	7	216
Importing to Australia	5	135
Importing to France	488	13
Jack with the RV8, concerns	9	331
Japan reimports of RV8s		
- car documents	1	39
- checklist	1	0
- checks & tips	1	39
- ownership checks	4	112
- Modifications	4	120
Land Transport Safety Authority, New Zealand	1	33
Le Mans visit - tips	1	49
Luggage, fitted set for an RV8	9	351
Luggage rack options	9	346
Maintenance locations	1	0
Manuals checklist, V8 engine	12	462
Mobile phone, new law	6	193
Old parts, hang on to them	1	33
	3	91
Phillips & Posidriv differences	9	320
Plaques, rally	8	287

RV8 Workshop Notes

Posidriv & Phillips differences	9	320
Publications:		
Owners Handbook		
AKM7144	1	0
Owners Service Record		
AKM7150	1	0
Owners Info Portfolio		
AKM7158	1	0
Repair Manual		
AKM7153	1	0
	4	118
Engine manuals, checklist	12	462
Engine Manual		
AKM7154ENG	1	0
LT77 Gearbox Manual		
AKM7155ENG	1	0
RAWS, first approval	7	223
R380 Gearbox Manual		
AKM7225	1	0
Rally plaques for the RV8	8	287
Reimporting from Japan		
- to Australia	5	135
- Australian RAWS update	7	215
- checklist	1	39
- options, local agent?	6	192
- corrosion checks	3	87
- type approval	1	39
- customs requirements	1	39
- Waxoyling	3	87
Remote key fob – see alarm transmitter above		
Ratchet, socket set caution	9	353
Repair manual MG RV8	3	71
Reimporting RV8s, auctions	6	195
Rover Dealer network	1	0
Rover Dealer network	2	0
Safety Issue -	13	480
- downpipe/clamp/tyre		
Seat belts, inertia reel unlock	9	329
Screws Phillips & Posidriv	9	320
Servicing	1	39
	6	172
Spare parts	1	33
	3	82
Spares, essential for touring abroad	8	288
Stoplock	6	180
Steering locks	6	180
Stolen cars (Japan)	4	112
Storing an RV8 over Winter	7	237
Technical Info CD, RV8	6	-
Toolkits for MG RV8	1	0
	1	9
	2	63
	3	72
	4	106
Toolkit, spare wheel moulding	6	166
Torque wrench settings	2	51
Under bonnet stickers	1	39

VIN identification	1	0
	5	147
Water leaks cure, legwell	9	350
Windstop	7	224
Windstop, folding design	9	345
Yellow Autolock	6	180

19. INTERIOR & INSTRUMENTS

Aircon outlet, improvement	12	450
Aircon – re-gassing	13	479
Alarm ECU, vulnerability	6	191
Ashtray insert	9	334
Bezels, removing bezels	9	344
Boot bulkhead clips	9	301
Boot opening switch on dash	12	443
Bulkhead clips, boot	9	301
Carpets, replacements source	8	267
Central locking, retrofit	9	340
Checks before purchase	1	0
Clipstone leather cleaner	1	17
Clipstone conditioner	1	18
Cockpit, too hot	5	126
Cockpit heat, solved	6	170
Courtesy light clips	5	141
Cruise control, retrofit	9	341
Dashboard		
- creak, solving	8	266
- fascia removal	1	12
	1	22
- radio fascia panel	3	79
- refurbishing laquer	8	277
Dashcam, avoid a drop	12	468
Door cappings		
- cracking	5	154
- refurbishment	5	154
	8	277
- relacquering trim	8	282
Door pockets modification	8	289
Driver headroom tip	1	35
Emergency flares	7	222
Fascia Shellac coating	2	57
Fascia instruments	2	57
Footwell lights	6	165
	6	166
Fuse box & fuses	5	148
Gaiter, rubber replacement	9	333
Gearbox knob		
- cleaning	1	18
- replacement	1	18
- renovation	3	77
Gear lever gaiter replacement	9	333
Glovebox	1	12
Glovebox, switch	6	166
Glovebox lid, refurbishing	8	277
laquer		
Hands free mobile kits	6	193
Headrest upgrade	11	400
Headrest, leather cushions	11	400

RV8 Workshop Notes

Heater blower motor & fuse	9	336	Upholstery		
Heater control cable	5	128	- leathercare tips	1	17
	7	204		11	419
	8	247	- seat removal	1	30
	8	248	- seat touch up	11	419
Heater matrix leak, cure	11	414	Velcro strips, trim panels	7	202
Hot RV8 cockpit	5	126	Warning light, No Charge	6	171
	6	170	Water leaks legwell	9	350
	7	204	Windstop, fitting	5	127
	7	227	- another installation	5	143
	8	247	- Classic Additions, fitting	9	328
	8	248	- drawings of a windstop	9	335
Ignition key, replacement	8	296	- folding windstop design	9	345
Ignition warning light glows	8	280	- neat installation	7	205
Immobiliser	4	117	- photos of a windstop	9	335
Immobiliser – ECU terminal	6	191	- windstop bracket mod	7	228
Immobiliser, synchronisation	7	234			
Instruments					
- bezels, removing	9	344	Index maintained by Peter Ellis		
- misting difficulties	2	57			
- oil pressure sensor	2	57			
- fascia switch bulbs	3	85			
Interior lights control caution	11	407			
Luggage, fitted	9	351			
Mobile phone, hands free kits	6	193			
Oil pressure switch	9	327			
Radio					
- amplifier replacement	12	459			
- FM waveband converter	2	76			
- FM band expander	7	220			
- iPod ICE option	7	239			
- replacement, reimport	7	221			
Seat belts, inertia reel	9	329			
Seat belt refurbishment	10	391			
	11	424			
Seat belts, replacement	11	424			
Seat belt stalks, repair/gaiter	10	392			
Seat frame, colour	9	352			
Seat frames, refurbishment	9	352			
Seats, headrest upgrade	11	400			
Seats, more legroom	5	139			
Seats, lowering	7	233			
Seats touch up	11	419			
Silkaflex, foil heat shield	6	170			
Speaker grilles, replacement	8	281			
Speedometer	1	39			
Speedometer, replacement					
mph dial for a reimport	11	432			
Sun visor, fire risk unusual	6	190			
Sun visor screws	6	166			
Tachometer - redlining	7	206			
Tachometer removal	9	317			
Temperature gauge	7	207			
- earthing Issues	13	482			
Trim colour	1	0			
	3	86			
Trim panels removal	1	30			
Trim panels, Velcro strips	7	202			