

RV8 Workshop Notes

Index to the whole series

This index covers all volumes of the RV8 Workshop Notes series and will be updated from time to time as the series develops. An updated Index is maintained on the V8 Website at www.v8register.net which holders of RV8 Workshop Notes can download to maintain their copies of the Index.

Topic	Vol	RV8 Note		
1. ENGINE				
Actuator, aircon vacuum flap	11	436		
Adams, Mark, useful re-chipping notes	10	360		
	11	402		
	11	403		
	11	410		
Advance & retard pipe	1	39		
	2	60		
	8	258		
Advance retard unit	4	120		
	11	422		
Air filters	1	0		
	1	41		
	3	91		
	3	99		
	4	119		
	6	175		
	11	431		
	464	12		
Air flow meter	1	4		
Air intake sensor	5	130		
Bonnet, gas struts upgrade	10	365		
Bosch starter motor	7	238		
Broken stud removal	12	442		
	12	461		
Coolant bleed insert	11	409		
Crankshaft rear oil seal	3	71		
Cruise control, retrofit	9	341		
Distributor, timing	11	422		
	11	423		
Distributor clamp nut wrench	7	229		
ECU, location, removal & refit	5	144		
	10	360		
ECU, re-chipping	7	226		
	7	230		
	11	402		
	11	403		
	11	410		
ECU re-chipping notes	10	360		
Engine crane or lift	10	397		
Engine load spreader	10	397		
Engine management				
- ECU – what is & what does it do?	11	428		
- Engine management system	11	429		
- ECU fault detection & codes	11	429		
			- Diagnostics, ECU	11 429
			- Data link connector	4 115
			- DLC cover strip	4 115
			- Diagnostic databook	4 122
			- Diagnostic leads	4 118
			- Diagnostic tests	4 118
				4 123
			- Rover Testbook or T4	4 118
			- Test equipment	4 118
			- Tune "Rover speak"	11 429
			Engine performance	
			- EPROMS (chips)	1 21
			- upgrade	1 21
				10 360
			- RPI Engineering	1 21
			- Upgrade	11 410
			Exhaust system	
			- catalytic overheat sensors	3 100
				4 101
			- catalytic converter	3 99
			- clamps	3 97
			- cats, replacements	9 309
			- down pipes	3 97
			- general	1 16
			- hangers, replacing	5 134
			- mounting hooks	1 25
			- manifolds nuts loose	5 138
			- manifold LHS noise	5 138
			- mounting brackets	1 25
			- corrosion	1 25
			- rattle	1 36
			- removal	8 292
			- wrapping or coating	11 416
			Oil filter, replacement	8 284
				464 12
			Flame trap hoses	
			- clamps	1 4
			- general	1 5
			Flywheel cover plate	3 71
			Heater hoses	1 5
			Heater box corrosion	1 25
			Heater matrix leak, cure	11 414
			Heat shield, starter motor	12 467
			Hose clamps	
			- general	1 4
			- Norma	1 4
			- Oetika	1 4
			Hot wire fuel injection system	
				5 140
			Hot start problem solved	11 437
			Idle	
			- engine erratic	5 140
			- running problems	6 188
			- spasmodic idle problems	6 186
			Ignition module, remote	10 369
			Ignition module, overheating	12 445
			Lucas Hot Wire system	5 140
			Inlet manifold gasket	

RV8 Workshop Notes

- corrosion	1	25	Water pump overhaul	3	99
- general	1	26	Water pump replacement	1	3
Manuals checklist, V8 engine	12	462		3	91
Mark Adams, chips	10	360	Water pump & air-con drive belts	3	90
	11	410	Water pump overhaul	9	314
Mass airflow sensor	10	374	Under bonnet checks	1	0
Misfire, solving	5	130			
	10	375			
Mountings, engine			2. IGNITION SYSTEM		
- adjusting the mounts	8	255	Cruise control, retrofit	9	341
- mounts	3	71	Distributor clamp nut wrench	7	229
- mounts orientation	9	324	Distributor, timing	11	422
Oil filter magnetic wrap	11	408		11	423
Oil pressure switch	9	327	Ignition key replacement	1	0
Oil pump				8	296
- cover & washers	3	88	Ignition module, remote	10	369
- hoses (replacements)	3	88	Ignition module, overheating	12	445
- priming the oil system	474	12	Magnicor plug leads	11	411
Optimax chip, improvements	7	200	Optimax chip, improvements	7	200
	8	251		8	251
	10	360		10	360
	11	402	Part number change points		
	11	403		1	24
	11	410	Starting gremlins	2	66
Part number change points	1	24	TDC check	473	12
PCV valve, check it is clear	8	249	Timing adjustments with reimported RV8s	7	200
Pipe clips	1	4		11	422
Plenum chamber hose	1	4	Timing correction in the RV8 Repair Manual AKM7144ENG	11	435
Radiator cover, replacement	10	358	Torque wrench settings	2	51
Ratchet, socket set caution	9	353	Unichip connector problems	7	201
Rattling sound in the engine	12	463			
Rear oil seal – crankshaft	3	71	3. COOLING SYSTEM		
Remote ignition module	10	369	Antifreeze concerns	9	322
Road speed sensor	11	440	Blanking panel, radiator	4	103
Rocker cover 3.9 badge				6	178
- badge	4	105	Coolant bleed insert	11	409
- breather element n/s	6	166	Coolant loss, cause	10	390
Sensor, air intake	5	130	Coolant, refilling system	10	357
Starter, overheating	5	146	Coolant refilling, bleed insert	11	409
Starter motor	7	238	Coolant, waterless concerns	12	446
Starting problems	6	188	Connecting pipe, corrosion	8	299
	11	437	Cooling fan modification	10	370
	11	438	Cooling fan override switch	10	373
Stepper motor, cleaning	8	283	Cooling hose layout	8	295
Stud, broken - removal	12	442	Cooling hose kit, identification	9	338
	12	641	Expansion tank		
Sump gasket, replacement	8	284	- crack in the neck of the tank	390	10
Sump gasket , caution	9	339	- plug	1	10
Sump gasket modification	11	420	- refilling reminder	1	3
TDC check	473	12	- corrosion	1	25
Throttle pedal	1	19	- filler plug spanner	1	37
Timing adjustments with reimported RV8s	7	200	- new overflow tank	6	170
Top Dead Centre check	473	12	- where does the coolant go?	9	347
Torque wrench settings	2	51	Fan, cooling fan modification	10	370
Unichip connector problems	7	201	Heater rail modification	9	349
V8 engine manuals, checklist	12	462	Hose, heavy indentation	9	349

RV8 Workshop Notes

Hoses, layout	6	185	Fuel filter replacement	3	92
	8	295		12	458
Hoses, replacements	9	338	Fuel pump		
Part number change points	1	24	- general	1	29
Plug, plastic/replacing	5	150	- noisy	1	43
	5	158	- resistor	1	43
Plug, get you home tip	5	159	- fuel pump	1	45
Pressure cap replacement	10	367	- replacement (Bosch)	3	92
Radiator coolant loss	9	347	Fuel system		
Radiator cooling fan switch			- hose clamps & clips	1	4
	2	69	- Oetika clamps	1	4
Radiator hoses	1	4	- Oetika clamps	1	7
	4	105	- filters & hoses	1	4
	9	349	- non evaporative loss system	1	4
Radiator hoses, steel				1	23
connecting pipe corrosion	8	299	- fuel filter	1	29
Radiator cover replacement	10	358	- filter replacement	3	92
Radiator hose, bleed insert	11	409	Fuel tank corrosion	9	326
	11	434	Gauge not reading correctly	8	270
Radiator hoses, replacements			Hot wire fuel injection system		
	6	185		5	140
	8	295	Lucas hot wire system	5	140
	9	338	Part number change points		
Radiator blanking panel	4	103		1	24
	6	178	Petrol tank		
Radiator pressure cap	10	367	- filler pipe	1	4
Radiator shroud stickers	6	181	- filler pipe	1	7
Radiator, refilling	10	357	- filler pipe restrictor	1	39
Radiator top hose self purging	11	434	- general	1	7
Radiator, upgraded	6	170	- hoses	1	4
Thermostat – check it has a vent	11	415	- Oetika clamps	1	7
Torque wrench settings	2	51	- removal	1	23
Water pump			- vent pipes	1	7
- feed & return	1	4	Pipes, safety check	8	285
- hose	1	5	Plenum chamber plug	4	105
- overhaul	9	314	Starter gremlin – fuel cut off switch	2	66
- replacement	1	3	Throttle – see engine management systems	4	123
Waterless coolant concerns	12	446	Torque wrench settings	2	51
4. FUEL SYSTEM			5. CLUTCH		
Bosch injectors	11	411	Clutch master cylinder		
Cruise control, retrofit	9	341	- cap	1	14
ECU location, removal & refit	5	144	- repair kit	1	6
Electronic fuel ignition				8	269
- throttle potentiometer	1	45	- replacement	1	6
- injectors	1	45	- new part number	1	50
- air flow meter	1	45	- replacement	1	50
- air valve stepper	1	45	- vital part number	1	6
Engine management	4	115	Clutch slave cylinder	1	6
	4	118		3	71
	4	122	Clutch pedal return spring	10	361
Fuel cut off switch				10	361
- cut off switch	2	66	Clutch slave repairs	6	197
- starting difficulty	7	219	Part number change points		
Fuel filter blocked, check	9	326		1	24
	12	458	Repair kits. Master/slave	8	269

RV8 Workshop Notes

Torque wrench settings	2	51	Breather, plastic replacement	11	413
				12	456
6. GEARBOX			Breather, thread compatibility	11	418
Bushes, rubber UKC854	10	381	CWP, new supplies	5	156
Clutch assembly	3	71	Limited slip differential	3	84
Crunching gears, solving	10	381	Noise from back axle	5	155
Gearbox lubrication, R380			Part number change points	1	24
	6	163	Quaife, differences with an LSD	10	388
Gearbox cross member	2	52	Rear shock absorber		
	3	71	- lower mounting bolt	1	32
Gearbox mountings	2	52	- replacement	1	32
	3	71	- servicing	1	32
Gearbox remote	3	71	Rear wheel bearings	1	40
Gearbox remote, grease	10	384	Rebuild & refurbishment	5	156
Gearbox removal	3	71	Replacement axles	6	169
Gearbox, LT77S or R380?	11	404	Synthetic oil recommended	6	263
Gearknob			Synthetic oils experience	8	264
- cleaning	1	18	Torque wrench settings	2	51
- renovation	3	71			
- replacement	1	18	9. REAR SUSPENSION		
- replacement, elm burr knob	8	256	Hoyle suspension upgrade	7	208
Gear lever gaiter replacement	9	333	Hoyle – what’s it like?	9	310
Gear lever greasing	10	384	Hoyle, installation notes	9	311
Gear lever grommet	4	105	Hoyle, setting up	10	363
Gear lever remote moving	10	381	Hoyle, Spax settings	10	364
Input shaft	3	71	Konis, adjusting & settings	7	214
Gearshift pattern LT77S/R380	11	404	Konis, uprated		
LT77 gearbox			- fitting a set	7	210
- greasing lever & remote	10	384	- in use in the Alps	7	211
- rubber bushes rotting	10	381	Lowering blocks	6	196
- lubricant	10	382	Lowering the back end	6	196
- repairing dust cap bracket	11	405	Modifications - caution	9	312
Notchy gearchange cures	10	382	Part number change points		
Oil change, photos	8	275		1	24
Oil, experience with synthetic	8	264	Rear spring shackle	10	383
Part number change points			Rear wheel bearings	1	40
	1	24	Recall notice	8	244
R380 gearbox			Shackle, rear spring caution	10	383
- changing oil & access	7	213	Spax Krypton Gas shocks	8	278
	8	271	Spax replacement shockers	8	278
	8	272	Spax settings	10	364
- change point	6	163	Replacement shockers	8	278
– greasing lever & remote	10	384	Shock absorber, adjustments	6	174
- lubrication	6	163	Shockers, adjustment guide	7	214
	10	382	Suspension upgrade kit	7	208
– repairing dust cap bracket	11	405	Torque wrench settings	2	51
- synthetic oils experience	8	264			
Rubber bushes UKC854	10	381	10. INSURANCE		
Torque wrench settings	2	51	Classic car cover		
Towing caution	8	252	- agreed value	2	61
Which gearbox do I have?	11	404	- reinstatement cost	2	61
			- specialist brokers	2	61
7. PROPSHAFT			- obtaining valuations	2	61
Part number change points			Disclosure reminder	4	-
	1	24	Immobilisers	4	117
Torque wrench settings	2	51	Renewals, no grace period	7	218
8. REAR AXLE					

RV8 Workshop Notes

Thatcham 1 immobiliser	4	117	Recall notice	8	244
	6	168	Shock absorber		
Thatcham 2 immobiliser	4	117	- adjustments/ride	6	174
	6	168	- adjustments guide	7	214
			- overhaul	3	94
				3	99
11. STEERING			- replacement	1	32
Ball joints				8	278
- lower	6	166	- servicing	1	32
- upper	6	166	Spax Krypton Gas shocks	8	278
Part number change points			Spax, replacement shockers	8	278
	1	24	Spax settings	10	364
Castor reduction			Spring, replacements	6	194
- details of the B&G kit	7	232	Steering, PAS	5	129
- kit is not right for the RV8	7	231	Steering rack	5	131
Pacing washers, dashboard creak	8	266	Torque wrench settings	2	51
Power assisted steering	7	235	Track rod end	6	166
Steering locks	6	180			
Steering, PAS	7	235	13. BRAKES		
PAS option review	9	354	Brakes, system & adjustments	9	330
EZ EPAS Swiss approvals	9	355	Brake master cylinder		
Steering column, collapsible	11	430	- repair kit	1	6
Steering rack			- replacement	1	6
- maintenance	2	54		5	152
- mounts warning	8	241	- refurbishing	10	359
- mounts, strengthening	8	242	- replacement yellow tag	10	379
- mounts, cracked report	8	243	Brake fluid choice	8	294
- removal	2	54	Brake pedal return spring	10	361
Torque wrench settings	2	51	Brake servo		
Track rod end	6	166	- failures (warning)	4	102
			- repair kit	1	6
			- replacement	1	6
			- caution, maintenance	4	104
12. FRONT SUSPENSION			Brake slave cylinders		
Ball joints, steering			- repair kit	1	6
- lower	6	166	- replacement	1	6
- upper	6	166	Discs, caution for eBay adverts for RV8 discs	9	305
Bump stop replacement	8	254	Front brake discs, caution	9	305
Bush replacement in AR bar eye	10	385	Front brake pads		
Castor shims	4	105	- pads	1	31
Castor reduction kit				3	96
- details of the B&G kit	7	232	- retaining clip	3	99
- kit not right for the RV8	7	231	Front callipers	1	31
- further caution	9	312	Front callipers corrosion	3	96
Drop links, checks	11	410	Glycol brake fluid	8	294
Drop links, replacement parts	11	412	Handbrake cable	1	31
Cross member corrosion	1	25		4	105
Front coil springs			Handbrake adjustment	3	75
- comparison	2	59	Handbrake linkage kit	6	166
- Japan spec	2	59	Handbrake modification	8	291
- removal & overhaul	3	98	Hydraulic hoses	1	6
- UK spec	2	59	Part number change points		
Konis, adjusting & settings	7	214		1	24
Konis, uprated				6	166
- fitting a set	7	210	Rear brake hose lock nut	6	166
- in use in the Alps	7	211	Rear brake & shoes	1	31
Part number change points				6	162
	1	24			
Power assisted steering	5	129	Rear brake adjustment		

RV8 Workshop Notes

- maintenance	3	75	- Snap-On tools lifter	3	73
- full inspection	3	75	- another source, lifter	3	78
- brake lining removal	3	75	Boot opening switch bulb	10	368
Rear brake linings, check	6	162	Boot opening switch on dash	12	443
Rear brake, replacement	6	169	Bulb, dashboard replacement	10	368
Rear wheel cylinder gasket			Bulbs, replacing with LEDs	10	386
	6	166	Central locking, retrofit	9	340
Return spring replacement	10	361	Conditioned air vents	6	189
Servos and brake systems	8	293	Cooling fan modification	10	370
Silicone brake fluid	8	294	Cooling fan override switch	10	373
Torque wrench settings	2	51	Cruise control, retrofit	9	341
			Dashboard switch bulb	10	368
			DRLs (daytime running lights)	10	398
			Daytime running lights, fitting	10	398
			Electrical devices, prudent safety measures	470	12
			FM radio frequency converter		
				3	76
			Fog lights		
			- fog lights	1	39
			- replacement sources	6	199
			Footwell lights	6	165
			Fuel pump resistor	1	43
			Front indicator lamp corrosion	5	157
				6	163
			Fuse box & fuses	5	148
			Fuel gauge not reading correctly	8	270
			Headlamp units		
			- conversion to LHD	9	308
				9	313
			- corrosion	1	25
			- cowl, removal	6	167
			- cowl removal & replacement	11	417
			- replacement (Bosch)	1	1
			- replacement	2	65
			- retainers	6	167
			Heater blower motor & fuse	9	336
			Indicators, front		
			- changing amber to clear lenses	6	177
				8	253
			- connector terminal corrosion		
				5	157
			Immobiliser	4	117
			Immobiliser – ECU terminal	6	191
			Immobiliser - synchronisation	7	234
			Immobiliser, volumetric sensor	10	371
			Instruments in fascia	1	24
			Insulation cracking	4	110
			Interior lights control caution	11	407
			Key fob, alarm not working	10	399
			LED replacement bulbs	10	386
				10	387
				12	457
			Lens, indicator – changing from amber to clear	6	176
			No charge light stays on	8	290

RV8 Workshop Notes

Parking sensor, rear (mod)	12	449		9	317
Part number change point				10	389
	1	24	- refurbishment specialist	10	362
Petrol tank sender unit	4	105	- wheel centre badges	1	15
Radio				8	276
- amplifier replacement	12	459		9	315
- CD stacker, fitting	7	239		9	317
- conversion (Japan)	1	39	- wheel lock nuts, wear	3	81
- frequency converter	3	76	Sealants	8	298
	7	220		10	372
	7	221	Space saver tyres, check	5	133
Relay No 1, replacing	6	165		8	297
Relative visibility concerns	12	455	Studs, dummy need care	8	261
Rev counter removal	9	318		9	315
Reverse lamp lucars	3	71	Torque wrench settings	2	51
Reversing light switch	7	212	Tired tyres, stored RV8s	5	132
Rear light cluster	4	105	Tyres		
Rear light repair	12	460	- replacements	5	160
Saving electrical parts	3	99	- replacements, suppliers	6	182
Speaker grilles, replacement			- more on replacements	6	179
	8	281	- update on replacement tyres	6	198
Speedometer change (import)	11	432	- pressures	6	174
Speedometer repairs	9	306	- pressures again	6	196
Starter motor			- pressures, modern tyres	9	337
- Bosch starter motor	7	238	- sealants for tyres	8	298
- heat shield, fitting	12	467		10	372
- not turning over	11	438	- spacesaver views	10	372
- overheating	5	146	- spacesaver wheel & tyre	9	304
- terminals corrosion	1	25	- spacesavers, critical view	9	307
- terminals repair	1	28	- more on spacesavers	9	316
Tachometer removal	9	318	- suppliers, recommended	6	182
Torque wrench settings	2	51	- tyres size calculator	10	395
Volumetric sensor	10	371	Wheel centre fixings	12	448
Warning light, No Charge	6	171	Wheel nuts, locking	4	121
Windscreen washer jets	1	8	Wheels, plastic rivets	12	447
Wiper blades & arms	4	105			
Wiper wheelboxes	4	105			
Wiper relays failed?	9	321			
			16. BODY		
15. WHEELS & TYRES			Air intake mesh	1	34
Allen key, wheel centre fixings	12	448		5	151
Badges, removing	8	276	Badge bar for an RV8	8	250
Checks before purchase	1	0	Badges, removal with care!	6	183
Front wheel bearings	1	38	Badges – doublesided tape	7	236
Part number change points			Badges, RV8 lettering	9	342
	1	24	Bonnet alignment		
Pressures, modern tyres	9	337	- alignment	3	80
Road wheels			- Gas struts upgrade	10	365
- centre caps	1	10	- release cable	6	166
	9	315	- stay, clip	6	166
- changed castings	1	10	Boot		
- corrosion	1	15	- Boot lock dashboard switch		
	3	93	bulb	10	366
- dummy studs, care! (tip)	8	261	- boot lock switch	10	366
- general	1	10	- gas struts	8	259
- refurbishment	1	15	- gas struts, regassing	9	323
	8	265	- gas struts, replacements	9	323
- refurbishment	9	314	- general	1	23
			- luggage rack options	9	346

RV8 Workshop Notes

- release mechanism	5	149	- rear window polish	9	303
- tool stowage mould	1	23	- replacement	2	53
- warning (closing)	1	0	- zip use & repair	4	109
Bumper, rear parking sensor	12	449		10	394
Bumper, rear, realignment	9	325	- zip lubrication	9	343
Cleaning to near concours standards	11	426	Hood rear window see backlight above		
Club badge mounting	2	58	Indicator lenses, changing to clear	6	176
	3	95	Inner door seal retainer strip	5	153
Colours (paintwork)	1	0	Jack with the RV8, concerns	9	331
	2	0	Knocking noise, underbody	6	187
Corrosion checks	1	25	Legroom, increasing	5	139
	1	42	Lens, indicator – changing from amber to clear		
	3	87		6	176
Door glass				8	253
- removal	2	68	Luggage, fitted set for an RV8	9	431
- refitting	2	68	Luggage rack options	9	346
- part numbers	2	68	MGF electric wing mirrors	10	375
Door handles	5	151	Noise from engine on LHS		
Door mirrors	1	2		5	138
- rubber covers	3	74	Nose cone, removal	7	203
- knob handles	3	74	Number plates		
- mirror glass	3	74	- correct plates, avoid a fine	10	396
	6	166	- doublesided tape	7	236
Door seal, inner	5	153	- rear fixings	1	39
Electric wing mirrors, fitting	10	375	- removing Japan spec plate	7	217
Exterior checks	1	0	- replacement number plate	8	279
Fire risk, unusual/visor mirror	6	190	Paint codes	4	125
Gas struts, caution	4	114		8	300
	8	259	Paint sources	11	439
Gaiter, rubber replacement	9	333	Parking sensor, rear	12	449
Gear lever gaiter replacement	9	333	Part number change points		
Grille badge, fitting	12	465		1	24
	12	466	Retainer strip, inner door seal	5	153
Header rail corrosion	1	25	Rear window, hood		
Headlamp cowl, remove	6	167	See hood backlight above		
Headlamp change to LHD	9	308	Rear bumper alignment	9	325
Hood			Rear bumper, parking sensor	12	449
- catches, safety check	8	286	Relative visibility concerns	12	455
- catches, check fixings	9	332	Seats, unusual fire risk!	6	190
- cleaning/refurb	4	107	Seats, more legroom	5	139
- fitting	1	0	Seats, lowering	7	233
- operation	1	0	Side skirt removal	5	145
- polish, plastic rear window	9	303	Sills		
	10	380	- mounting brackets	1	25
- rattle	1	20	- tread plates	1	27
- rear surround	1	25		4	105
- Renovo products	4	113	Tonneau covers		
	9	303	- full	2	55
- replacement, caution	8	262	- half	2	55
- replacement hoods, more	8	268	Torque wrench settings	2	51
- sheared pivot repair	1	47	Touch up paint codes	8	300
- stiff operation	1	46	Touch up paint sources	11	439
- toggle catch checks	9	332	Tow bar, fitting	9	319
Hood backlight			Underbody knocks	6	187
- avoiding crease	4	108	Water leaks	1	22
- cat deterrent!	2	53			
- press stud tool	9	348			

RV8 Workshop Notes

	2	62		
	5	136		
	9	350		
Waxoyling reimports	3	87		
Wheel arch flares	2	70		
Windscreen				
- carbon fibre replacement	8	246		
- checks	1	0		
- frame corrosion	1	25		
- leaks, water ingress	3	93		
	5	136		
- refitting	1	22		
- replacement suuound	8	246		
- removal	1	22		
- rust, pictures	7	225		
- sealing rubbers	1	22		
- VIN number etching	3	89		
	8	273		
Windscreen glass				
- removal	1	22		
- refitting	1	22		
- replacement supply	7	240		
Windstop, fitting	5	127		
	9	328		
Windstop	7	224		
Windstop bracket mod	7	228		
Windstop design, folding	9	345		
Windstop, folding design	9	345		
Windstop for taller drivers	9	302		
Wing mirrors, electric	10	375		
	10	377		
Wings				
- Rover badges (Japan)	1	39		
Wiper bezel	5	151		
Wiper blades adjustment	1	13		
Wipe maintenance	12	444		
17. SERVICE TOOLS				
Auten hydraulic car lift	7	209		
Britool equipment	3	71		
Draper tool 176	1	12		
	1	23		
Draper tool T40	1	12		
Filler plug spanner	1	37		
Hydraulic car lift or ramp	7	209		
Jack, using it on an RV8	11	427		
Lift, hydraulic	7	209		
Tool storage moulding	1	23		
RV8 toolkit				
- checklist of contents	1	9		
- general	1	39		
- replacements	2	63		
- new toolkit supplies	4	106		
- torch replacement	3	72		
Sump plug spanner	1	37		
	4	106		
Trolley jack, using on an RV8	11	427		
Zyliss Strong Boy	1	14		
18. VARIOUS				
Acquiring an MG RV8	1	0		
Alarm transmitter				
- ECU, vulnerability	6	191		
- instructions card	8	274		
- reprogramming	1	0		
- replacements	1	0		
- retrofitting alarm & central locking system	5	142		
Auctions in Japan	6	195		
Badge bar for an RV8	8	250		
Battery chargers, care in use	471	12		
Battery conditioner, mounting	469	12		
Battery conditioners, popular	472	12		
Buying an MG RV8				
- guidance note	1	0		
- dreams come true!	3	83		
- reimporter's checks	4	112		
Cleaning an RV8 to near concours standard	11	426		
Colours, for the RV8	7	216		
Concours, cleaning an RV8	11	426		
Dehumidifier, Winter storage	7	237		
Disklock	6	180		
DVLA info on your car	11	433		
DVLA info update	12	441		
Electrical devices, care in lay-up	470	12		
Fire extinguishers in cars	4	110		
Fire risk, unusual/mirror	6	190		
Gas struts, fire risk	4	114		
Hands free phone, new law	6	193		
Hood press studs	9	348		
How many RV8s were made?	7	216		
Importing to Australia	5	135		
Jack with the RV8, concerns	9	331		
Japan reimports of RV8s				
- car documents	1	39		
- checklist	1	0		
- checks & tips	1	39		
- ownership checks	4	112		
- Modifications	4	120		
Land Transport Safety Authority, New Zealand	1	33		
Le Mans visit - tips	1	49		
Luggage, fitted set for an RV8	9	351		
Luggage rack options	9	346		
Maintenance locations	1	0		
Manuals checklist, V8 engine	12	462		
Mobile phone, new law	6	193		
Old parts, hang on to them	1	33		
	3	91		
Phillips & Posidriv differences	9	320		
Plaques, rally	8	287		
Posidriv & Phillips differences	9	320		
Publications:				

RV8 Workshop Notes

Owners Handbook AKM7144	1	0	Windstop	7	224
Owners Service Record AKM7150	1	0	Windstop, folding design	9	345
Owners Info Portfolio AKM7158	1	0	Yellow Autolock	6	180
Repair Manual AKM7153	1	0			
	4	118	19. INTERIOR & INSTRUMENTS		
Engine manuals, checklist	12	462	Aircon outlet, improvement	12	450
Engine Manual AKM7154ENG	1	0	Alarm ECU, vulnerability	6	191
LT77 Gearbox Manual AKM7155ENG	1	0	Ashtray insert	9	334
RAWS, first approval	7	223	Bezels, removing bezels	9	344
R380 Gearbox Manual AKM7225	1	0	Boot bulkhead clips	9	301
Rally plaques for the RV8	8	287	Boot opening switch on dash	12	443
Reimporting from Japan			Bulkhead clips, boot	9	301
- to Australia	5	135	Carpets, replacements source	8	267
- Australian RAWS update	7	215	Central locking, retrofit	9	340
- checklist	1	39	Checks before purchase	1	0
- options, local agent?	6	192	Clipstone leather cleaner	1	17
- corrosion checks	3	87	Clipstone conditioner	1	18
- type approval	1	39	Cockpit, too hot	5	126
- customs requirements	1	39	Cockpit heat, solved	6	170
- Waxoyling	3	87	Courtesy light clips	5	141
Remote key fob – see alarm transmitter above			Cruise control, retrofit	9	341
Ratchet, socket set caution	9	353	Dashboard		
Repair manual MG RV8	3	71	- creak, solving	8	266
Reimporting RV8s, auctions	6	195	- fascia removal	1	12
Rover Dealer network	1	0		1	22
Rover Dealer network	2	0	- radio fascia panel	3	79
Seat belts, inertia reel unlock	9	329	- refurbishing laquer	8	277
Screws Phillips & Posidriv	9	320	Dashcam, avoid a drop	12	468
Servicing	1	39	Door cappings		
	6	172	- cracking	5	154
Spare parts	1	33	- refurbishment	5	154
	3	82		8	277
Spares, essential for touring abroad	8	288	- relacquering trim	8	282
Stoplock	6	180	Door pockets modification	8	289
Steering locks	6	180	Driver headroom tip	1	35
Stolen cars (Japan)	4	112	Emergency flares	7	222
Storing an RV8 over Winter	7	237	Fascia Shellac coating	2	57
Technical Info CD, RV8	6	-	Fascia instruments	2	57
Toolkits for MG RV8	1	0	Footwell lights	6	165
	1	9		6	166
	2	63	Fuse box & fuses	5	148
	3	72	Gaiter, rubber replacement	9	333
	4	106	Gearbox knob		
Toolkit, spare wheel moulding	6	166	- cleaning	1	18
			- replacement	1	18
Torque wrench settings	2	51	- renovation	3	77
Under bonnet stickers	1	39	Gear lever gaiter replacement	9	333
VIN identification	1	0	Glovebox	1	12
	5	147	Glovebox, switch	6	166
Water leaks cure, legwell	9	350	Glovebox lid, refurbishing laquer	8	277
			Hands free mobile kits	6	193
			Headrest upgrade	11	400
			Headrest, leather cushions	11	400
			Heater blower motor & fuse	9	336
			Heater control cable	5	128
				7	204
				8	247

RV8 Workshop Notes

	8	248		
Heater matrix leak, cure	11	414	- seat touch up	11 419
Hot RV8 cockpit	5	126	Velcro strips, trim panels	7 202
	6	170	Warning light, No Charge	6 171
	7	204	Water leaks legwell	9 350
	7	227	Windstop, fitting	5 127
	8	247	- another installation	5 143
	8	248	- Classic Additions, fitting	9 328
Ignition key, replacement	8	296	- drawings of a windstop	9 335
Ignition warning light glows	8	280	- folding windstop design	9 345
Immobiliser	4	117	- neat installation	7 205
Immobiliser – ECU terminal	6	191	- photos of a windstop	9 335
Immobiliser, synchronisation	7	234	- windstop bracket mod	7 228
Instruments				
- bezels, removing	9	344		
- misting difficulties	2	57		
- oil pressure sensor	2	57		
- fascia switch bulbs	3	85		
Interior lights control caution	11	407		
Luggage, fitted	9	351		
Mobile phone, hands free kits	6	193		
Oil pressure switch	9	327		
Radio				
- amplifier replacement	12	459		
- FM waveband converter	2	76		
- FM band expander	7	220		
- iPod ICE option	7	239		
- replacement, reimport	7	221		
Seat belts, inertia reel	9	329		
Seat belt refurbishment	10	391		
	11	424		
Seat belts, replacement	11	424		
Seat belt stalks, repair/gaiter	10	392		
Seat frame, colour	9	352		
Seat frames, refurbishment	9	352		
Seats, headrest upgrade	11	400		
Seats, more legroom	5	139		
Seats, lowering	7	233		
Seats touch up	11	419		
Silkaflex, foil heat shield	6	170		
Speaker grilles, replacement	8	281		
Speedometer	1	39		
Speedometer, replacement				
mph dial for a reimport	11	432		
Sun visor, fire risk unusual	6	190		
Sun visor screws	6	166		
Tachometer - redlining	7	206		
Tachometer removal	9	317		
Temperature gauge	7	207		
Trim colour	1	0		
	3	86		
Trim panels removal	1	30		
Trim panels, Velcro strips	7	202		
Upholstery				
- leathercare tips	1	17		
	11	419		
- seat removal	1	30		

Index prepared by Victor Smith (V8 Harvest Gold 1089)