


BETA This is a new service – your [feedback](#) will help us to improve it.

Check the MOT history of a vehicle

Registration number: 

Vehicle make:	MG
Vehicle model:	BGT
Date first used:	1 January 1974
Fuel type:	Petrol
Colour:	Yellow

MOT history of this vehicle

Test date:	13 February 2016
Expiry date:	12 February 2017
Test Result:	Pass
Odometer reading:	6,814 miles
MOT test number:	3320 7345 0773

Test date:	24 March 2015
Expiry date:	23 March 2016
Test Result:	Pass
Odometer reading:	5,845 miles
MOT test number:	6174 7328 5094

No MOT test recorded for 2014

Test date:	4 October 2013
Expiry date:	11 October 2014
Test Result:	Pass
Odometer reading:	4,877 miles
MOT test number:	1777 7737 3214

Test date:	2 October 2012
Expiry date:	11 October 2013
Test Result:	Pass
Odometer reading:	3,835 miles
MOT test number:	8679 7677 2223

Checking the MOT history of a Vehicle on the GOV.UK website

Test date:	10 October 2011
Expiry date:	11 October 2012
Test Result:	Pass
Odometer reading:	2,343 miles
MOT test number:	3857 8388 1489

Test date:	12 October 2010
Expiry date:	11 October 2011
Test Result:	Pass
Odometer reading:	413 miles
MOT test number:	1816 3518 0216

Test date:	29 September 2009
Expiry date:	3 October 2010
Test Result:	Pass
Odometer reading:	97,617 miles
MOT test number:	3216 5217 9237

Advisory notice item(s):
brake pedal rubber worn
slight noise from offside front wheel bearing

Test date:	4 October 2008
Expiry date:	3 October 2009
Test Result:	Pass
Odometer reading:	95,012 miles
MOT test number:	4008 7827 8239

Test date:	30 August 2007
Expiry date:	29 August 2008
Test Result:	Pass
Odometer reading:	94,929 miles
MOT test number:	1149 7244 7243

Test date:	21 August 2007
Test Result:	Fail
Odometer reading:	94,927 miles
MOT test number:	4934 0333 7284

Checking the MOT history of a Vehicle on the GOV.UK website

Reason(s) for failure:

Nearside Front Upper Suspension arm has excessive play in a pin/bush (2.4.G.2)
Nearside Upper Front suspension has excessive movement at wishbone bearing (2.5.A.1c)
Nearside Lower Front suspension has excessive play in a lower wishbone bearing (2.5.B.1a)
Offside Lower Front suspension has excessive play in a lower wishbone bearing (2.5.B.1a)
Offside Front Exhaust has a major leak of exhaust gases (7.1.2)

Advisory notice item(s):

Nearside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)
Offside Headlamp not in good working order but not adversely affecting beam image (1.2.4a)
Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
underside rusty

Test date:	11 August 2006
------------	-----------------------

Expiry date:	10 August 2007
--------------	-----------------------

Test Result:	Pass
--------------	-------------

Odometer reading:	94,422 miles
-------------------	---------------------

MOT test number:	7939 1342 6202
------------------	-----------------------

Test date:	9 August 2006
------------	----------------------

Test Result:	Fail
--------------	-------------

Odometer reading:	94,420 miles
-------------------	---------------------

MOT test number:	3449 5102 6422
------------------	-----------------------

Reason(s) for failure:

Horn not working (1.6.2a)
Nearside Windscreen wiper blade deteriorated (8.2.2)
Nearside Steering rack gaiter split (2.2.D.2d)
rear brake application uneven (3.7.B.2)
Parking brake: efficiency below requirements (3.7.B.7)

Advisory notice item(s):

Nearside Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
Offside Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)

[Search again](#)

Website address: <https://www.check-mot.service.gov.uk/>