


MGB bonnet lock and safety catch



No	Part No	Description
3	AHA 5543	Cup-lock locating
4	HZA 4451	Plate catch
	SF 604041	Screw catch plate
	LWZ 204	Washer-spring
5	14G 2444	Pin-bonnet lock
6	4G 3676	Thimble-bonnet lock
7	HZA 563	Spring-bonnet lock
8	4G 2494	Spring-catch plate return
9	HZA 332	Catch-safety
	PMZ 308	Screw-safety catch
10	BHA 4388	Nut-anchor
11	AHA 5617	Bracket-safety catch
	PMZ 308	Screw-bracket
	PMZ 203	Washer-plain
	LWZ 203	Washer-spring

Source: MGB, Tourer, GT and V8 – Up to September 1976 Parts Catalogue AKM 0039, page 108-K1

See:

Information gateway: MGB bonnet safety catch concerns
<http://www.v8register.net/subpages/gatewaybonnetsafetycatch1.htm>

V8NOTE446 – Failed MGB bonnet catch - an alternative solution
<http://www.v8register.net/subpages/V8NOTE446.htm>

V8NOTE444 – Modification to avoid a failed MGB bonnet catch
<http://www.v8register.net/subpages/V8NOTE444.htm>

V8NOTE436 - Caution with your bonnet catch
<http://www.v8register.net/subpages/V8NOTE436.htm>