

Broken drop link (anti-roll bar link) on an MGBGTV8



Alan McLean has made more progress with his broken drop link saying "I attach a couple of photos of the old drop link which I removed from my car on Saturday." See the photo on the next page too.

Broken drop link (anti-roll bar link) on an MGBGTV8

