

Restoring a rubber bumpered MGBGTV8 – Roger Powell Nixon reports on progress



Roger Powell reports "Block Huggers from my MGBGTV8 that I grit blasted, sprayed with high temperature exhaust paint before baking. The threads have been cleaned up and extended manifold nuts fitted with stainless steel washers since these photos were taken".



Manifold before blasting

