


## RV8 rusty fuel tank



Jeff Shaw is giving the RV8 he bought at the H&H auction at Duxford in March 2020 a thorough check and says "I dropped my fuel tank down today and upon looking inside it's clear it will have to be changed. The sender unit was rusted solid – the gauge always shows full. The only part inside not rusty was the bottom inch of the tank - I assume it was stored for long periods empty. As you can see the outside looks like new".