


## MGBGTV8 - door seal sill retaining strip



MGB-TOURER,GT AND V8-UP TO SEPTEMBER 1976					
Ill. No.	Part No.	DESCRIPTION	Qty.	Change Point	REMARKS
<b>LINERS,FINISHERS,DOOR SEALS,MAP POCKET.GT-continued.</b>					
<b>POCKET-MAP</b>					
27	AHH 8163	Red .....	NLA		
27	AHH 8162	Black.....	NLA		Use prior to
27	AHH 9412	Black.....	NLA		AHH 9412
27	AHH 9447	Black.....	1		(B)GBD-22443 TO
27	AHH 9448	Brown .....	NLA		(C)G-HD4-158230
27	KGK 9435	Autumn Leaf.....	NLA		(B)GBUD-502009 TO
27	XGK 2210	Autumn Leaf.....	1		(C)G-HD4-158230
27	XGN 2210	Navy.....	1		(C)G-HD4-158231 TO
27	XGT 2917	Ochre \$.....	NLA		187840
27	XGN 2917	Navy \$.....	1		(C)G-HD5-187841 ON
	XGA 2917	Black \$.....	NLA		(C)G-D2D1-101 ON
	XGK 2917	Autumn Leaf \$.....	1		(C)G-HD5-219001 TO
28	AHH 8117	Finisher-map pocket.....	1		258000
	FWP 906	Washer-cup .....	2		(C)G-HD5-258001 TO
	AD 606061	Screw.....	2		296000
<b>SEAL-DOOR</b>					
29	AHH 9240	Red .....	NLA		(C)G-HD5-296001
29	AHH 9241	Blue .....	2		TO 328800
29	AHH 9541	Mushroom .....	2		(C)G-D2D1-101 TO(+)
29	KGK 9538	Autumn Leaf.....	2		(C)G-HD5-328801 ON
29	KGK 9538	Navy.....	2		(C)G-D2D1-(+) ON
29	KGK 820	Navy.....	NLA		Use prior to
29	KGT 820	Ochre.....	2		KGK 820
29	KGA 820	Black.....	NLA		(C)G-HD5-295683
29	KGK 820	Autumn Leaf.....	2		TO 328800
29	XGA 6652	Black.....	2		(C)G-D2D1-101 TO(+)
29	XGK 6652	Autumn Leaf.....	2		(C)G-HD5-328801 TO
30	AHH 7768	Strip-retaining-seal.....	2		367803(EXCEPT
	AB 606031	Screw-strip .....	12		N.America),
31	14A 6797	Clip-door seal to flange.....	A/R		328801 ON(N.America)
32	AHH 8796	Liner-dash masking-RH.....	1		(C)G-D2D1-(+) TO
32	AHH 8797	Liner-dash masking-LH.....	1		(+)
					(C)G-HD5-367804 ON
					(C)G-D2D1-(+) ON

In a V8 Bulletin Board posting Geoff Hall said "when my car was rebuilt some ten years ago I removed the original threshold plates prior to respray, new door seals and carpet which were subsequently fitted. The car is now back on the road and I have found in my workshop two strips of metal which are obviously from this area but I just cannot work out how to fit them or where. I cannot find them in a catalogue but believe they may be original. The pieces are the same length as the threshold plates and have six holes for fixing. In profile they look something like a question mark and I would think they were fitted to protect the door seal but I cannot work out how to fit them - over/under the threshold plate - over under the carpet and across the beading. Learning all the time? Help please".

The part is a metal strip (item 30 alongside and above) to retain, or more likely protect, the sill section of the rubber door seal (item 29 alongside). It is fixed to the rubber mat sill. See item 30 above, part number **AHH7768**. See pages 108-O 29 & 108-O 30 in the parts manual AKM0039.

## MGBGTV8 - door seal sill retaining strip



**Left:** view from passenger legwell to the door seal sill retaining strip showing it has a profile like a number **2**.

**Above and below,** the strip is fitted over the rubber mat sill with six fixings.

