

Rebuilding an MGBGTV8 – Damask 0450 (Part 14 of a series of reports)

'Tis Christmas, and something was shining inside the nearside A post. A quick zing with the cutting disc, and look what I found - a chromium plated socket. Imagine what that would have sounded like, every time you went round a corner!



This week, the boot floor came out. Not only was it totally rusted out, but also it gave access to the rear chassis rails, which were holed in several places.



Also, at the front, the nearside 'trumpet' has been removed. This has revealed a frilly edge which would otherwise have gone unnoticed.