Where can I get good quality replacement distributor parts for an MGBGTV8? - call the Distributor Doctor



Replacement distributor vacuum unit part number 54424497



Replacement Lucas rotor arm part number 54422044



Left: connecting spout on the replacement distributor vacuum unit is in a different position to the original, which was on the tip rather than the side.



Replacement distributor condenser part number 423871